



Wood lower storms will be restored and reused. Uppers are metal and broken and will be removed.

Existing windows are not original to the house and are not efficient.



New windows will be one over one as previous.



No interior/exterior trim will be removed or modified.



Most of the windows are cracked, warped, broken, and do not open due to many layers of paint.
Replacing just the sashes. Full wood window protected by Fibrex® composite exterior.



Windows rattle due to proximity to Dutton Road.