

CITY OF ROCHESTER HILLS
DEPARTMENT OF PUBLIC SERVICES

October 28, 2004

PARKING RESTRICTIONS
HAMPTON CIRCLE (Section 26)

Background

On Tuesday, March 9, 2004, the Advisory Traffic and Safety Board (ATSB) approved the following TCO (March 9, 2003 meeting minutes Attached):

- PK-78.1 “No Parking” signs within the right-of-way of south side of Hampton Circle from Barclay Circle (at their south intersection) to a point nine hundred fifty (950) feet easterly thereof.
- PK-78.2 “No Parking” signs within the right-of-way of the north side of Hampton Circle from Barclay Circle (at their south intersection) to a point two hundred sixty (260) feet easterly thereof.
- PK-78.3 “No Parking” signs within the right-of-way of the north side of Hampton Circle from Barclay Circle (at their south intersection) to a point three hundred eighty (380) feet to a point twelve-hundred fifty (1,250) easterly thereof.

The decision was made to leave a one-hundred (120) foot gap across the frontage of 645 Barclay Circle to allow interim on-street parking spaces for the medical office until the Hampton Circle Rehabilitation Project was completed with a continuous striped center-turn lane.

Upon completion of the project, staff issued TCO PK-83 “No Parking” within the right-of-way of north side of Hampton Circle from Barclay Circle (at their south intersection) to a point twelve-hundred fifty (1,250) feet easterly thereof. PK-83 also rescinds PK-78.2 and PK-78.3.

Action Requested

The Department of Public Service requests the ATSB support having TCO No. PK-83 issued.

M. Matich, Traffic Technician

MGM\mgm

I:\ENG\TRAF\STUDIES\PARKING\HAMPTON CIRCLE NO PARKING.DOC