USZTAN L.L.C.

COMMERCIAL & INDUSTRIAL CONTRACTOR
CONSTRUCTION MANAGEMENT
261 Collier Road, Aubum Hills, Michigan 48326
Phone (245) 332-7448 Fax (248) 332-7452
www.usztan.com

Fred Di nn 18455 Cherwood Detroit, VI 48826

Dear M. Dunn,

Per your request Usztan LLC inspected the home located at 1841 Crooks. Rd. Rochester Hills. M for the purpose of restoring the dwelling to a livable condition while keeping within local his torical requirements.

Upon ir spection the following items were noted;

→ Sinucture

- Existing foundations are leaking and have become compromised in certain areas. It is believed they are not below current requirements of 42" and that since the structure is not heated frost damage to the footings has occurred.
- Several structure components have been cut or removed
- A portion of the framing has been exposed to significant water damage and need replacement
- The roof structure is in need of complete removal. Existing shingles/shakes and plywood underlayment requires replacement, while the extent of roof truss damage cannot be determined, condition is suspect.
- Significant mold growth was observed and we recommend further investigation and testing

- Siding is not original and does not meet historic requirements
- Windows and door cannot be salvaged.

Existing systems are completely removed or destroy beyond repair.

Upon review of the structure it not feasible to restore the existing dwelling while keeping to historic requirements. Few, if any original components can be salvage for use in the remediction of the structure. It is Jaztan opinion that the structure is beyond repair and recommends complete demolition.

That you for the opportunity to assist you and please feel free to contact us in the future for any additional opportunities.

STRICE Re y