CITY OF ROCHESTER HILLS DEPARTMENT OF PUBLIC SERVICES

April 5, 2006

PARKING RESTRICTIONS SCHOOL ROAD (Section 24)

Background

Recently the Department of Public Services reviewed the current traffic signage for School Road, from John R Road to Dequindre Road. As result, we found regulatory parking restriction signs missing from the field for Traffic Control Order (TCO) PK-36. TCO PK-36 restricts parking along the south side of School Road, beginning from a point 250' west of Parke Street to a point 750' easterly thereof. On December 15, 1993 Rochester Hills City Council adopted TCO Pk-36 rescinding and superseding Road Commission for Oakland County TCO P 63-173-76 (issued 1976).

Our records indicate that PK-36 was initially issued as a result of a chronic parking problems area residents residing along on south side of School Road incurred from the over flow parking of City Helen V. Allen Park Memorial Park. At the time, baseball fields for the park were located on north side of School Road at Parke Street. The baseball fields for Helen V. Allen Memorial Park have since been relocated from north side of School Road to the south side of School Road and east of Parke Street (see attached map). Presently the Department of Public Services or the Parks Department is not aware of current School Road parking complaints related to the baseball fields for Helen V. Allen Memorial Park.

Action Requested

Therefore, we no can longer identify a School Road parking problem at Parke Street and recommend the Advisory Traffic and Safety Board supports a City Council Resolution to removal and rescinds TCO PK-36 and the replacement of the parking regulatory signs for School Road.

M. Matich, Traffic Technician

 $MGM\mbox{\em}mgm$

I:\Eng\TRAF\TRAFFIC STUDIES\PARKING\School Road Parking.doc