

VACANT BUILDINGSEnforcement | EN-2018-01040

Property Information

70-15-15-327-002 1021 HARDING AVE Subdivision:
 ROCHESTER HILLS MI, 48307-2523 Lot: Block:

Name Information

Owner: MILLER, DOROTHY B Phone:
 Occupant: Phone:
 Filer: Phone:

Enforcement Information

Date Filed: 07/20/2018 Date Closed: Status: COMPLIANCE LETTER
 Complaint:
 Last Action Date: Last Inspection: 12/03/2018
 Last Action:

CCL RECHECK Inspection | MARK MCLOCKLIN

Status: Scheduled Result:
 Scheduled: 01/21/2019 Completed:

CCL RECHECK Inspection | MARK MCLOCKLIN

Status: Completed Result: No Change
 Scheduled: 12/03/2018 Completed: 12/03/2018

CCL RECHECK Inspection | MARK MCLOCKLIN

Status: Completed Result: No Change
 Scheduled: 11/01/2018 Completed: 11/01/2018

Comments:

Comment ON NOVEMBER 1,2018 2:00 PM, MEETING WITH PAUL MILLER, SCOTT COPE AND MYSELF TO DISCUSSED THE STATUS OF HIS HOUSE AT 1021 HARDING. SCOTT ASKED PAUL TO OABTAIN AN ENGINEERING REPORT / EVALUATION OF THE HOUSE WITHIN 30 DAYS FROM TODAY. PAUL AGREED BUT HE IS HAVING A HARD TIME FINDING SOMEONE THAT IS CHEAPTER THEN 15.000 DOLLARS. PAUL STATED THAT HE WOULD CLEAN UP THE FRONT YARD, PAINT THE BOARDED WINDOWS AND RETARPED THE ROOF AND REVALUTATE THIS IN 30 DAYS.

CCL RECHECK Inspection | MARK MCLOCKLIN

Status: Completed Result: No Change
 Scheduled: 09/24/2018 Completed: 09/24/2018

Comments:

Comment PER BOB WHITE, HOLD OFF UNTIL WE CAN MEET WITH SCOTT.

CCL RECHECK Inspection | MARK MCLOCKLIN

Status: Completed Result: No Change
 Scheduled: 08/30/2018 Completed: 08/30/2018

RT RECHECK Inspection | MARK MCLOCKLIN

Status: Completed Result: Violation(s)
 Scheduled: 07/27/2018 Completed: 07/27/2018

Violations:

Uncorrected

Status: Completed
Scheduled: 07/20/2018

Result: Violation(s)
Completed: 07/20/2018

Violations:

Uncorrected SEC 84-15 C VACANT BUILDINGS

BUILDINGS THAT HAVE REMAINED VACANT AND BOARDED FOR MORE THAN 180 DAYS WILL BE CONSIDERED AS BLIGHT AND THE BUILDING DEPARTMENT MAY ASK FOR AN ORDER TO DEMOLISH THE BUILDING.

I.E. UNINHABITABLE HOUSE DUE TO FIRE MUST BE DEMOLISHED ASAP.
