State of Michigan Historic Preservation Office **Intensive Level Survey**

Rochester Hills Historic Districts Survey

Address

Street: 1841

Crooks Rd.

Helen O'Neil Pottery House

City: Rochester Hills

County: Oakland

ZIP 48309

Current Name:

Historic Name:

Evaluations

Contributes to:

1841 Crooks Road More Data Needed

NR Eligible: Contributing:

Historic Use:

Contributing Site

SHPO Evaluation:

Photo

Filename: RHPhotos\Crooks\1841 Crooks.jpg

Roll: View: Frame:

D/single dwelling

Resources on Property/Status

Current Use:

D/single dwelling

Owner Type: Private

Credit: Burke Jenkins

Northeast

Caption: 1841 Crooks Rd., Rochester Hills, M1

Main Building

Foundation Roof: L. Asphalt 1. Stone: Granite 2. 2. Concrete 3. 3. Other: Wall:

1. Wood: Weatherboard 1. Brick 2. 2.

3. 3.

Period of Significance:

ca. 1860s-70s.

Area of Significance:

¹ Architecture Agriculture

Arch/Builder:

Date Built: ca. 1860s-1870s

Architectural Classification:

Material Notes:

Description:

Upright and wing gable roof frame house with 2 story upright and 1 story wing. Recessed porch in wing and small addition to south end. Three rear ell additions have concrete foundations. Last addition is a screened porch. Two brick chimneys. 4/4 windows with decorative trim. Decorative

corner brackets on porch.

Other Buildings/Features:

Barn in rear north. Small outbuilding rear south. Split rail fence.

Significant Persons:

Statement of Significance

Good, intact example of upright and wing house type popular in Avon Township and Oakland County in 19th century. 1872 atlas map -- A.C. Parker, 230 acres, shows house and sawmill. 1896--

Deborah Tucker, 98 acres, shows house. 1908--Wm. McKinstrey, 98a, shows house. 1938 rural property inventory, E.J. Beattie, 29 acres, does not give date built for house; indicates remodeling in

1910.

References:

Michigan Rural Property Inventory, Avon Township, 20G: 1993 survey form

Surveyor's Comments:

State of Michigan Historic Preservation Office **Intensive Level Survey**

Rochester Hills Historic Districts Survey

Address

Street: 1841

Crooks Rd.

City: Rochester Hills

County: Oakland

ZIP 48309

Current Name: Historic Name:

Evaluations

Contributes to:

1841 Crooks Road Not NR Eligible

NR Eligible: Contributing:

Contributing Site

SHPO Evaluation:

Photo

Filename: RHPhotos\Crooks\1841 Crooks a.jpg

Frame:

Historic Use: Current Use:

Owner Type:

AS/animal facility

Resources on Property/Status

View:

Private

East Credit: Burke Jenkins

Caption: 1841 Crooks Rd., Rochester Hills, MI

Main Building

Foundation	Roof:	Period of Significance:
1. Stone	1. Asphalt	
2.	2.	Area of Significance:
3.	3.	¹ Agriculture
Wall:	Other:	² Architecture
1. Wood	1.	3
2.	2.	Arch/Builder:
3.	3.	Date Built:
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		

Architectural Classification:

Material Notes:

Description:

Large gambrel roof barn with vertical plank siding.

Other Buildings/Features:

Significant Persons:

Statement of Significance

References:

Surveyor's Comments:

State of Michigan Historic Preservation Office **Intensive Level Survey**

Rochester Hills Historic Districts Survey

Address

Street: 1841

Crooks Rd.

City: Rochester Hills

County: Oakland

ZIP 48309

Current Name: Historic Name:

Evaluations

Contributes to:

1841 Crooks Road Not NR Eligible

NR Eligible: Contributing:

More Data Needed

SHPO Evaluation:

Photo

Filename: RHPhotos\Crooks\1841 Crooks b.jpg

Roll:

Frame:

Historic Use:

South View:

Current Use: Owner Type: Private Credit: Burke Jenkins

Caption: 1841 Crooks Rd., Rochester Hills, MI

Main Building

Resources on Property/Status

Foundation Roof:

Period of Significance:

Area of Significance:

1.

1. Wood: Shingle

2.

2.

3.

2.

3.

Wall:

1. Wood

3.

Other:

1.

2.

3.

Arch/Builder:

2

3

Date Built:

Architectural Classification:

Material Notes:

Description:

Small gable roof outbuilding. Vertical plank siding.

Other Buildings/Features:

Significant Persons:

Statement of Significance

Pump house? Can't tell from street if tall enough for outhouse.

References:

Surveyor's Comments:

Need to determine rough date and function of building.