Innovation Hills Streambank Stabilization






Photo 1: Project Location



Photo 3: Bank collapse just downstream of turtle trail

Photo 2: Turtle Trail Bank Failure – Looking upstream,