

## Environmental & Engineering Services Nationwide



# PHASE I ENVIRONMENTAL SITE

Commercial Property and Gasoline Dispensing Station 945 and 975 South Rochester Road | Rochester Hills, Michigan PM Project Number 01-11390-0-0001

## Prepared for:

Rochester Avon Partners, LLC 251 East Merrill Street Birmingham, Michigan 48009

**ASSESSMENT** 

## Prepared by:

**PM Environmental, Inc.** 4080 West Eleven Mile Road Berkley, Michigan 48072

**ENVIRONMENTAL SERVICES** 

BUILDING ARCHITECTURE, ENGINEERING & SCIENCE

INDUSTRIAL HYGIENE SERVICES

BROWNFIELDS & ECONOMIC INCENTIVES CONSULTING

Know Your Risk.
Take Control.
Work with the Experts.

www.pmenv.com



**Corporate Headquarters** 

Lansing, Michigan 3340 Ranger Road, Lansing, MI 48906

f: 877.884.6775 t: 517.321.3331 **Michigan Locations** 

Berkley Grand Rapids Lansing Bay City Chesterfield Oak Park

September 10, 2019

Mr. Doraid Markus Rochester Avon Partners, LLC 251 East Merrill Street Birmingham, Michigan 48009

Re: Phase I Environmental Site Assessment of the

**Commercial Property and Gasoline Dispensing Station** 

Located at 945 and 975 South Rochester Road, Rochester Hills, Michigan

PM Environmental, Inc. Project No. 01-11390-0-0001

Dear Mr. Markus:

PM Environmental, Incorporated (PM) has completed the Phase I Environmental Site Assessment (ESA) of the above referenced property. This Phase I ESA was conducted in accordance with (1) the United States Environmental Protection Agency (USEPA) Standards and Practices for All Appropriate Inquiries {(AAI), 40 CFR Part 312} and (2) guidelines established by the American Society for Testing and Materials (ASTM) in the Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process / Designation E 1527-13 (ASTM Standard Practice E 1527-13).

The Phase I ESA for the above referenced property represents the product of PM's professional expertise and judgment in the environmental consulting industry, and it is reasonable for **ROCHESTER AVON PARTNERS**, **LLC** to rely on PM's Phase I ESA report.

If you have any questions related to this report please do not hesitate to contact our office at 248.336.9988.

Sincerely,

PM ENVIRONMENTAL. INC.

Jacob Bloom Staff Consultant Steven E. Price, CHMM Principal and Vice President

#### **EXECUTIVE SUMMARY**

PM Environmental, Inc., (PM) was retained to conduct a Phase I Environmental Site Assessment (ESA) of the Commercial Property and Gasoline Dispensing Station located at 945 and 975 South Rochester Road, Rochester Hills, Oakland County, Michigan (hereafter referred to as the "subject property"). This Phase I ESA was conducted in accordance with (1) the United States Environmental Protection Agency (USEPA) Standards and Practices for All Appropriate Inquiries {(AAI), 40 CFR Part 312} and (2) guidelines established by the American Society for Testing and Materials (ASTM) in the Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process / Designation E 1527-13 (ASTM Standard Practice E 1527-13).

## THIS REPORT WAS PREPARED FOR THE EXCLUSIVE USE OF <u>ROCHESTER AVON</u> PARTNERS, LLC, WHOM MAY RELY ON THE REPORT'S CONTENTS.

Item	Comments
Number of Parcels and Acreage	Two parcels totaling 1.01 acres
Number of Building(s) and Square Footage	One single-story multi-tenant commercial building containing 5,409 square feet (945 South Rochester Road) and one single-story convenience store building containing 1,407 square feet (975 South Rochester Road)
Current Property Use	945 Rochester Road: Retail sales of jewelry and professional office activities 975 South Rochester Road: Gasoline dispensing station
Current Underground Storage Tanks (USTs)	One 10,000-gallon gasoline UST located south of the convenience store, and one 8,000-gallon compartmental UST located west of the convenience store.

Reasonably ascertainable records for the subject property extended back to approximately 1940. Data failure occurred prior to that date, and from 1949 to 1957. However, PM did not identify any significant data gaps during the completion of this Phase I ESA.

#### 945 South Rochester Road

Standard and historical sources were able to document the subject property was developed with agricultural fields from at least 1937 until between 1949 and 1957 when the current commercial building was constructed. Additions to the northern portion of the building were constructed in 1977. Occupants of the property included a veterinarian hospital from at least 1957 until 1975 and various retail businesses and professional offices since the late 1970s. PM was unable to identify occupants of the building prior to 1957. However, based upon the size and layout of the building during this time period, the building was likely utilized for similar veterinarian hospital operations prior to 1957.

## 975 South Rochester Road

Standard and historical sources were able to document the subject property consisted of agricultural and vacant land from at least 1937 until between 1964 and 1967 when the current building was constructed in the northeastern portion. The building was utilized for gasoline service station operations from at least 1967 until 1999, when the building was renovated into the current convenience store and gasoline dispensing station. A canopy was constructed in the western portion in 1980, which was replaced with the current canopy in 1997. The property has operated as a gasoline dispensing station since 1999.

The following table summarizes the conditions identified as part of this assessment. Affirmative answers are further discussed below the table:

Type of Condition	Identified During the Course of this Assessment
De Minimis Condition	No
Significant Data Gap	No
Historical Recognized Environmental Condition (HREC)	No
Recognized Environmental Condition (REC)	Yes
Controlled Recognized Environmental Condition (CREC)	Yes
Significant Non-ASTM Scope Considerations and/or Business Environmental Risks	No

## **Recognized Environmental Condition**

We have performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM Practice E 1527-13 of the Commercial Property and Gasoline Dispensing Station located at 945 and 975 South Rochester Road, Rochester Hills, Oakland County, Michigan, the subject property. Any exceptions to, or deletions from, this practice are described in Section 1.4 of this report. This assessment has revealed no evidence of recognized environmental conditions connected with the property except the following:

- The subject property, 975 South Rochester Road, operated as a gasoline dispensing station since between 1964 and 1967. Additionally, the subject property is a closed Leaking Underground Storage Tank (LUST) site with two reported releases in 1996. The releases were granted a Restricted Tier I Commercial III Closure in February 2005. Review of previous site assessment activities documents that soil and groundwater contamination remains on-site above the current Part 213 Residential and Nonresidential Risk Based Screening Levels (RBSLs). In addition, contaminant concentrations may be indicative of a vapor intrusion concern. Based on these analytical results and its closed LUST status, the subject property meets the definition of a "property," in accordance with Part 213 of P.A. 451 of the Michigan Natural Resources Environmental Protection Act (NREPA), as amended.
- Review of previous site investigations document the current UST system was last assessed in August 2008. The subject property has continued to operate as a gasoline dispensing station with the current layout since August 2008 with no site assessment activities since that time. The potential exists that a new release has occurred from the current UST system and/or fuel dispensers.
- The subject property, 975 South Rochester Road, operated as a gasoline service station from at least 1967 until 1999. Historical interior waste streams associated with the former service operations would have consisted of general hazardous substances and/or petroleum products. The previous site investigation activates did not adequately assess all areas of the former gasoline service station. A significant portion of this time period preceded major environmental regulations and current waste management and disposal procedures. The historical waste management practices associated with the former gasoline service station operations are unknown and may be a source of subsurface contamination.

- The previous site investigation activates did not adequately assess the former gasoline service station area, which likely contained in-ground hoists. In-ground hoists have an underground reservoir for hydraulic fluids, which can contain polychlorinated biphenyls (PCBs). The potential exists that a release occurred from the former hydraulic hoist system and/or underground reservoir.
- The subject property, 975 South Rochester Road, operated as a gasoline dispensing and/or service station since between 1964 and 1967. PM was unable to obtain information regarding the UST systems prior to and between 1967 and 1972. Therefore, additional fueling and/or new or waste oil USTs may have historically been present. Further, records indicate the subject buildings were connected to natural gas in 1978 and 1980, and the 975 South Rochester Road subject building likely utilized a fuel oil UST prior to natural gas connection. The potential exists for orphan USTs to be present on the property and/or for a release to have occurred.

No adjoining and/or nearby RECs have been identified.

## **Controlled Recognized Environmental Condition**

A CREC, as defined in the ASTM Standard, is a recognized environmental condition (REC) resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls. The following CREC was identified during completion of this Phase I ESA:

• As discussed in the REC section above, the subject property, 975 South Rochester Road, is a closed LUST site with two releases reported in 1996. The release was granted a Restricted Tier I Commercial III Closure in February 2005. Review of previous site assessment activities documents that soil and groundwater contamination remains on-site above the current Part 213 Residential and Nonresidential RBSLs. In addition, contaminant concentrations may be indicative of a vapor intrusion concern. A deed restriction was recorded in 2004 that eliminates the use of groundwater for any purpose on the subject property, and any future change in the land use may necessitate further evaluation of potential risks to the public health, safety, and welfare to the environment. Based on the closed LUST status and restrictions associated with the LUST closure, PM has identified the closed LUST status as a CREC.

#### Recommendations

These RECs have been brought to the attention of the client within the requirements of the ASTM Standard Designation E-1527-13.

PM has been engaged to complete a Baseline Environmental Assessment (BEA) and a Documentation of Due Care Compliance (DDCC) which will be provided under separate cover.

The summary presented above is general in nature and should not be considered apart from the entire text of the report, which contains the qualifications, considerations and subject property details mentioned herein. Details of findings and conclusions are elaborated upon in this report.

## Phase I ESA of the Commercial Property and Gasoline Dispensing Station Located at 945 and 975 South Rochester Road, Rochester Hills, Michigan PM Project No. 01-11390-0-0001; September 10, 2019

This report has been reviewed for its completeness and accuracy. Please feel free to contact our office at 248.336.9988 to discuss this report.

**REPORT PREPARED BY:** 

PM Environmental, Inc.

Jacob Bloom Staff Consultant **REPORT REVIEWED BY:** 

Juller Galle

PM Environmental, Inc.

Kristin Gable

National Manager – Due Diligence Group

Steven E. Price, CHMM Principal and Vice President

## **TABLE OF CONTENTS**

1.0	INTRODUCTION	1	
	1.1: Property Overview	1	
	1.2: Purpose and Scope of Services	1	
	1.3: Significant Assumptions		
	1.4: Limitations, Deviations, and Special Terms and Conditions		
2.0			
	2.1: Recorded Land Title Records		
	2.2: Reason for Performing this Phase I ESA		
3.0			
4.0			
_	4.1: Aerial Photographs and Sanborn Maps		
	4.2: Local Street Directories		
	4.3: Assessing Department		
	4.4: Building Department		
	4.5: Fire Department		
	4.6: Health Department		
	4.7: Utilities		
	4.7.1: Municipal Water/Water Wells		
	4.7.2: Sanitary Sewer/Septic System		
	4.7.3: Heat Source		
	4.8: Underground Storage Tank (UST) Systems		
	4.9: Previous Environmental Reports		
	4.9.1: Summary of Previous Environmental Reports		
	4.10: Environmental Liens, Activity and Use Limitations, and Government Institutional		
	Engineering Controls		
5.0			
6.0			
7.0		15	,
	7.1: Subject Property Observations		
	7.1.1: Current Operations		
8.0	·		
9.0			
	9.1: Subject Property and Occupant Listings		
	9.2: Adjoining and Nearby Sites		
	0 FINDINGS, OPINIONS AND CONCLUSIONS		
	10.1: De Minimis Condition		
	10.2: Significant Data Gaps		
	10.3: Historical Recognized Environmental Conditions (HRECs)		
	10.4: Recognized Environmental Conditions (RECs)		
	10.5: Controlled Recognized Environmental Conditions (CRECs)	22	,
	10.6: Recommendations		
11.0		23	
12.			
13.			

## **FIGURES**

Figure 1: Property Vicinity Map

Figure 2: Generalized Diagram of the Subject Property and Adjoining Properties

## **APPENDICES**

Appendix A: Property Photographs from Site Reconnaissance Appendix B: Correspondence and Supporting Documentation

Appendix C: Previous Site Investigations

Appendix D: Regulatory Database and File Review Correspondence

Appendix E: Professional Resumes

Appendix F: Acronyms and Terminology, Scope of Work, ASTM Reference Document, and

User's Continuing Obligations under CERCLA

#### 1.0 INTRODUCTION

This Phase I ESA was conducted in accordance with (1) the United States Environmental Protection Agency (USEPA) Standards and Practices for All Appropriate Inquiries {(AAI), 40 CFR Part 312} and (2) guidelines established by the American Society for Testing and Materials (ASTM) in the Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process / Designation E 1527-13 (ASTM Standard Practice E 1527-13).

## THIS REPORT WAS PREPARED FOR THE EXCLUSIVE USE OF <u>ROCHESTER AVON PARTNERS, LLC</u>, WHOM MAY RELY ON THE REPORT'S CONTENTS.

PM acknowledges that this party may rely on the contents and conclusions presented in this report. Unless stated otherwise in writing, PM makes no other warranty, representation, or extension of reliance upon the findings of this report to any other entity or third party.

## 1.1: Property Overview

Subject Property	945 and 975 South Rochester Road, Rochester Hills, Oakland County,
Location/Address	Michigan
Number of Parcels and Acreage	Two parcels totaling 1.01 acres
Number of Building(s) and Square Footage	One single-story multi-tenant commercial building containing 5,409 square feet (945 South Rochester Road) and one single-story convenience store building containing 1,407 square feet (975 South Rochester Road)
Current Property Use	945 Rochester Road: Retail sales of jewelry and professional office activities 975 South Rochester Road: Gasoline dispensing station
Current Zoning	B-2: General Business and B-5: Automotive Business

The subject property location is depicted on Figure 1, Property Vicinity Map. A diagram of the subject property and adjoining properties is included as Figure 2, Generalized Diagram of the Subject Property and Adjoining Properties. Photographs taken during the site reconnaissance are included in Appendix A.

## 1.2: Purpose and Scope of Services

The purpose of this Phase I ESA was to evaluate the current and historical conditions of the subject property in an effort to identify *recognized environmental conditions* (RECs), *controlled recognized environmental conditions* (CRECs), and *historical recognized environmental conditions* (HRECs) in connection with the subject property. This Phase I ESA is intended to reduce, but not eliminate, uncertainty regarding the potential for RECs, CRECs, and HRECs in connection with the subject property.

Acronyms and terms used in this report are described in Appendix F. Additionally, PM's scope of services is included in Appendix F.

## 1.3: Significant Assumptions

Pursuant to ASTM Standard Practice E 1527-13, PM assumes that the information provided by all sources and parties, including the User, is accurate and complete, except where obvious inconsistencies or inaccuracies were identified.

#### 1.4: Limitations, Deviations, and Special Terms and Conditions

There are no deviations from the ASTM Standard. Non-ASTM Scope considerations are included in Section 11.0. Any physical limitations identified during the completion of this report are referenced in Section 7.0.

Due to changing environmental regulatory conditions and potential on-site or adjacent activities occurring after this assessment, the client may not presume the continuing applicability to the subject property of the conclusions in this assessment for more than 180 days after the report's issuance date, per ASTM Standard Practice E 1527-13.

To the best of PM's knowledge, no special terms or conditions apply to the preparation of this Phase I ESA that would deviate the scope of work from the ASTM Standard Practice E 1527-13.

PM was not provided with a copy of the recorded land title records for subject property by the client and was not requested to complete a title search. Therefore, PM cannot comment on any potential relevant information that may have been obtained through review of these records.

#### 2.0 USER PROVIDED INFORMATION

The ASTM Standard defines a User as "the party seeking to use Practice E 1527 to complete an environmental site assessment. A User may include, without limitation, a potential purchaser of property, a potential tenant of property, an owner of property, a lender, or a property manager." The User has specific obligations for completing a successful application of this practice as outlined in Section 6 of the ASTM Standard Practice E 1527-13.

In order to qualify for one of the Landowner Liability Protections (LLPs) offered by the Small Business Liability Relief and Brownfield's Revitalization Act of 2001 (the "Brownfield's Amendments") (if desired), the User must provide certain information (if available) identified in the User Questionnaire to the environmental professional. Failure to provide this information could result in a determination that "all appropriate inquiry" is not complete.

The following responses were provided by the User. A copy of the completed User Questionnaire is included in Appendix B.

Question	Response
Name of Preparer and User Entity	Mr. Doraid Markus; Rochester Avon Partners, LLC
Are you aware of any environmental cleanup liens against the property that are filed or recorded under federal, tribal, state or local law?	No
Are you aware of any Activity and Use Limitations, such as engineering controls, land use restrictions or institutional controls that are in place at the site and/or have been filed or recorded in a registry under federal, tribal, state or local law?	Yes; it is a gasoline dispensing station Refer to Section 4.10 for additional information.

Question	Response	
As the user of this ESA do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business?	No	
Does the purchase price being paid for this property reasonably reflect the fair market value of the property?	Yes	
If you conclude that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the property?	Not applicable	
Are you aware of commonly known or reasonably ascertainable information about the property that would help the environmental professional to identify conditions indicative of releases or threatened releases? For example, as user:		
Do you know the past uses of the property?	Yes; gasoline dispensing stations Refer to Sections 4.9 and 6.0 for additional information.	
Do you know of specific chemicals that are present or once were present at the property?	No	
Do you know of spills or other chemical releases that have taken place at the property?	No	
Do you know of any environmental cleanups that have taken place at the property?	No	
As the user of this ESA, based on your knowledge and experience related to the property are there any obvious indicators that point to the presence or likely presence of contamination at the property?	No	

## 2.1: Recorded Land Title Records

PM requested reasonably ascertainable recorded land title records for the subject property from the User. However, PM did not receive any title records from the User within the time constraints of this report. Additionally, PM was not requested to complete a title search by the User. PM did review available environmental lien and activity and use limitations for the subject property, which are further discussed in Section 4.10. Based upon the information reviewed as part of this Phase I ESA, PM has not identified the lack of provided land title records as a data failure that represents a significant data gap.

## 2.2: Reason for Performing this Phase I ESA

According to the User, this Phase I ESA was conducted as part of environmental due diligence related to purchasing the subject property.

## 3.0 PHYSICAL SETTING

	NG INFORMATION FOR THE SUBJECT TY AND SURROUNDING AREA	SOURCE	
Topography: Refer to Figure 1 for an excerpt of the Topographic Map			
Site Elevation	843 feet above mean sea level (msl)	United States Geological	
Topographic Gradient	Northwest	Survey Division (U.S.G.S.) 7.5-Minute Topographic	
Closest Surface Water	The Clinton River located approximately 835 feet northwest of the subject property at an elevation of 820 feet above msl	Map of the Rochester, Michigan Quadrangle, 1967 (photo revised in 1981)	
General Soil Character descriptions	ristics: Refer to Appendix B for a copy of the so	il survey map and soil type	
Soil Type	Urban land		
Description	This soil type is typically an area covered by commercial buildings, condominiums, apartment buildings, parking lots, streets, sidewalks, driveways, railroad yards, industrial complexes, and other structures. Permeability and corrosivity are not defined. A typical soil profile is not defined.	United States Department of Agriculture, Custom Soil Survey of Oakland County, Michigan (survey area data: September 7, 2018)	
Area Specific Geology	/Hydrogeology Characteristics:		
Geology	Geology consists of sand to between 5.0 below ground surface (bgs), a mix of sand and silt to 11.0 feet bgs, underlain by clay to 14.0 feet bgs, the maximum depth explored.	Previous site investigations	
Hydrogeology	Perched groundwater was encountered between 3.5 and 5.5 feet bgs. Groundwater flow direction was calculated to the northwest, towards the Clinton River	for the subject property (April 1997-July 2008)	
Oil and Gas Wells:			
Current Oil and Gas Wells on Subject Property	None identified	Michigan Department of Environment, Great Lakes,	
Historical Oil and Gas Wells on Subject Property	None identified	and Energy (EGLE) Oil, Gas and Minerals Division (OGMD) Data Portal	

## 4.0 RECORDS REVIEW

PM reviewed reasonably ascertainable records to identify obvious uses of the subject property from the present, back to the property's obvious first developed use, or back to 1940, whichever is earlier. Reasonably ascertainable records reviewed as part of this Phase I ESA documented the use of the property back to 1940. Data failure occurred prior to that date and between 1949 and 1957. In PM's professional opinion, this data failure does not represent a significant data gap.

## 4.1: Aerial Photographs and Sanborn Maps

PM reviewed reasonably ascertainable aerial photographs for the subject property area. The sources and years reviewed are identified in the table below. Relevant aerial photographs are included in Appendix B.

PM attempted to review reasonably ascertainable Sanborn Fire Insurance Maps for the subject property. However, no Sanborn Fire Insurance Maps were available for the subject property.

The following table summarizes the sources reviewed and the information obtained about the subject property from these sources. Information obtained about the adjoining properties from these sources is summarized in Section 8.0.

## **Aerial Summary for the Subject Property**

Year and Source	Summary of Information
rear and Source	Appears to be utilized for agricultural purposes based on the well-defined crop
1940 Aerial (Oakland County)	rows. East Avon Road is present to the south and South Rochester Road is present to the west.
1949 Aerial (WSU)	945 South Rochester Road: A driveway utilized by the northeast adjoining property is present in the northern portion.  The remainder appears similar to the previous aerial year.
1957 Aerial (WSU)	Agricultural activities have ceased.  945 South Rochester Road: A building has been constructed in the central portion. A driveway is visible in the northern and eastern portions.  975 South Rochester Road: A driveway is visible along the eastern subject property boundary. The remainder appears to consist of vacant land.
1963 Aerial (Oakland County)	945 South Rochester Road: A driveway is visible in the southern portion.  The remainder appears similar to the previous aerial year.
1967 Aerial (WSU)	945 South Rochester Road: Driveways and parking areas surround the building. 975 South Rochester Road: The current building has been constructed in the northeastern portion. Fuel dispensers are visible south and west of the building. Paved parking areas surround the building.
1970 Aerial (SEMCOG)	Similar to the previous aerial year.
1974 Aerial (Oakland County)	Similar to the previous aerial year.
1980 Aerial (Oakland County)	<ul><li>945 South Rochester Road: Additions to the northern portion of the building have been constructed.</li><li>975 South Rochester Road: A canopy has been constructed in the western portion.</li></ul>
1983 Aerial (MSU)	Similar to the previous aerial year.
1990 Aerial (Oakland County)	Similar to the previous aerial year.
1997 Aerial (Oakland County)	975 South Rochester Road: The former canopy has been removed and the current canopy has been constructed in the western portion.  The remainder appears similar to the previous aerial year.
2002 Aerial (Oakland County)	Similar to the previous aerial year.
2006 Aerial (Oakland County)	975 South Rochester Road: The fuel dispenser in the southern portion has been removed.  The remainder appears similar to the previous aerial year and appears similar to the current layout.

Year and Source	Summary of Information
2010 Aerial (Oakland County)	Similar to the previous aerial year.
2014 Aerial	
(Oakland County)	Similar to the previous aerial year.
2017 Aerial (Oakland County)	Similar to the previous aerial year.

A summary of this information along with other historical sources is included in Section 6.0.

## 4.2: Local Street Directories

Reasonably ascertainable local street directories for Rochester Hills, Michigan were researched. Directories were available from 1957 to 2014. Directories were researched in at least five-year increments, when available. It should not be construed that the earliest date represented is the initial date of occupancy.

## Subject Property: 945 South Rochester Road

2014	Professional Offices
	DMK Construction Services
	International Diamond Importer
	JS Capitol Construction Inc.
2007-2003	Agape Salon and Spa
	International Diamond Importers and Jewelry
	Premiere Condominium Managing LLC
2001-2000	Bill Barrett Seminars
2001 2000	Cruise Holidays
	International Jewelry Inc.
1998-1997	Professional Offices
1000 1001	International Jewelry
	Perraut Corporation
	Remote Executive Service
	Universal School Products
	Western Staff Service
1995-1994	Professional Offices
1990-1994	International Diamond Importers
	Remote Executive
1993-1992	Professional Offices
1995-1992	-
	International Diamond Importers
	Jewelry Creations
	Perraut Corporation Victoria Secret Nails
1000 1000	
1990-1989	Bach Computers
	Professional Offices
	International Diamond Importers
4007 4000	Perraut Corporation
1987-1986	Professional Offices
	International Diamond Importers
	Perraut Corporation

1984-1983	Professional Offices Rochester Unity Stop Smoking Center
1001 1000	Unity of Rochester
1981-1980	Marine Strong S-
	Perraut Rooney PLC
	Storage Big Erector
1978-1977	Not Listed
1975-1974	Groom Room
	Oakland Groom Room
1972-1971	Oakland Groom Room
1969-1965	Not Listed
1963-1962	Pet Land
1960	Residential
1957	Not Listed

## Historical Subject Property: 943 South Rochester Road

2014-1983	Not Listed
1981-1980	The Heritage Group
	Realty World
1978-1977	Not Listed
1975-1957	Rochester Veterinary Hospital

## **Subject Property: 975 South Rochester Road**

2014	Amy Plus Inc.
	K & B Mini Mart
2013	Amy Plus Inc.
	K & B Mini Mart
	UHaul Neighborhood Dealer Shell
2012-2011	UHaul Neighborhood Dealer Shell
2010	Not Listed
2007-2006	First Star Petro Mart
2004-1997	Rochester and Avon Shell
1995-1986	Winchester Shell
1984-1983	Plugins Rochester Shell
1981-1977	Not Listed
1975-1974	Rochester Hills Texaco
1972-1971	Ryder Truck Rental
	Rochester Hills Texaco
1969-1968	Bellairs Texaco Service
1966-1957	Not Listed

A summary of this information along with other historical sources is included in Section 6.0.

PM also reviewed listings for adjoining commercial properties. Information from the listings reviewed is included in Section 8.0.

## 4.3: Assessing Department

Reasonably ascertainable assessment information provided by the City of Rochester Hills Assessing Department was obtained and reviewed. Assessing records document that the subject property consists of two parcels totaling 1.01 acres. The northern parcel (945 South Rochester Road) is develop with a single-story commercial building containing 5,409 square feet and constructed between 1949 and 1957. The southern parcel (975 South Rochester Road) is developed with a single-story convenience store building containing 1,407 square feet, constructed between 1964 and 1967, and remodeled in 1999.

Historical assessing records document 945 South Rochester Road was historically occupied by the Rochester Veterinary Hospital, however, no specific dates were provided. A historical sketch identifies that additions to the northern portions of the commercial building at 945 South Rochester Road were constructed in 1977. An undated historical sketch for 975 South Rochester Road documents the eastern portion of the building historically contained two automotive service bays, and the western portion contained sales and office areas. No additional relevant historical information was provided in the records reviewed. Refer to Section 6.0 for additional information regarding the historical operations on the subject property. Copies of available assessment records for the subject property and the current legal description are included in Appendix B.

## 4.4: Building Department

PM submitted a Freedom of Information Act (FOIA) request to the City of Rochester Hills Clerk's Office to review building department records for the subject property. PM reviewed copies of electrical, mechanical, sign, and building permits for the subject parcels dated between 2005 and 2018. Additionally, PM reviewed historical aperture cards which contained historical building plans/blueprints for each of the current buildings on the subject property. A blueprint dated September 26, 1978 documents that 975 South Rochester Road contained two 10,000-gallon and one 6,000-gallon underground storage tanks (USTs) of unknown substances which were located south of the current building. Additionally, the blueprint documents one fuel dispenser was located south of the building and two fuel dispensers were located west of the building. No additional relevant historical information was provided in the records reviewed. Refer to Section 4.8 for additional information regarding the current and former UST systems.

## 4.5: Fire Department

PM submitted a FOIA request to the City of Rochester Hills Clerk's Office to review fire department records for the subject property. PM reviewed copies of available fire department inspections for the subject parcels dated between 1978 and 2012. A tank installation permit for 945 South Rochester Road identifies that one 500-gallon propane aboveground storage tank (AST) was installed north of the building in March 1978. Fire inspection records for 975 South Rochester Road dated between January and November 1983, identify that the parcel operated as a gasoline service station and violations were identified with the repair of leaking fuel dispenser nozzles, and removal of 55-gallon drums of unknown product from the rear of the station. These violations were subsequently corrected. The remaining records identify minor fire code violations for each of the subject parcels, however, no outstanding violations have been reported.

## 4.6: Health Department

PM submitted a FOIA request to the Oakland County Health Department to review records for the subject property. PM did not receive a response within the time constraints of this report. If PM does receive a response, and it changes the findings of the report, the client will be notified. Based on information gathered as part of this Phase I ESA and PM's experience with files maintained by this office, it is unlikely that information provided will be relevant to this assessment. Therefore, PM has not identified this lack of response as a data failure that represents a significant data gap.

## 4.7: Utilities

#### 4.7.1: Municipal Water/Water Wells

The subject property is currently connected to municipal water. PM attempted to obtain initial tap dates for the subject property from a representative of the City of Rochester Hills Department of Public Works – Water and Sewer Division, but no dates could be provided. However, the representative indicated the water mains were initially installed within the subject property area in at least 1966. Based upon this information, the subject property was likely tapped to municipal water in 1966 or within several years of availability. Prior to municipal water connection, the subject property likely utilized a private water well. Based on the lack of current use, PM has not identified the potential former water well as a REC.

## 4.7.2: Sanitary Sewer/Septic System

The subject property is currently connected to municipal sewer. PM attempted to obtain initial tap dates for the subject property from a representative of the City of Rochester Hills Department of Public Works – Water and Sewer Division, but no dates could be provided. However, the representative indicated the sewer mains were initially installed within the subject property area in at least 1966. Based upon this information, 975 South Rochester Road was likely tapped to municipal sewer in 1966, which is consistent with initial construction. Prior to municipal sewer connection, 945 South Rochester Road likely utilized a private septic field. Based on the previous veterinarian hospital use of 945 South Rochester Road prior to 1966, PM has not identified the potential former septic field as a REC.

#### 4.7.3: Heat Source

The subject property is connected to natural gas, which is supplied by Consumers Energy. Review of the Consumers Energy SIMS website indicates that 945 and 975 South Rochester Road were connected to natural gas between 1978 and 1980. Review of a natural gas main distribution map identifies the mains within the vicinity of the subject property were installed in at least 1952. Therefore, 1978 and 1980 are likely reconnection dates and the subject property was likely connected to natural gas in 1952 and or within several years of initial development.

Additionally, Fire Department records document that 945 South Rochester Road utilized a 500-gallon propane tank in at least March 1978, which may have been utilized for heating purposes. Based on the gaseous nature of the propane, PM has not identified the former propane tank as a REC. Additionally, previous site investigations identify a 1,000-gallon fuel oil UST was historically utilized in the gasoline service station (975 South Rochester Road) in at least 1977, which was likely utilized to heat the gasoline service station. PM has identified the potential historical fuel oil use as a REC, which is further discussed in Section 4.8.

## 4.8: Underground Storage Tank (UST) Systems

The subject property contained at least five former USTs. The following table indicates the size of the UST, contents, location (if known), the dates of installation and removal, and the source of the information.

#### **Historical UST Information**

Size	Contents	Location	Date Installed	Date Removed	Source
550-gallons	Fuel oil	North of the building**	1977	Unknown*	Regulatory files
1,000-gallons	Used oil	South of the building**	1977	1997	Regulatory files
6,000-gallons	Gasoline	South of the building**	1972	2008	Regulatory files
10,000-gallons	Gasoline	South of the building**	1977	1997	Regulatory files
10,000-gallons	Gasoline	South of the building**	1972	2008	Regulatory files

<sup>\*</sup>Previous site investigations were unable to confirm when the 550-gallon fuel oil UST was removed from the property, however, the previous site investigation activities completed between 2004-2008 concluded the UST was likely removed in 1997.

At least five UST have been documented to have been removed from the property; however, 975 South Rochester Road operated as a gasoline dispensing and/or service station since between 1964 and 1967. PM was unable to obtain information regarding the UST systems prior to and between 1967 and 1972. Therefore, additional fueling and/or new or waste oil USTs may have historically been present. Further, records indicate the subject buildings were connected to natural gas in 1978 and 1980, and the 975 South Rochester Road subject building utilized a fuel oil UST prior to natural gas connection. The potential exists for orphan USTs to be present on the property and/or for a release to have occurred, which represents a REC.

The current UST system consists of one 8,000-gallon compartmental diesel and gasoline UST, and one 10,000-gallon gasoline USTs. The USTs are located south and west of the subject building (see Figure 2).

The following table describes the date of installation, contents and size for the current UST system, as well as the materials of construction and leak detection devises, and should be considered informational only. It should be noted that PM did not physically confirm the construction information and can only report what is indicated in state UST registration information and/or what is provided by the current owner. PM is not a certified UST installer or inspector. A complete UST system compliance inspection by a licensed UST installation and maintenance contractor would be necessary to confirm compliance with all applicable state and federal regulations.

## **Current UST System**

Tank Number	6	7
Year Installed	1996	2008

<sup>\*\*</sup>USTs located north and south of the 975 South Rochester Road subject building.

Registration Status/Proof of Insurance  Do the Tanks appear to meet 1998 requirements?  Tank Construction Stored  Over Fill Protection Equipment  Tank Corrosion Protection Equipment  Tank Release Detection (Type)  Piping Release Detection (Type)  Tightness Tested (yes/no) & date of last test Piping Corrosion Protection  Protection (Type)  Piping Corrosion Protection (Type)  Piping Corrosion Protection (Type)  Piping Release Detection (Type)  Tightness Tested (yes/no) & date of last test Piping Corrosion Protection (Type)  Protection (Type)  Piping Corrosion Protection (Type) (Type)  Piping Corrosion Protection (Type)	Ci-o	10 000 gallana	0.000 gallana (dual compartment)	
CLARA  Bureau of Fire Services Storage Tank Division (STD). PM did not receive the pollution liability insurance documentation within the time constraints of this report, however, the current owner indicated the USTs are privately insured.    Do the Tanks appear to meet 1998   Yes	Size	10,000-gallons	8,000-gallons (dual compartment)	
the pollution liability insurance documentation within the time constraints of this report, however, the current owner indicated the USTs are privately insured.  Tank construction  Substance Stored  Over Fill Protection Equipment  Tank Corrosion Protection  Equipment  Tank Release Detection  (Type)  Piping Release Detection  \$\text{\$\text{\$Ves\$}}\$  Tightness Tested (yes/no) & date of last test  Piping Construction  Posserved observation wells in the current gasoline UST basin. No additional monitoring  PM observed observation wells were identified on the subject property.	Registration			
Tank Corrosion Protection (Type)  Piping Release Detection (Type)  Tightness Tested (yes/no) & date of last test Piping Construction Protection Fiberglase Piping Construction  Possive (yes/no) & date of last test Piping Construction Protection Protection Fiberglase Piping Construction Piping Corrosion Protection Fiberglase Piping Construction Piping Corrosion Protection Piping Corrosion Protection Automatic tank gauging, inventory control, and overfill and spill device protection Automatic line leak detectors Current property owner.  Fiberglass reinforced plastic  Piping Corrosion Protection Protection Protection Piping Corrosion Protection Possive (yes/no) Ada (yes/no) Ad	Status/Proof of			
Do the Tanks appear to meet 1998 requirements?  Tank Construction Substance Stored Over Fill Protection Equipment Tank Corrosion Protection Equipment Tank Release Detection (Type) Piping Release Detection (Type) Tightness Tested (yes/no) & date of last test Piping Construction Protection Fiberglass Reinforced Plastic Composite (steel with fiberglass)  Yes  Yes  Composite (steel with fiberglass)  Diesel and gasoline  Not applicable for fiberglass  Fiberglass Petection (Automatic tank gauging, inventory control, and overfill and spill device protection Automatic line leak detectors  Fiberglass reinforced plastic  Piping Corrosion Protection Piping Corrosion Protection  Not applicable for fiberglass  PM was unable to obtain the most recent tightness test for the USTs from the current property owner.  Fiberglass reinforced plastic  PM observed observation wells in the current gasoline UST basin. No additional monitoring  PM observed observation wells were identified on the subject property.	Insurance			
appear to meet 1998 requirements?  Tank Construction Substance Stored Over Fill Protection Equipment Tank Corrosion Protection Equipped? Tank Release Detection (Type) Piping Release Detection (Type) Tightness Tested (yes/no) & date of last test Piping Construction Piping Construction Piping Construction Piping Corrosion Protection (Type) PM was unable to obtain the most recent tightness test for the USTs from the current property owner. Piping Construction Piping Corrosion Protection Posserved observation wells in the current gasoline UST basin. No additional monitoring PM observed observation wells were identified on the subject property.		report, however, the current owner	indicated the USTs are privately insured.	
Tank Construction Substance Stored Over Fill Protection Equipment Tank Release Detection (Type) Piping Release Detection (Type) Tightness Tested (yes/no) & date of last test Piping Construction Piping Construction Piping Construction Piping Corrosion Protection Piping Construction PM observed observation wells in the current gasoline UST basin. No additional monitoring PM observed observation wells in the current gasoline UST basin. No additional monitoring Piping Release Detection (Type) PM observed observation wells in the current gasoline UST basin. No additional monitoring monitoring wells were identified on the subject property				
requirements? Tank Construction Substance Stored Over Fill Protection Equipment Tank Corrosion Protection Equipped? Tank Release Detection (Type) Piping Release Detection (Type) Tightness Tested (yes/no) & date of last test Piping Construction Piping Corrosion Protection  Piping Construction  PM was unable to obtain the most recent tightness test for the USTs from the current property owner.  Fiberglass reinforced plastic  PM observed observation wells in the current gasoline UST basin. No additional monitoring  PM observed observation wells in the current gasoline UST basin. No additional monitoring  PM observed observation wells in the current gasoline UST basin. No additional	• •		Yes	
Tank Construction Substance Stored Over Fill Protection Equipment Tank Corrosion Protection (Type) Piping Release Detection (Type) Tightness Tested (yes/no) & date of last test Piping Construction Piping Corrosion Protection (Typing Corrosion Protection (Type)  Tightness Tested (yes/no) Automatic tank gauging, inventory control, and overfill and spill device protection (Type) Tightness Tested (yes/no) Automatic tenk gauging, inventory control, and overfill and spill device protection (Type) Tightness Tested (yes/no) Automatic line leak detectors (Type) Tightness Tested (yes/no) Automatic tank gauging, inventory control, and overfill and spill device protection (Type)  PM was unable to obtain the most recent tightness test for the USTs from the current property owner.  The control of the current property of the subject property o			100	
Construction Substance Stored Over Fill Protection Equipment Tank Corrosion Protection Equipmed?  Automatic tank gauging, inventory control, and overfill and spill device protection (Type) Piping Release Detection (Type) Tightness Tested (yes/no) & date of last test Piping Construction Piping Construction Piping Corrosion Protection  PM observed observation wells in the current gasoline UST basin. No additional monitoring Piping wells were identified on the subject property.				
Substance Stored  Over Fill Protection Equipment  Tank Corrosion Protection Equipped?  Tank Release Detection (Type)  Piping Release Detection (Type)  Tightness Tested (yes/no) & date of last test Piping Construction  Piping Corrosion Protection  Piping Corrosion Protection  Piping Corrosion Protection  PM was unable to obtain the most recent tightness test for the USTs from the current property owner.  Fiberglass reinforced plastic  PM observed observation wells in the current gasoline UST basin. No additional monitoring  PM observed observation wells in the current gasoline UST basin. No additional monitoring		Fiberalass Reinforced Plastic	Composite (steel with fiberglass)	
Stored Over Fill Protection Equipment  Tank Corrosion Protection Equipped?  Tank Release Detection (Type)  Piping Release Detection (Type)  Tightness Tested (yes/no) & date of last test  Piping Construction  Piping Corrosion Protection Number of Monitoring  PM observed observation wells in the current gasoline UST basin. No additional		1 iberglass Reimoreed Flastic	Gomposite (Steel With liberglass)	
Over Fill Protection Equipment  Tank Corrosion Protection Equipped?  Tank Release Detection (Type)  Piping Release Detection (Type)  Tightness Tested (yes/no) & date of last test  Piping Construction  Piping Corrosion Protection  Not applicable for fiberglass  Automatic line leak detectors (Lype)  Automatic line leak detectors (Lype)  PM was unable to obtain the most recent tightness test for the USTs from the current property owner.  Fiberglass reinforced plastic  Not applicable for fiberglass  PM observed observation wells in the current gasoline UST basin. No additional monitoring  PM observed observation wells in the current gasoline UST basin. No additional	Substance	Gasolina	Diesel and gasoline	
Protection Equipment  Tank Corrosion Protection Equipped?  Tank Release Detection (Type)  Piping Release Detection (Type)  Tightness Tested (yes/no) & date of last test  Piping Construction  Piping Corrosion Protection  Number of Monitoring  Monitoring  Not applicable for fiberglass  Not applicable for fiberglass  Not applicable for fiberglass  Pyes  Not applicable for fiberglass  Not applicable for fiberglass  PM observed observation wells in the current gasoline UST basin. No additional	Stored	Gasonie	Diesei allu gasolille	
Equipment Tank Corrosion Protection Equipped?  Tank Release Detection (Type)  Piping Release Detection (Type)  Tightness Tested (yes/no) & date of last test  Piping Construction  Piping Corrosion Protection  Number of Monitoring  Not applicable for fiberglass  PM observed observation wells in the current gasoline UST basin. No additional	Over Fill			
Tank Corrosion Protection Equipped?  Tank Release Detection (Type)  Piping Release Detection (Type)  Tightness Tested (yes/no) & date of last test  Piping Construction  Piping Corrosion Protection Number of Monitoring  Not applicable for fiberglass  Not applicable for fiberglass  Automatic line leak detectors Automatic line leak detectors  Automatic line leak detectors  Fiberglass recent tightness test for the USTs from the current property owner.  Fiberglass reinforced plastic  PM observed observation wells in the current gasoline UST basin. No additional	Protection		Yes	
Protection Equipped?  Tank Release Detection (Type)  Piping Release Detection (Type)  Tightness Tested (yes/no) & date of last test  Piping Construction  Piping Corrosion Protection  Not applicable for fiberglass  Automatic tank gauging, inventory control, and overfill and spill device protection  Automatic line leak detectors  Automatic line leak detectors  Current property owner.  Fiberglass reinforced plastic  Piping Corrosion Protection  Number of Monitoring  PM observed observation wells in the current gasoline UST basin. No additional	Equipment			
Tank Release Detection (Type)  Piping Release Detection (Type)  Tightness Tested (yes/no) & date of last test  Piping Construction  Piping Corrosion Protection  Number of Monitoring  Mutomatic tank gauging, inventory control, and overfill and spill device protection  Automatic line leak detectors  Automatic line leak detectors  Fiberglass recent tightness test for the USTs from the current property owner.  Fiberglass reinforced plastic  Not applicable for fiberglass  PM observed observation wells in the current gasoline UST basin. No additional	Tank Corrosion			
Tank Release Detection (Type)  Piping Release Detection (Type)  Tightness Tested (yes/no) & date of last test  Piping Construction  Piping Corrosion Protection  Number of Monitoring  Mutomatic tank gauging, inventory control, and overfill and spill device protection  Automatic line leak detectors Automatic line leak detectors  Current property development tightness test for the USTs from the current property owner.  Fiberglass reinforced plastic  Not applicable for fiberglass  PM observed observation wells in the current gasoline UST basin. No additional monitoring wells were identified on the subject property.	Protection	Not applica	ble for fiberglass	
Detection (Type)  Piping Release Detection (Type)  Tightness Tested (yes/no) & date of last test  Piping Construction  Piping Corrosion Protection  Number of Monitoring  Automatic tank gauging, inventory control, and overfill and spill device protection  Automatic line leak detectors  Automatic line leak detectors  Fundamental control contr	Equipped?			
Piping Release Detection (Type)  Tightness Tested (yes/no) & date of last test  Piping Construction  Piping Corrosion Protection  Number of Monitoring  Monitoring  Automatic line leak detectors  Automatic line leak detectors  Automatic line leak detectors  Fiberglass recent tightness test for the USTs from the current property owner.  The construction of the current property owner of the current property owner of the current property owner of the current gasoline UST basin. No additional property owner identified on the subject property owner.	Tank Release			
Piping Release Detection (Type) Tightness Tested (yes/no) & date of last test Piping Construction Piping Corrosion Protection Number of Monitoring  Automatic line leak detectors Automatic line leak detectors  Fiberglask detectors  Fiberglask recent tightness test for the USTs from the current property owner.  Fiberglass reinforced plastic  Not applicable for fiberglass  PM observed observation wells in the current gasoline UST basin. No additional monitoring wells were identified on the subject property.	Detection	Automatic tank gauging, inventory control, and overfill and spill device protection		
Tightness Tested (yes/no) & date of last test Piping Construction Piping Corrosion Protection Number of Monitoring  Monitoring  Automatic line leak detectors  PM was unable to obtain the most recent tightness test for the USTs from the current property owner.  Fiberglass reinforced plastic  Not applicable for fiberglass  PM observed observation wells in the current gasoline UST basin. No additional monitoring wells were identified on the subject property	(Type)			
Tightness Tested (yes/no) & date of last test Piping Construction Piping Corrosion Protection Number of Monitoring  Monitoring  Monitoring  PM was unable to obtain the most recent tightness test for the USTs from the current property owner.  Fiberglass reinforced plastic  Not applicable for fiberglass  PM observed observation wells in the current gasoline UST basin. No additional monitoring wells were identified on the subject property	Piping Release			
Tightness Tested (yes/no) & date of last	Detection	Automatic line leak detectors		
Tested (yes/no) & date of last test  Piping Construction  Piping Corrosion Protection  Number of Monitoring  PM was unable to obtain the most recent tightness test for the USTs from the current property owner.  Fiberglass reinforced plastic  Not applicable for fiberglass  PM observed observation wells in the current gasoline UST basin. No additional monitoring wells were identified on the subject property	(Type)			
& date of last test  Piping Construction  Piping Corrosion Protection  Number of Monitoring  Monitoring  Current property owner.  Fiberglass reinforced plastic  Not applicable for fiberglass  Protection  PM observed observation wells in the current gasoline UST basin. No additional	Tightness			
Test Piping Construction Piping Corrosion Protection Number of Monitoring  PM observed observation wells in the current gasoline UST basin. No additional monitoring wells were identified on the subject property.	Tested (yes/no)	PM was unable to obtain the most recent tightness test for the USTs from the		
Piping Construction Piping Corrosion Protection Number of Monitoring  PM observed observation wells in the current gasoline UST basin. No additional	& date of last	current property owner.		
Construction  Piping Corrosion Protection  Number of Monitoring  PM observed observation wells in the current gasoline UST basin. No additional	test			
Piping Corrosion Protection Number of Monitoring  PM observed observation wells in the current gasoline UST basin. No additional	Piping	Fiberglass reinforced plastic		
Corrosion Protection Number of Monitoring  PM observed observation wells in the current gasoline UST basin. No additional	Construction	ribergiass reinforced plastic		
Protection  Number of Monitoring  PM observed observation wells in the current gasoline UST basin. No additional monitoring wells were identified on the subject property.	Piping			
Protection  Number of Monitoring  PM observed observation wells in the current gasoline UST basin. No additional monitoring wells were identified on the subject property.		Not applicable for fiberglass		
Number of Monitoring  PM observed observation wells in the current gasoline UST basin. No additional monitoring wells were identified on the subject property.	Protection			
Monitoring wells were identified on the subject property		DM observed observation wells in the current assoling LICT basis. No additional		
	Monitoring			
wells on-site		monitoring wells were identified on the subject property.		

An automatic leak detection system was observed mounted on a wall in the office and appeared to be functioning normally. A fuel alarm was activated during the site reconnaissance associated with tank 7. According to a representative of the current occupant, the alarm is currently being addressed.

PM reviewed LARA STD registration and inspection records which document the most recent inspection was completed in September 2016. No violations were identified, and the facility was approved.

PM also obtained Michigan Department of Agricultural (MDA) inspection records that consisted of inspections that verified the dispensers were accurately dispensing the proper quantities of fuel, and skimmer inspections to verify that the card readers and security tape on the fuel dispensers were in good standing. The most recent MDA inspection was completed in April 2019, which did not document any violations associated with the card readers or fuel dispensers and the facility was approved.

Review of previous site investigations document the current UST system was last assessed in August 2008. The subject property has continued to operate as a gasoline dispensing station with the current layout since August 2008 with no site assessment activities since that time. The potential exists that a new release has occurred from the current UST system and/or fuel dispensers, which represents a REC.

## 4.9: Previous Environmental Reports

PM reviewed the following previous environmental reports for the subject property. Relevant portions of the reports are included in Appendix C.

Name of Report	Date of Report	Company that Prepared Report
Final Assessment Report	4-8-1997	EnecoTech Midwest, Inc. (ETM)
Groundwater Monitoring Report	7-28-1997	ETM
Groundwater Monitoring Report	10-8-1997	ETM
Groundwater Monitoring Report	1-22-2003	Groundwater & Environmental Services, Inc. (GES)
Closure Report	8-27-2004	GES
Phase I ESA	2-22-2005	AKT Peerless Environmental Services (AKT)
Subsurface Investigation Report	3-31-2005	AKT
Underground Storage Tank System Assessment and Closure Report	7-17-2008	Midwest Environmental Consulting Group (MECG)

## 4.9.1: Summary of Previous Environmental Reports

Open or Closed LUST Site:	Closed
Release Identification(s):	C-0214-96 and C-0252-96
Release Date(s)	April 8, 1996 and April 24, 1996
Is soil contamination present above an applicable regulatory level?	Yes
Is soil contamination delineated in all directions?	No
Is groundwater contamination present above an applicable regulatory level?	Yes
Is groundwater contamination delineated in all directions?	No
Significant deficiencies identified?	Yes; lack of sampling in the areas of former service operations; lack of ground penetrating radar (GPR) survey data to assess the for potential orphan USTs.

The subject property, 975 South Rochester Road, is a closed LUST site with two releases reported on April 8, 1996 (Leak ID: C-0214-96) and April 24, 1996 (Leak ID: C-0252-96) which were granted a Tier I Commercial III Restricted Closure on February 17, 2005.

Various site assessment activities were conducted between 1997 and 2008 which included the removal of several USTs along with the excavation of approximately 40 cubic yards of soil; soil and groundwater sampling activities; and groundwater monitoring activities. Analytical results following the August 2004 Closure Report and March 2005 Subsurface Investigation Report groundwater sampling events exceed the current Part 213 Risk Based Screening Levels (RBSLs),

and the current Recommended Interim Action Screening Levels (RIASLs) indicating a vapor intrusion concern may be present. Additionally, the March 2005 site investigation activities included a ground penetrating radar (GPR) survey to assess the potential for orphan USTs. The report indicates the GPR survey did not identify any anomalies consistent with the presence of orphan USTs, however, the GPR analytical data was not included within the report reviewed. Therefore, PM has identified the lack of the GPR analytical data as a significant deficiency and the potential for orphan USTs as a REC, which is described in Section 4.8. Furthermore, the site investigation activities completed between 1997 and 2008 did not collect any groundwater or soil samples within the footprint of the subject building. Therefore, the long-term historical automotive service operations have not been adequately assessed and is identified as a REC. Refer to Section 6.0 for additional information.

Based on the cumulative 1997-2008 analytical results, concentrations of various gasoline VOCs were identified in soil and groundwater exceeding the current Part 213 Residential and Nonresidential Risk Based Screening Levels (RBSLs). In addition, contaminant concentrations may be indicative of a vapor intrusion concern based on the separation distance and lack of delineation of contamination towards the subject building. Based on these analytical results and its closed LUST status, the subject property meets the definition of a "property," in accordance with Part 213 of P.A. 451 of the Michigan Natural Resources Environmental Protection Act (NREPA), as amended, which represents a REC.

Additionally, based on the closed LUST status and restrictions associated with the LUST Closure, PM has identified the closed LUST status as a CREC.

## 4.10: Environmental Liens, Activity and Use Limitations, and Government Institutional and Engineering Controls

Review of the Deed-Restricted Closure from August 2004 indicated a deed restriction was recorded for the subject property. The deed restriction eliminates the use of groundwater for any purpose on the subject property, and any future change in the land use may necessitate further evaluation of potential risks to the public health, safety, and welfare to the environment.

## 5.0 INTERVIEWS

The objective of completing interviews with knowledgeable site contacts is to obtain information about the uses and physical characteristics of the property. In general, interviewees supported the information reviewed from other historical sources (i.e. aerial photos, city records, etc.).

Represents	Interviewed	Name and Title	Length of Time Associated with Subject Property	Comments
Current Property Owner and Yes Key Site Manager		Ms. Arleen Allen, current property owner of 945 South Rochester Road	22 years	Ms. Allen indicated the subject property has been occupied by various retail businesses and professional offices since the 1990s. Ms. Allen also identified that the subject property was historically occupied by a veterinarian hospital, but could not provide specific dates. Ms. Allen did not identify any environmental concerns or USTs associated with the subject property.
		Mr. Doraid Markus, User, current property owner of 975 South Rochester Road	Two months	Mr. Markus indicated the subject property has been historically occupied by various gasoline dispensing station operations since the 1960s. No additional information was provided by Mr. Markus.
Former Property Owner	No	Not applicable	Not applicable	Contact information for the former owner was not reasonably ascertainable or provided by the User
Current Occupant(s)	No I Notannicania I		Not applicable	PM attempted to interview the current occupants of the subject property, however, no relevant information could be provided.
Former Occupant(s) No Not applicable		Not applicable	Contact information for the former occupants was not reasonably ascertainable or provided by the User	
Other(s)	No	Not applicable	Not applicable	No other relevant interviews were conducted as part of this Phase I ESA.

## 6.0 SUMMARY OF HISTORICAL USE

## 945 South Rochester Road

Standard and historical sources were able to document the subject property was developed with agricultural fields from at least 1937 until between 1949 and 1957 when the current commercial building was constructed. Additions to the northern portion of the building were constructed in 1977. Occupants of the property included a veterinarian hospital from at least 1957 until 1975 and various retail businesses and professional offices since the late 1970s. PM was unable to identify occupants of the building prior to 1957. However, based upon the size and layout of the building

during this time period, the building was likely utilized for similar veterinarian hospital operations prior to 1957.

## 975 South Rochester Road

Standard and historical sources were able to document the subject property consisted of agricultural and vacant land from at least 1937 until between 1964 and 1967 when the current building was constructed in the northeastern portion. The building was utilized for gasoline service station operations from at least 1967 until 1999, when the building was renovated into the current convenience store and gasoline dispensing station. A canopy was constructed in the western portion in 1980, which was replaced with the current canopy in 1997. The property has operated as a gasoline dispensing station since 1999.

Historical interior waste streams associated with the former service operations would have consisted of general hazardous substances and/or petroleum products. The previous site investigation activates did not adequately assess all areas of the former gasoline service station. A significant portion of this time period preceded major environmental regulations and current waste management and disposal procedures. The historical waste management practices associated with the former gasoline service station operations are unknown and may be a source of subsurface contamination, which represents a REC.

The previous site investigation activates did not adequately assess the former gasoline service station area, which likely contained in-ground hoists. In-ground hoists have an underground reservoir for hydraulic fluids, which can contain polychlorinated biphenyls (PCBs). The potential exists that a release occurred from the former hydraulic hoist system and/or underground reservoir, which represents a REC.

## 7.0 SUBJECT PROPERTY RECONNAISSANCE

Reconnaissance Information		
PM Field Personnel:	PM Field Personnel: Mr. Jacob Bloom	
Site Reconnaissance Date: August 28, 2019		
Escort: No escort		
Limitations:	None identified	

## 7.1: Subject Property Observations

The northern parcel, identified as 945 South Rochester Road, consists of a single-story commercial building containing 5,409 square feet, and is divided into three tenant spaces which include retail areas, office areas, storage areas, and restrooms. The entire building is on a poured concrete foundation. Interior finish materials include metal deck ceilings, acoustical ceiling tiles, drywall ceilings and walls, concrete block walls, ceramic tile floors and walls, 12-inch by 12-inch vinyl floor tiles, and carpeting.

The southern parcel, identified as 975 South Rochester Road, consists of a single-story convenience store building containing 1,407 square feet, which is divided into a retail area, storage areas, an office, and restrooms. The entire building is on a poured concrete foundation. Interior finish materials include acoustical ceiling tiles, metal deck ceilings, drywall walls, wooden paneling, concrete block walls, ceramic tile floors, and poured concrete floors which appeared to be in good condition with no staining, damage, or cracking observed.

A canopy with four fuel dispensers is present west of the convenience store, which is further discussed below. Asphalt and concrete parking areas surround the subject buildings. The remainder of the property contains groomed grass and landscaped areas.

The following table summarizes the site observations. Affirmative responses are discussed in more detail following the table.

Category	Feature	Observed
	Elevators	No
	Air Compressors	No
	Incinerators	No
	Waste Treatment Systems	No
	Presses/Stamping Equipment	No
Interior Equipment	Press Pits and/or In-ground Pits	No
	Hydraulic Lifts or In-ground hoists	No
	Paint Booth	No
	Plating Tanks	No
	Parts Washers	No
	Lathes, Screw Machines, etc.	No
	Aboveground Storage Tanks (ASTs)	No
Aboveground Chemical or	Drums, Barrels and/or Containers > 5 gallons	No
Other Waste Storage or Waste Streams	Chip Hoppers	No
vvaste Streams	Hazardous or Petroleum Waste Streams	No
	Underground Storage Tanks	Yes
	Fuel Dispensers	Yes
Underground Chemical or	Sumps or Cisterns	No
Waste Storage, Drainage or	Dry Wells	No
Collection Systems	Oil/Water Separators	No
•	Floor Drains, Trench Drains, etc.	Yes
	Pipeline Markers	No
	Stressed Vegetation	No
	Stained Soil or Pavement	No
	Monitoring Wells	No
	Pad or Pole Mounted Transformers and/or Capacitors	Yes
	Soil Piles of Unknown Origin	No
	Exterior Dumpsters with Staining	No
Exterior Observations	Leachate or Other Waste Seeps	No
	Trash, Debris, and/or Other Waste Materials	No
	Uncontrolled Dumping or Disposal Areas	No
	Surface Water Discoloration, Sheen or Free Product	No
	Strong, Pungent or Noxious Odors	No
	Storm water retention or detention ponds	No
	Pits, Ponds, Lagoons	No

**Underground Storage Tanks:** Refer to Section 4.8 for additional information.

**Fuel dispensers:** Four fuel dispensers are located west of the convenience store building and are covered by a metal canopy. No staining or evidence of a release was observed in the area of the fuel dispensers and the concrete surrounding the dispensers appeared to be in good condition with no significant cracking or damage. However, PM has identified the gasoline dispensing operations since 2008 with no additional site investigation activities as a REC, which is further discussed in Section 4.8.

**Floor Drains, Trench Drains, etc.:** PM observed floor drains located within the restrooms, storage areas. No staining or evidence of poor waste management practices was observed in association with the drains.

Pad or Pole Mounted Transformers and/or Capacitors: The subject property is supplied with aboveground secondary electrical services from one pole-mounted transformers located in the southern portion of 945 South Rochester Road. The transformer is not labeled regarding polychlorinated biphenyl (PCB) content. No leakage of the transformers was observed at the time of the site reconnaissance.

#### 7.1.1: Current Operations

The northern parcel, identified as 945 Rochester Road, is occupied by retail sales of jewelry and professional office activities. The southern parcel, identified 975 South Rochester Road, is occupied by a gasoline dispensing station.

#### 8.0 ADJOINING PROPERTIES

The following paragraphs provide information about the adjoining properties obtained during the site reconnaissance and through review of reasonably ascertainable information.

## **North and East Adjoining Property**

The north and east adjoining property, identified as 923 South Rochester Road, is currently occupied by Comerica Bank. Review of historical sources document the property consisted of agricultural land from at least 1940 until between 1940 and 1949 when a dwelling was constructed in the northeastern portion. The building was demolished between 1957 and 1963 when a hospital building was constructed. The hospital building was demolished between 1970 and 1974 when the current building was constructed. Occupants of the property included a hospital from at least 1957 until 1974 and various bank branches since 1978.

#### South Adjoining Properties, West Avon Road

The south adjoining property, identified as 1039 South Rochester Road, is currently occupied by Leader Dogs for the Blind, a dog training center. Review of historical sources document the property consisted of agricultural land from at least 1940 until between 1949 and 1957 when several buildings were constructed. Additional buildings and additions were constructed to the buildings between the 1970s and 1980s, and several of the buildings in the northern portion were demolished in the late 1990s. The property has been occupied by Leader Dog for the Blind since at least 1957. This property is identified in the regulatory database. Refer to Section 9.2 for additional information.

The southwest adjoining property, identified as 1010 South Rochester Road, is currently occupied by a Speedway gasoline dispensing station. Review of historical sources document the property consisted of agricultural land from at least 1940 until between 1970 and 1974 when a gasoline service station was constructed. The property was renovated into a gasoline dispensing station during the late 1990s and has been occupied by various gasoline dispensing station operations since that time. This property is identified in the regulatory database. Refer to Section 9.2 for additional information.

## West Adjoining Property, across South Rochester Road

The west adjoining property, identified as 950 South Rochester Road, is currently occupied Sanyo Machine America Corporation, an automation assembly line manufacturer of automotive parts. Review of historical sources document the property consisted of agricultural land from at least 1940 until between 1949 and 1957 when the central and southern portions of the current building were constructed. Additions to the northern portion of the building were constructed in the 1970s and 1980s. Occupants of the property include Detroit Broach and Machine, a broach machine manufacturing company from at least 1957 until 1987; and the current occupant since 1989. This property is identified in the regulatory database. Refer to Section 9.2 for additional information.

## 9.0 REGULATORY RECORDS REVIEW

PM retained EDR to provide current regulatory database information compiled by a variety of federal and state regulatory agencies. A copy of the complete database is included in Appendix D. The following information was obtained:

Туре	Regulatory Agency Database	Approximate Minimum Search Distance (AMSD)	Number of Sites within AMSD
Federal	National Priority List (NPL) Sites	1 mile	0
Federal	Delisted National Priority List (DNPL) Sites	½ mile	0
Federal	Superfund Enterprise Management System (SEMS) (formerly CERCLIS – renamed in 2015) Sites	½ mile	0
Federal	SEMS-Archive Sites (formerly CERLIS-NFRAP – renamed 2015)	½ mile	0
Federal	Resource Conservation and Recovery Act (RCRA) Corrective Action Report (CORRACTS) Sites	1 mile	0
Federal	RCRA non-CORRACTS Treatment, Storage or Disposal Facilities (TSDF) Sites	½ mile	0
Federal	RCRA Large Quantity Generators (LQG) Sites	subject property and adjoining properties	0
Federal	RCRA Small Quantity Generators (SQG) Sites	subject property and adjoining properties	0
Federal	RCRA Conditionally Exempt Small Quantity Generators (CESQG) Sites	subject property and adjoining properties	0
Federal	RCRA Non-Generators (NON-GEN) Sites	subject property and adjoining properties	1
Federal	Institutional Control / Engineering Control Registries	subject property	0
Federal	Environmental Response and Notification System (ERNS)	subject property	0
State & Tribal	Hazardous Waste Sites (HWS) (equivalents to NPL and CERCLIS)	1 mile	0
State & Tribal	Solid Waste Facilities/Landfill Sites (SWF/LF)	½ mile	0
State & Tribal	Leaking Underground Storage Tank (LUST) Sites	½ mile	7
State & Tribal	Registered Underground Storage Tank (UST) Sites	subject property and adjoining properties	4

Туре	Regulatory Agency Database	Approximate Minimum Search Distance (AMSD)	Number of Sites within AMSD
State & Tribal	Institutional Control / Engineering Control Registries	subject property	0
State & Tribal	Brownfield Sites	½ mile	1
State & Tribal	Michigan Inventory of Facilities (Includes Part 201 Sites and Baseline Environmental Assessment {BEA} Sites)	½ mile	12
Either	Unmappable Database Listings (a.k.a. Orphan Sites)	database-dependent	0

## 9.1: Subject Property and Occupant Listings

The regulatory database report identified the following listings for the subject property or its known occupants on the referenced databases:

**Express 100 Inc.** – The subject property is identified as a Part 213 site on the Michigan Inventory of Facilities site, an active UST site, and closed LUST site with two reported releases in 1996. Refer to Section 4.9 for a summary of the LUST site investigation activities and Section 4.8 for a summary of the current and former UST systems.

The subject property is also identified as a Waste Data System (WDS) site, which is likely associated with the historical gasoline service station operations. PM attempted to review file information regarding the WDS listing, but no records were available. PM has identified the long-term historical gasoline service stations as a REC. Refer to Section 6.0 for additional information.

## 9.2: Adjoining and Nearby Sites

PM's review of the referenced databases also considered the potential or likelihood of contamination from adjoining and nearby sites. To evaluate which of the adjoining and nearby sites identified in the regulatory database report present an environmental risk to the subject property, PM considered the following criteria:

- The type of database on which the site is identified.
- The topographic position of the identified site relative to the subject property.
- The direction and distance of the identified site from the subject property.
- Local soil conditions in the subject property area.
- The known or inferred groundwater flow direction in the subject property area.
- The status of the respective regulatory agency-required investigation(s) of the identified site, if any.
- Surface and subsurface obstructions and diversions (e.g., buildings, roads, sewer systems, utility service lines, rivers, lakes, and ditches) located between the identified site and the subject property.

Only those sites that are judged to present a potential environmental risk to the subject property and/or warrant additional clarification are further evaluated. Using the referenced criteria, and based upon a review of readily available information contained within the regulatory database report, PM did not identify adjoining (i.e., bordering) or nearby sites (e.g., properties within a ¼-mile radius) listed in the regulatory database report that were judged to present a potential environmental risk to the subject property, with the exception of the following:

Detroit Broach and Machine and Sanyo Machine America – This property is identified as 950 South Rochester Road and is the west adjoining property. The regulatory database identifies this property as a closed UST site and a RCRA non-generator of hazardous waste site since at least 1980, with no reported violations. Review of regulatory file information documents the property historically utilized two 2,000-gallon used oil USTs, which were reported installed in 1970 and removed from the property in 1990. Soil analytical results from a sampling event from the UST basin during removal activities did not identified any contaminants above laboratory method detection limits (MDLs), therefore, a release was not reported. PM attempted to review regulatory file information regarding the RCRA listing, however no records were available to review. Based on the distance from the subject property (i.e. approximately 320 feet across South Rochester Road), the documented groundwater flow direction towards the northwest away from the subject property, and the lack of reported releases, PM has not identified this property as a REC.

**Speedway #8832** – This property is identified as 1010 South Rochester Road and is the southwest adjoining property. The regulatory database identifies this property as a Part 213 site on the Michigan Inventory of Facilities site, an active UST site, and an open LUST site with two reported releases in 1991 and 2014. Review of regulatory file information documents the releases were associated with several gasoline and diesel USTs which have since been removed. Site investigation activities document the property has removed 1,000 cubic yards of soil and remediated approximately 194,150 gallons of groundwater since 1993. However, site investigation activities completed in 2016 document contaminants in soil and groundwater above the Nonresidential Part 213 RBSLs. Based on the distance from the subject property (i.e. approximately 200 feet across East Avon Road), and the documented groundwater flow direction towards the northwest away from the subject property, PM has not identified this property as a REC.

**Leader Dog for the Blind** – This property is identified as 1039 South Rochester Road and is the south adjoining property. The regulatory database identifies this property as a closed UST site. The regulatory database indicates the property historically utilized one 1,000-gallon gasoline UST, which was installed in 1985 and removed in 1999. PM attempted to review regulatory file information regarding the UST listing, however a response was not received within the time constraints of this report. Based on the lack of reported releases, and the distance from the subject property (i.e. approximately 190 feet across East Avon Road), PM has not identified this property as a REC.

## 10.0 FINDINGS, OPINIONS AND CONCLUSIONS

#### 10.1: De Minimis Condition

A de minimis condition, as defined in the ASTM Standard, is a condition that generally does not present a threat to human health or the environment and generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. Conditions determined to be de minimis are not RECs or CRECs. No de minimis conditions were identified during this assessment.

## 10.2: Significant Data Gaps

A data gap, as defined in the ASTM Standard, is a lack of or inability to obtain information required by the ASTM Standard despite good faith efforts by the environmental professional to gather such

information. The environmental professional must then determine whether these gaps are significant. PM did not identify or encounter any instances of significant data gaps during the course of this ESA.

## 10.3: Historical Recognized Environmental Conditions (HRECs)

An HREC, as defined in the ASTM Standard, is a past release of hazardous substances or petroleum products that has occurred in connection with the subject property and has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted residential use criteria established by a regulatory authority, without subjecting the subject property to any required controls. PM has not identified any HRECs in association with the subject property.

## 10.4: Recognized Environmental Conditions (RECs)

We have performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM Practice E 1527-13 of the Commercial Property and Gasoline Dispensing Station located at 945 and 975 South Rochester Road, Rochester, Oakland County, Michigan, the subject property. Any exceptions to, or deletions from, this practice are described in Section 1.4 of this report. This assessment has revealed no evidence of recognized environmental conditions connected with the property except the following:

- The subject property, 975 South Rochester Road, operated as a gasoline dispensing station since between 1964 and 1967. Additionally, the subject property is a closed Leaking Underground Storage Tank (LUST) site with two reported releases in 1996. The releases were granted a Restricted Tier I Commercial III Closure in February 2005. Review of previous site assessment activities documents that soil and groundwater contamination remains on-site above the current Part 213 Residential and Nonresidential Risk Based Screening Levels (RBSLs). In addition, contaminant concentrations may be indicative of a vapor intrusion concern. Based on these analytical results and its closed LUST status, the subject property meets the definition of a "property," in accordance with Part 213 of P.A. 451 of the Michigan Natural Resources Environmental Protection Act (NREPA), as amended.
- Review of previous site investigations document the current UST system was last assessed in August 2008. The subject property has continued to operate as a gasoline dispensing station with the current layout since August 2008 with no site assessment activities since that time. The potential exists that a new release has occurred from the current UST system and/or fuel dispensers.
- The subject property, 975 South Rochester Road, operated as a gasoline service station from at least 1967 until 1999. Historical interior waste streams associated with the former service operations would have consisted of general hazardous substances and/or petroleum products. The previous site investigation activates did not adequately assess all areas of the former gasoline service station. A significant portion of this time period preceded major environmental regulations and current waste management and disposal procedures. The historical waste management practices associated with the former gasoline service station operations are unknown and may be a source of subsurface contamination.

- The previous site investigation activates did not adequately assess the former gasoline service station area, which likely contained in-ground hoists. In-ground hoists have an underground reservoir for hydraulic fluids, which can contain polychlorinated biphenyls (PCBs). The potential exists that a release occurred from the former hydraulic hoist system and/or underground reservoir.
- The subject property, 975 South Rochester Road, operated as a gasoline dispensing and/or service station since between 1964 and 1967. PM was unable to obtain information regarding the UST systems prior to and between 1967 and 1972. Therefore, additional fueling and/or new or waste oil USTs may have historically been present. Further, records indicate the subject buildings were connected to natural gas in 1978 and 1980, and the 975 South Rochester Road subject building likely utilized a fuel oil UST prior to natural gas connection. The potential exists for orphan USTs to be present on the property and/or for a release to have occurred.

No adjoining and/or nearby RECs have been identified.

## 10.5: Controlled Recognized Environmental Conditions (CRECs)

A CREC, as defined in the ASTM Standard, is a recognized environmental condition (REC) resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls. The following CREC(s) was identified during completion of this Phase I ESA:

• As discussed in the REC section above, the subject property, 975 South Rochester Road, is a closed LUST site with two releases reported in 1996. The release was granted a Restricted Tier I Commercial III Closure in February 2005. Review of previous site assessment activities documents that soil and groundwater contamination remains on-site above the current Part 213 Residential and Nonresidential RBSLs. In addition, contaminant concentrations may be indicative of a vapor intrusion concern. A deed restriction was recorded in 2004 that eliminates the use of groundwater for any purpose on the subject property, and any future change in the land use may necessitate further evaluation of potential risks to the public health, safety, and welfare to the environment. Based on the closed LUST status and restrictions associated with the LUST closure, PM has identified the closed LUST status as a CREC.

## 10.6: Recommendations

We have performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM Practice E 1527-13 of the Commercial Property and Gasoline Dispensing Station located at 945 and 975 South Rochester Road, Rochester, Oakland County, Michigan, the subject property. Any exceptions to, or deletions from, this practice are described in Section 1.4 of this report. This assessment has revealed no evidence of recognized environmental conditions connected with the property except as listed in Section 10.4 of this report.

PM has been engaged to complete a Baseline Environmental Assessment (BEA) and a Documentation of Due Care Compliance (DDCC) which will be provided under separate cover.

#### 11.0 NON-ASTM SCOPE CONSIDERATIONS/BUSINESS ENVIRONMENTAL RISKS

PM has included a discussion of Non-ASTM Scope Considerations based upon industry standards and lender requirements. A Business Environmental Risk is defined as a risk which can have a material environmental or environmentally-driven impact on the business associated with the current or planned use of a parcel of commercial real estate, not necessarily limited to those environmental issues required to be investigated in this practice.

Non-ASTM Item	Observations or Information
Potential Asbestos Containing Materials (ACMs)	Based on PM's limited visual observations during the site reconnaissance, suspect ACMs identified included vinyl floor tiles, drywall walls, and acoustical ceiling tiles. The materials appeared to be in good condition. It is understood that significant interior demolition is planned. Therefore, PM recommends the completion of an ACM survey to determine if asbestos is present in the building materials that will be disturbed. PM can provide a proposal to complete this scope of work at the request of the client.
Lead Based Paint (LBP)	Based on the construction of the 975 South Rochester Road subject building in at least 1967 (pre-1978 when Federal regulations banned the use of LBP), there is the potential for existing paint to be lead based. However, the painted surfaces were observed to be in generally good condition, the subject property is not a residential use, and there is no regulatory requirement to sampled suspected LBP surfaces at this time. Therefore, no further action is recommended regarding suspected LBP at the subject property. If a more definitive determination for LBP is preferred, PM can provide a scope of work to address.
Visual Mold or Significant Moisture Damage	PM performed a limited visual assessment for the presence of mold, conditions conducive to mold, and evidence of moisture in readily accessible interior areas of the subject property. PM did not note obvious visual indications of the presence of mold, conditions conducive to mold, or evidence of moisture in readily accessible interior areas of the subject property.

## 12.0 SIGNATURE(S) OF ENVIRONMENTAL PROFESSIONAL(S)

We declare that, to the best of our professional knowledge and belief, we meet the definition of *Environmental professional* as defined in §312.10 of 40 CFR 312 and we have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. We have developed and performed the all appropriate inquires in conformance with the standards and practices set forth in 40 CFR Part 312.

Kristin Gable

National Manager – Due Diligence Group

Culler Galle

Steven E. Price, CHMM Principal and Vice President

#### 13.0 REFERENCES

The following published sources were utilized during completion of this Phase I ESA:


- Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process, ASTM, ASTM Designation E 1527-13, Published November 2013.
- Bresser's Cross-Index City Directories, Bresser's in Detroit, Michigan. City: Rochester Hills. Years: 1957-2014.
- United States Geological Survey Division (U.S.G.S.) 7.5 Minute Topographic Map Rochester, Michigan Quadrangle, 1967 (photo-revised 1981).
- Custom Soil Resource Report of Oakland County, Michigan, U.S. Department of Agriculture, September 7, 2018.

In addition, PM reviewed the following previous site investigations, some of which are available from public sources.

Name of Report	Date of Report	Company that Prepared Report	
Final Assessment Report	4-8-1997	EnecoTech Midwest, Inc. (ETM)	
Groundwater Monitoring Report	7-28-1997	ETM	
Groundwater Monitoring Report	10-8-1997	ETM	
Groundwater Monitoring Report	1-22-2003	Groundwater & Environmental Services, Inc. (GES)	
Closure Report	8-27-2004	GES	
Phase I ESA	2-22-2005	AKT Peerless Environmental Services (AKT)	
Subsurface Investigation Report	3-31-2005	AKT	
Underground Storage Tank System Assessment and Closure Report	7-17-2008	Midwest Environmental Consulting Group (MECG)	

## **Figures**







## **OAKLAND COUNTY**

FIGURE 1

PROPERTY VICINITY MAP


UNITED STATES GEOLOGICAL SURVEY, 7.5 MINUTE SERIES ROCHESTER, MI QUADRANGLE, 1967. PHOTO REVISED 1981.






PROJ: COMMERCIAL PROPERTY AND GASOLINE DISPENSING STATION 945 AND 975 ROCHESTER ROAD ROCHESTER, MI

THIS IS NOT A LEGAL SURVEY	DRN BY:	CS	DATE: 9/10/2019
2,000'	CHKD BY:	JB	1" = 2,000'
IF NOT 1" ON THIS SHEET, ADJUST SCALES ACCORDINGLY.	FILE NAME: 01-1	1390-	-0-001F00R00



## Appendix A







# Photograph 1



Overall view of the 975 South Rochester Road.

# Photograph 2



Overall view of 945 South Rochester Road.



# Photograph 3



Exterior view of 945 South Rochester Road.

# Photograph 4



Exterior view of 945 South Rochester Road.



# Photograph 5



Exterior view of 975 South Rochester Road.

# Photograph 6



Exterior view of 975 South Rochester Road.



# Photograph 7



Exterior view of 975 South Rochester Road.

# Photograph 8



Exterior view of 975 South Rochester Road.



# Photograph 9



Exterior view of 975 South Rochester Road.

# Photograph 10



Interior view of 975 South Rochester Road.




# Photograph 11



Interior view of 975 South Rochester Road.

# Photograph 12



Interior view of 975 South Rochester Road.



## Photograph 13



View of the veeder root.

## Photograph 14



View of the north and east adjoining property.



# Photograph 15



View of the south adjoining property.

# Photograph 16



View of the southwest adjoining property.




# Photograph 17



View of the west adjoining property.

# Appendix B





# Phase I ESA - ASTM User Questionnaire

The ASTM Standard defines a User as "the party seeking to use Practice E 1527 to complete a environmental site assessment. A User may include, without limitation, a potential purchaser of property, a potential tenant of property, an owner of property, a lender, or a property manager. In order to qualify for one of the Landowner Liability Protections (LLPs) offered by the Sma Business Liability Relief and Brownfield's Revitalization Act of 2001 (the "Brownfield's Amendments") the User must provide the following information (if available) to the environmental professional. Failure to provide this information could results in a determination that "a appropriate inquiry" is not complete.  Please answer the following questions to the best of your knowledge and return to Phenvironmental, Inc. (PM) with the signed copy of your proposal.  1. Environmental Clean-up liens that are filed or recorded against the site (40 CFR 312.25)  Are you aware of any environmental cleanup liens against the property that are filed or recorded under federal, tribal, state or local law?  1. Activity and land use limitations that are in place on the site or that have been filed in a registry (40 CFR 312.26)  Are you aware of any Activity and Use Limitations (AULs), such as engineering controls, land use restrictions, or institutional controls that are in place at the site and/or have been filed or recorded in a registry under federal, tribal, state, or local law?  1. Specialized knowledge or experience of the person seeking to qualify for a LLP (40 CFR 312.28)  3. Specialized knowledge or experience of the person seeking to qualify for a LLP (40 CFR 312.28)  3. Specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and the processes used by this type of business?  1. If yes, what type of business are you associated with	Project Address:	945 and 975 Rochester Road in Roche	ester, Michigan	
Business Liability Relief and Brownfield's Revitalization Act of 2001 (the "Brownfield' Amendments") the User must provide the following information (if available) to the environmente professional. Failure to provide this information could results in a determination that "a appropriate inquiry" is not complete.  Please answer the following questions to the best of your knowledge and return to Plenvironmental, Inc. (PM) with the signed copy of your proposal.  1. Environmental Clean-up liens that are filed or recorded against the site (40 CFR 312.25)  Are you aware of any environmental cleanup liens against the property that are filed or recorded under federal, tribal, state or local law?  If so, please describe that type of liens:  2. Activity and land use limitations that are in place on the site or that have been filed in a registry (40 CFR 312.26)  Are you aware of any Activity and Use Limitations (AULs), such as engineering controls, land use restrictions, or institutional controls that are in place at the site and/or have been filed or recorded in a registry under federal, tribal, state, or local law?  If yes, what type of AULs are you aware of?  3. Specialized knowledge or experience of the person seeking to qualify for a LLP (40 CFR 312.28)  As the user of this ESA do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and the processes used by this type of business?  If yes, what type of business?  If yes, what type of business are you associated with?	environmental site ass	essment. A User may include, without lin	nitation, a potential purchase	er of
1. Environmental, Inc. (PM) with the signed copy of your proposal.  1. Environmental Clean-up liens that are filed or recorded against the site (40 CFR 312.25)  Are you aware of any environmental cleanup liens against the property that are filed or recorded under federal, tribal, state or local law?  If so, please describe that type of liens:  2. Activity and land use limitations that are in place on the site or that have been filed in a registry (40 CFR 312.26)  Are you aware of any Activity and Use Limitations (AULs), such as engineering controls, land use restrictions, or institutional controls that are in place at the site and/or have been filed or recorded in a registry under federal, tribal, state, or local law?  If yes, what type of AULs are you aware of?  3. Specialized knowledge or experience of the person seeking to qualify for a LLP (40 CFR 312.28)  As the user of this ESA do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and the processes used by this type of business?  If yes, what type of business are you associated with?	Business Liability Re Amendments") the <b>Use</b> professional. Failure	lief and Brownfield's Revitalization A r must provide the following information (i to provide this information could resu	ct of 2001 (the "Brownfie if available) to the environme	eld's ental
Are you aware of any environmental cleanup liens against the property that are filed or recorded under federal, tribal, state or local law?  2. Activity and land use limitations that are in place on the site or that have been filed in a registry (40 CFR 312.26)  Are you aware of any Activity and Use Limitations (AULs), such as engineering controls, land use restrictions, or institutional controls that are in place at the site and/or have been filed or recorded in a registry under federal, tribal, state, or local law?  If yes, what type of AULs are you aware of?  3. Specialized knowledge or experience of the person seeking to qualify for a LLP (40 CFR 312.28)  As the user of this ESA do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and the processes used by this type of business?  If yes, what type of business are you associated with?	Please answer the fo Environmental, Inc. (F	llowing questions to the best of your PM) with the signed copy of your propo	knowledge and return to esal.	PM
Are you aware of any environmental cleanup liens against the property that are filed or recorded under federal, tribal, state or local law?  2. Activity and land use limitations that are in place on the site or that have been filed in a registry (40 CFR 312.26)  Are you aware of any Activity and Use Limitations (AULs), such as engineering controls, land use restrictions, or institutional controls that are in place at the site and/or have been filed or recorded in a registry under federal, tribal, state, or local law?  If yes, what type of AULs are you aware of?  3. Specialized knowledge or experience of the person seeking to qualify for a LLP (40 CFR 312.28)  As the user of this ESA do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and the processes used by this type of business?  If yes, what type of business are you associated with?	1. Environmental Clear	n-up liens that are filed or recorded agains	t the site (40 CFR 312.25)	
2. Activity and land use limitations that are in place on the site or that have been filed in a registry (40 CFR 312.26)  Are you aware of any Activity and Use Limitations (AULs), such as engineering controls, land use restrictions, or institutional controls that are in place at the site and/or have been filed or recorded in a registry under federal, tribal, state, or local law?  If yes, what type of AULs are you aware of?  3. Specialized knowledge or experience of the person seeking to qualify for a LLP (40 CFR 312.28)  As the user of this ESA do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and the processes used by this type of business?  If yes, what type of business are you associated with?	Are you aware of any er	nvironmental cleanup liens against the proper	tv that are filed or	6
Are you aware of any Activity and Use Limitations (AULs), such as engineering controls, land use restrictions, or institutional controls that are in place at the site and/or have been filled or recorded in a registry under federal, tribal, state, or local law?  If yes, what type of AULs are you aware of?  3. Specialized knowledge or experience of the person seeking to qualify for a LLP (40 CFR 312.28)  As the user of this ESA do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and the processes used by this type of business?  If yes, what type of business are you associated with?	If so, please describe the	at type of liens:		
Are you aware of any Activity and Use Limitations (AULs), such as engineering controls, land use restrictions, or institutional controls that are in place at the site and/or have been filed or recorded in a registry under federal, tribal, state, or local law?  If yes, what type of AULs are you aware of?  3. Specialized knowledge or experience of the person seeking to qualify for a LLP (40 CFR 312.28)  As the user of this ESA do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and the processes used by this type of business?  If yes, what type of business are you associated with?				
land use restrictions, or institutional controls that are in place at the site and/or have been filed or recorded in a registry under federal, tribal, state, or local law?  If yes, what type of AULs are you aware of?  3. Specialized knowledge or experience of the person seeking to qualify for a LLP (40 CFR 312.28)  As the user of this ESA do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and the processes used by this type of business?  If yes, what type of business are you associated with?	2. Activity and land use (40 CFR 312.26)	limitations that are in place on the site or t	hat have been filed in a regist	lry
3. Specialized knowledge or experience of the person seeking to qualify for a LLP (40 CFR 312.28)  As the user of this ESA do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and the processes used by this type of business?  If yes, what type of business are you associated with?	land use restrictions, or	institutional controls that are in place at the	site and/or have Yes No	0
As the user of this ESA do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and the processes used by this type of business?  If yes, what type of business are you associated with?	If yes, what type of AULs	are you aware of?		
As the user of this ESA do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and the processes used by this type of business?  If yes, what type of business are you associated with?		gus stupin		·,
As the user of this ESA do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and the processes used by this type of business?  If yes, what type of business are you associated with?				
to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and the processes used by this type of business?  If yes, what type of business are you associated with?	3. Specialized knowledg	je or experience of the person seeking to q	ualify for a LLP (40 CFR 312.2	8)
	to the property or nearby business as the current o that you would have spec	properties? For example, are you involved in or former occupants of the property or an adio	the same line of	
What types of chemicals are used in your business?	If yes, what type of busin	ess are you associated with?		
	What types of chemicals	are used in your business?		
		<del></del>		


# Phase I ESA - ASTM User Questionnaire

Project Address:	945 and 975 Rochester Road in Rochester, Michigan				
4. Relationship to the contaminated (40 CFR	purchase price to the fair 312.29)	market value	of the property	if it w	ere not
Does the purchase pric value of the property?	e being paid for this property i	reasonably refle	ct the fair market	Yes	) <sub>No</sub>
If you conclude that the purchase price is beca property?	ere is a difference, have you use contamination is known o	u considered wor believed to b	hether the lower be present at the	Yes	No
5. Commonly known o	r reasonably ascertainable ir	nformation abo	ut the property (4	0 CFR	312.30)
Are you aware of comm property that would help	nonly known or reasonably aso the environmental profession d releases? For example as a	certainable infor al to identify cor	mation about the		· · · · · · · · · · · · · · · · · · ·
a. Do you know of the pa	ast uses of the property?			Yes	No
If yes, please list what p	ast uses are you aware of?	Gus	Shitin		
		<u> </u>	station ventla	,	
b. Do you know of spe property?	cific chemicals that are prese	ent or once wer	e present at the	Yes	No
If yes, please list what cl	nemicals you are aware of?		, A		
c. Do you know of spil property?	ls or other chemical releases	that have take	en place on the	Yes	No
d. Do you know of any er	Yes	No			
If yes, do you have copie	s of any of the reports docume	enting the work?		Yes	CNO

If you have any documentation of the previous environmental clean-up please provide copies to PM when you return this questionnaire.

# Phase I ESA - ASTM User Questionnaire

<del></del>	
Project Address:	945 and 975 Rochester Road in Rochester, Michigan
	obviousness of the presence of likely presence of contamination at the to detect the contamination by appropriate investigation (40CFR 312.31)
	passed on your knowledge and experience related to the property indicators that point to the presence or likely presence of Yes perty?
If yes, please comment of	on what those indicators are (i.e. lower purchase price, areas of staining,
poor housekeeping, etc.	
: :	
:,	
User Name:	Rochesta Aven Partners, CCc
Company Name proper is being purchased under:	
Street Address:	251 E. MERAN # 205
City, State, Zip code:	BIRMINGHAM ME 48009
User Phone Number:	248-203-9090
Signature of the User:	Du mand
Date Questionnaire was completed on:	8/13/19





**NRCS** 

Natural Resources Conservation Service A product of the National Cooperative Soil Survey, a joint effort of the United States Department of Agriculture and other Federal agencies, State agencies including the Agricultural Experiment Stations, and local participants

# Custom Soil Resource Report for Oakland County, Michigan



# **Preface**

Soil surveys contain information that affects land use planning in survey areas. They highlight soil limitations that affect various land uses and provide information about the properties of the soils in the survey areas. Soil surveys are designed for many different users, including farmers, ranchers, foresters, agronomists, urban planners, community officials, engineers, developers, builders, and home buyers. Also, conservationists, teachers, students, and specialists in recreation, waste disposal, and pollution control can use the surveys to help them understand, protect, or enhance the environment.

Various land use regulations of Federal, State, and local governments may impose special restrictions on land use or land treatment. Soil surveys identify soil properties that are used in making various land use or land treatment decisions. The information is intended to help the land users identify and reduce the effects of soil limitations on various land uses. The landowner or user is responsible for identifying and complying with existing laws and regulations.

Although soil survey information can be used for general farm, local, and wider area planning, onsite investigation is needed to supplement this information in some cases. Examples include soil quality assessments (http://www.nrcs.usda.gov/wps/portal/nrcs/main/soils/health/) and certain conservation and engineering applications. For more detailed information, contact your local USDA Service Center (https://offices.sc.egov.usda.gov/locator/app?agency=nrcs) or your NRCS State Soil Scientist (http://www.nrcs.usda.gov/wps/portal/nrcs/detail/soils/contactus/?cid=nrcs142p2 053951).

Great differences in soil properties can occur within short distances. Some soils are seasonally wet or subject to flooding. Some are too unstable to be used as a foundation for buildings or roads. Clayey or wet soils are poorly suited to use as septic tank absorption fields. A high water table makes a soil poorly suited to basements or underground installations.

The National Cooperative Soil Survey is a joint effort of the United States Department of Agriculture and other Federal agencies, State agencies including the Agricultural Experiment Stations, and local agencies. The Natural Resources Conservation Service (NRCS) has leadership for the Federal part of the National Cooperative Soil Survey.

Information about soils is updated periodically. Updated information is available through the NRCS Web Soil Survey, the site for official soil survey information.

The U.S. Department of Agriculture (USDA) prohibits discrimination in all its programs and activities on the basis of race, color, national origin, age, disability, and where applicable, sex, marital status, familial status, parental status, religion, sexual orientation, genetic information, political beliefs, reprisal, or because all or a part of an individual's income is derived from any public assistance program. (Not all prohibited bases apply to all programs.) Persons with disabilities who require

alternative means for communication of program information (Braille, large print, audiotape, etc.) should contact USDA's TARGET Center at (202) 720-2600 (voice and TDD). To file a complaint of discrimination, write to USDA, Director, Office of Civil Rights, 1400 Independence Avenue, S.W., Washington, D.C. 20250-9410 or call (800) 795-3272 (voice) or (202) 720-6382 (TDD). USDA is an equal opportunity provider and employer.

# **Contents**

Preface	2
How Soil Surveys Are Made	5
Soil Map	
Soil Map	
Legend	
Map Unit Legend	
Map Unit Descriptions	
Oakland County, Michigan	
59—Urban land	13
Soil Information for All Uses	14
Soil Reports	14
Soil Qualities and Features	
Soil Features	14
References	17

# **How Soil Surveys Are Made**

Soil surveys are made to provide information about the soils and miscellaneous areas in a specific area. They include a description of the soils and miscellaneous areas and their location on the landscape and tables that show soil properties and limitations affecting various uses. Soil scientists observed the steepness, length, and shape of the slopes; the general pattern of drainage; the kinds of crops and native plants; and the kinds of bedrock. They observed and described many soil profiles. A soil profile is the sequence of natural layers, or horizons, in a soil. The profile extends from the surface down into the unconsolidated material in which the soil formed or from the surface down to bedrock. The unconsolidated material is devoid of roots and other living organisms and has not been changed by other biological activity.

Currently, soils are mapped according to the boundaries of major land resource areas (MLRAs). MLRAs are geographically associated land resource units that share common characteristics related to physiography, geology, climate, water resources, soils, biological resources, and land uses (USDA, 2006). Soil survey areas typically consist of parts of one or more MLRA.

The soils and miscellaneous areas in a survey area occur in an orderly pattern that is related to the geology, landforms, relief, climate, and natural vegetation of the area. Each kind of soil and miscellaneous area is associated with a particular kind of landform or with a segment of the landform. By observing the soils and miscellaneous areas in the survey area and relating their position to specific segments of the landform, a soil scientist develops a concept, or model, of how they were formed. Thus, during mapping, this model enables the soil scientist to predict with a considerable degree of accuracy the kind of soil or miscellaneous area at a specific location on the landscape.

Commonly, individual soils on the landscape merge into one another as their characteristics gradually change. To construct an accurate soil map, however, soil scientists must determine the boundaries between the soils. They can observe only a limited number of soil profiles. Nevertheless, these observations, supplemented by an understanding of the soil-vegetation-landscape relationship, are sufficient to verify predictions of the kinds of soil in an area and to determine the boundaries.

Soil scientists recorded the characteristics of the soil profiles that they studied. They noted soil color, texture, size and shape of soil aggregates, kind and amount of rock fragments, distribution of plant roots, reaction, and other features that enable them to identify soils. After describing the soils in the survey area and determining their properties, the soil scientists assigned the soils to taxonomic classes (units). Taxonomic classes are concepts. Each taxonomic class has a set of soil characteristics with precisely defined limits. The classes are used as a basis for comparison to classify soils systematically. Soil taxonomy, the system of taxonomic classification used in the United States, is based mainly on the kind and character of soil properties and the arrangement of horizons within the profile. After the soil

## Custom Soil Resource Report

scientists classified and named the soils in the survey area, they compared the individual soils with similar soils in the same taxonomic class in other areas so that they could confirm data and assemble additional data based on experience and research.

The objective of soil mapping is not to delineate pure map unit components; the objective is to separate the landscape into landforms or landform segments that have similar use and management requirements. Each map unit is defined by a unique combination of soil components and/or miscellaneous areas in predictable proportions. Some components may be highly contrasting to the other components of the map unit. The presence of minor components in a map unit in no way diminishes the usefulness or accuracy of the data. The delineation of such landforms and landform segments on the map provides sufficient information for the development of resource plans. If intensive use of small areas is planned, onsite investigation is needed to define and locate the soils and miscellaneous areas.

Soil scientists make many field observations in the process of producing a soil map. The frequency of observation is dependent upon several factors, including scale of mapping, intensity of mapping, design of map units, complexity of the landscape, and experience of the soil scientist. Observations are made to test and refine the soil-landscape model and predictions and to verify the classification of the soils at specific locations. Once the soil-landscape model is refined, a significantly smaller number of measurements of individual soil properties are made and recorded. These measurements may include field measurements, such as those for color, depth to bedrock, and texture, and laboratory measurements, such as those for content of sand, silt, clay, salt, and other components. Properties of each soil typically vary from one point to another across the landscape.

Observations for map unit components are aggregated to develop ranges of characteristics for the components. The aggregated values are presented. Direct measurements do not exist for every property presented for every map unit component. Values for some properties are estimated from combinations of other properties.

While a soil survey is in progress, samples of some of the soils in the area generally are collected for laboratory analyses and for engineering tests. Soil scientists interpret the data from these analyses and tests as well as the field-observed characteristics and the soil properties to determine the expected behavior of the soils under different uses. Interpretations for all of the soils are field tested through observation of the soils in different uses and under different levels of management. Some interpretations are modified to fit local conditions, and some new interpretations are developed to meet local needs. Data are assembled from other sources, such as research information, production records, and field experience of specialists. For example, data on crop yields under defined levels of management are assembled from farm records and from field or plot experiments on the same kinds of soil.

Predictions about soil behavior are based not only on soil properties but also on such variables as climate and biological activity. Soil conditions are predictable over long periods of time, but they are not predictable from year to year. For example, soil scientists can predict with a fairly high degree of accuracy that a given soil will have a high water table within certain depths in most years, but they cannot predict that a high water table will always be at a specific level in the soil on a specific date.

After soil scientists located and identified the significant natural bodies of soil in the survey area, they drew the boundaries of these bodies on aerial photographs and

## Custom Soil Resource Report

identified each as a specific map unit. Aerial photographs show trees, buildings, fields, roads, and rivers, all of which help in locating boundaries accurately.

# Soil Map

The soil map section includes the soil map for the defined area of interest, a list of soil map units on the map and extent of each map unit, and cartographic symbols displayed on the map. Also presented are various metadata about data used to produce the map, and a description of each soil map unit.



#### MAP LEGEND

#### Area of Interest (AOI)

Area of Interest (AOI)

#### Soils

Soil Map Unit Polygons



Soil Map Unit Lines



Soil Map Unit Points

#### **Special Point Features**

(o)

Blowout

 $\boxtimes$ 

Borrow Pit

Ж

Clay Spot

 $\wedge$ 

Closed Depression

Š

Gravel Pit

...

**Gravelly Spot** 

0

Landfill Lava Flow

٨.

Marsh or swamp

2

Mine or Quarry

欠

Miscellaneous Water

0

Perennial Water
Rock Outcrop

+

Saline Spot

. .

Sandy Spot

Severely Eroded Spot

Sinkhole

30

Slide or Slip

Ø

Sodic Spot

## \_\_\_\_



Spoil Area Stony Spot



Very Stony Spot



Wet Spot Other



Special Line Features

## Water Features

\_

Streams and Canals

## Transportation

ransp

Rails

~

Interstate Highways

US Routes



Major Roads



Local Roads

## Background

Marie Control

Aerial Photography

## MAP INFORMATION

The soil surveys that comprise your AOI were mapped at 1:15.800.

Warning: Soil Map may not be valid at this scale.

Enlargement of maps beyond the scale of mapping can cause misunderstanding of the detail of mapping and accuracy of soil line placement. The maps do not show the small areas of contrasting soils that could have been shown at a more detailed scale.

Please rely on the bar scale on each map sheet for map measurements.

Source of Map: Natural Resources Conservation Service Web Soil Survey URL:

Coordinate System: Web Mercator (EPSG:3857)

Maps from the Web Soil Survey are based on the Web Mercator projection, which preserves direction and shape but distorts distance and area. A projection that preserves area, such as the Albers equal-area conic projection, should be used if more accurate calculations of distance or area are required.

This product is generated from the USDA-NRCS certified data as of the version date(s) listed below.

Soil Survey Area: Oakland County, Michigan Survey Area Data: Version 17, Sep 7, 2018

Soil map units are labeled (as space allows) for map scales 1:50.000 or larger.

Date(s) aerial images were photographed: Jun 27, 2014—Nov 5, 2016

The orthophoto or other base map on which the soil lines were compiled and digitized probably differs from the background imagery displayed on these maps. As a result, some minor shifting of map unit boundaries may be evident.

# Map Unit Legend

Map Unit Symbol	Map Unit Name	Acres in AOI	Percent of AOI	
59	Urban land	1.0	100.0%	
Totals for Area of Interest		1.0	100.0%	

# **Map Unit Descriptions**

The map units delineated on the detailed soil maps in a soil survey represent the soils or miscellaneous areas in the survey area. The map unit descriptions, along with the maps, can be used to determine the composition and properties of a unit.

A map unit delineation on a soil map represents an area dominated by one or more major kinds of soil or miscellaneous areas. A map unit is identified and named according to the taxonomic classification of the dominant soils. Within a taxonomic class there are precisely defined limits for the properties of the soils. On the landscape, however, the soils are natural phenomena, and they have the characteristic variability of all natural phenomena. Thus, the range of some observed properties may extend beyond the limits defined for a taxonomic class. Areas of soils of a single taxonomic class rarely, if ever, can be mapped without including areas of other taxonomic classes. Consequently, every map unit is made up of the soils or miscellaneous areas for which it is named and some minor components that belong to taxonomic classes other than those of the major soils.

Most minor soils have properties similar to those of the dominant soil or soils in the map unit, and thus they do not affect use and management. These are called noncontrasting, or similar, components. They may or may not be mentioned in a particular map unit description. Other minor components, however, have properties and behavioral characteristics divergent enough to affect use or to require different management. These are called contrasting, or dissimilar, components. They generally are in small areas and could not be mapped separately because of the scale used. Some small areas of strongly contrasting soils or miscellaneous areas are identified by a special symbol on the maps. If included in the database for a given area, the contrasting minor components are identified in the map unit descriptions along with some characteristics of each. A few areas of minor components may not have been observed, and consequently they are not mentioned in the descriptions, especially where the pattern was so complex that it was impractical to make enough observations to identify all the soils and miscellaneous areas on the landscape.

The presence of minor components in a map unit in no way diminishes the usefulness or accuracy of the data. The objective of mapping is not to delineate pure taxonomic classes but rather to separate the landscape into landforms or landform segments that have similar use and management requirements. The delineation of such segments on the map provides sufficient information for the development of resource plans. If intensive use of small areas is planned, however, onsite investigation is needed to define and locate the soils and miscellaneous areas.

## Custom Soil Resource Report

An identifying symbol precedes the map unit name in the map unit descriptions. Each description includes general facts about the unit and gives important soil properties and qualities.

Soils that have profiles that are almost alike make up a *soil series*. Except for differences in texture of the surface layer, all the soils of a series have major horizons that are similar in composition, thickness, and arrangement.

Soils of one series can differ in texture of the surface layer, slope, stoniness, salinity, degree of erosion, and other characteristics that affect their use. On the basis of such differences, a soil series is divided into *soil phases*. Most of the areas shown on the detailed soil maps are phases of soil series. The name of a soil phase commonly indicates a feature that affects use or management. For example, Alpha silt loam, 0 to 2 percent slopes, is a phase of the Alpha series.

Some map units are made up of two or more major soils or miscellaneous areas. These map units are complexes, associations, or undifferentiated groups.

A *complex* consists of two or more soils or miscellaneous areas in such an intricate pattern or in such small areas that they cannot be shown separately on the maps. The pattern and proportion of the soils or miscellaneous areas are somewhat similar in all areas. Alpha-Beta complex, 0 to 6 percent slopes, is an example.

An *association* is made up of two or more geographically associated soils or miscellaneous areas that are shown as one unit on the maps. Because of present or anticipated uses of the map units in the survey area, it was not considered practical or necessary to map the soils or miscellaneous areas separately. The pattern and relative proportion of the soils or miscellaneous areas are somewhat similar. Alpha-Beta association, 0 to 2 percent slopes, is an example.

An *undifferentiated group* is made up of two or more soils or miscellaneous areas that could be mapped individually but are mapped as one unit because similar interpretations can be made for use and management. The pattern and proportion of the soils or miscellaneous areas in a mapped area are not uniform. An area can be made up of only one of the major soils or miscellaneous areas, or it can be made up of all of them. Alpha and Beta soils, 0 to 2 percent slopes, is an example.

Some surveys include *miscellaneous areas*. Such areas have little or no soil material and support little or no vegetation. Rock outcrop is an example.

# Oakland County, Michigan

## 59—Urban land

## **Map Unit Setting**

National map unit symbol: 6bjh Elevation: 660 to 980 feet

Mean annual precipitation: 35 to 40 inches Mean annual air temperature: 50 to 55 degrees F

Frost-free period: 155 to 180 days

Farmland classification: Not prime farmland

## **Map Unit Composition**

Urban land: 100 percent

Estimates are based on observations, descriptions, and transects of the mapunit.

# Soil Information for All Uses

## Soil Reports

The Soil Reports section includes various formatted tabular and narrative reports (tables) containing data for each selected soil map unit and each component of each unit. No aggregation of data has occurred as is done in reports in the Soil Properties and Qualities and Suitabilities and Limitations sections.

The reports contain soil interpretive information as well as basic soil properties and qualities. A description of each report (table) is included.

## Soil Qualities and Features

This folder contains tabular reports that present various soil qualities and features. The reports (tables) include all selected map units and components for each map unit. Soil qualities are behavior and performance attributes that are not directly measured, but are inferred from observations of dynamic conditions and from soil properties. Example soil qualities include natural drainage, and frost action. Soil features are attributes that are not directly part of the soil. Example soil features include slope and depth to restrictive layer. These features can greatly impact the use and management of the soil.

## **Soil Features**

This table gives estimates of various soil features. The estimates are used in land use planning that involves engineering considerations.

A *restrictive layer* is a nearly continuous layer that has one or more physical, chemical, or thermal properties that significantly impede the movement of water and air through the soil or that restrict roots or otherwise provide an unfavorable root environment. Examples are bedrock, cemented layers, dense layers, and frozen layers. The table indicates the hardness and thickness of the restrictive layer, both of which significantly affect the ease of excavation. *Depth to top* is the vertical distance from the soil surface to the upper boundary of the restrictive layer.

Subsidence is the settlement of organic soils or of saturated mineral soils of very low density. Subsidence generally results from either desiccation and shrinkage, or oxidation of organic material, or both, following drainage. Subsidence takes place gradually, usually over a period of several years. The table shows the expected

## Custom Soil Resource Report

initial subsidence, which usually is a result of drainage, and total subsidence, which results from a combination of factors.

Potential for frost action is the likelihood of upward or lateral expansion of the soil caused by the formation of segregated ice lenses (frost heave) and the subsequent collapse of the soil and loss of strength on thawing. Frost action occurs when moisture moves into the freezing zone of the soil. Temperature, texture, density, saturated hydraulic conductivity (Ksat), content of organic matter, and depth to the water table are the most important factors considered in evaluating the potential for frost action. It is assumed that the soil is not insulated by vegetation or snow and is not artificially drained. Silty and highly structured, clayey soils that have a high water table in winter are the most susceptible to frost action. Well drained, very gravelly, or very sandy soils are the least susceptible. Frost heave and low soil strength during thawing cause damage to pavements and other rigid structures.

Risk of corrosion pertains to potential soil-induced electrochemical or chemical action that corrodes or weakens uncoated steel or concrete. The rate of corrosion of uncoated steel is related to such factors as soil moisture, particle-size distribution, acidity, and electrical conductivity of the soil. The rate of corrosion of concrete is based mainly on the sulfate and sodium content, texture, moisture content, and acidity of the soil. Special site examination and design may be needed if the combination of factors results in a severe hazard of corrosion. The steel or concrete in installations that intersect soil boundaries or soil layers is more susceptible to corrosion than the steel or concrete in installations that are entirely within one kind of soil or within one soil layer.

For uncoated steel, the risk of corrosion, expressed as *low*, *moderate*, or *high*, is based on soil drainage class, total acidity, electrical resistivity near field capacity, and electrical conductivity of the saturation extract.

For concrete, the risk of corrosion also is expressed as *low*, *moderate*, or *high*. It is based on soil texture, acidity, and amount of sulfates in the saturation extract.

## Custom Soil Resource Report

Soil Features–Oakland County, Michigan									
Map symbol and	Restrictive Layer			Subsidence		Potential for frost	Risk of corrosion		
soil name	Kind	Depth to top	Thickness	Hardness	Initial	Total	action	Uncoated steel	Concrete
		Low-RV- High	Range		Low- High	Low- High			
		In	In		In	In			
59—Urban land									
Urban land		_	_		_	_			

# References

American Association of State Highway and Transportation Officials (AASHTO). 2004. Standard specifications for transportation materials and methods of sampling and testing. 24th edition.

American Society for Testing and Materials (ASTM). 2005. Standard classification of soils for engineering purposes. ASTM Standard D2487-00.

Cowardin, L.M., V. Carter, F.C. Golet, and E.T. LaRoe. 1979. Classification of wetlands and deep-water habitats of the United States. U.S. Fish and Wildlife Service FWS/OBS-79/31.

Federal Register. July 13, 1994. Changes in hydric soils of the United States.

Federal Register. September 18, 2002. Hydric soils of the United States.

Hurt, G.W., and L.M. Vasilas, editors. Version 6.0, 2006. Field indicators of hydric soils in the United States.

National Research Council. 1995. Wetlands: Characteristics and boundaries.

Soil Survey Division Staff. 1993. Soil survey manual. Soil Conservation Service. U.S. Department of Agriculture Handbook 18. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2 054262

Soil Survey Staff. 1999. Soil taxonomy: A basic system of soil classification for making and interpreting soil surveys. 2nd edition. Natural Resources Conservation Service, U.S. Department of Agriculture Handbook 436. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2 053577

Soil Survey Staff. 2010. Keys to soil taxonomy. 11th edition. U.S. Department of Agriculture, Natural Resources Conservation Service. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2 053580

Tiner, R.W., Jr. 1985. Wetlands of Delaware. U.S. Fish and Wildlife Service and Delaware Department of Natural Resources and Environmental Control, Wetlands Section.

United States Army Corps of Engineers, Environmental Laboratory. 1987. Corps of Engineers wetlands delineation manual. Waterways Experiment Station Technical Report Y-87-1.

United States Department of Agriculture, Natural Resources Conservation Service. National forestry manual. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/soils/home/?cid=nrcs142p2 053374


United States Department of Agriculture, Natural Resources Conservation Service. National range and pasture handbook. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/landuse/rangepasture/?cid=stelprdb1043084

## Custom Soil Resource Report

United States Department of Agriculture, Natural Resources Conservation Service. National soil survey handbook, title 430-VI. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/soils/scientists/?cid=nrcs142p2\_054242

United States Department of Agriculture, Natural Resources Conservation Service. 2006. Land resource regions and major land resource areas of the United States, the Caribbean, and the Pacific Basin. U.S. Department of Agriculture Handbook 296. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2\_053624

United States Department of Agriculture, Soil Conservation Service. 1961. Land capability classification. U.S. Department of Agriculture Handbook 210. http://www.nrcs.usda.gov/Internet/FSE\_DOCUMENTS/nrcs142p2\_052290.pdf








Location: 945 and 975 Rochester Road, Rochester Hills, Michigan

PM Project No. 01-11390-0-0001

Aerial Year: 1940

**Source: Oakland County** 








PM Project No. 01-11390-0-0001

Aerial Year: 1957

**Source: Wayne State University** 








PM Project No. 01-11390-0-0001

Aerial Year: 1967

**Source: Wayne State University** 








PM Project No. 01-11390-0-0001

Aerial Year: 1980








PM Project No. 01-11390-0-0001

Aerial Year: 1997







PM Project No. 01-11390-0-0001

Aerial Year: 2006









PM Project No. 01-11390-0-0001

Aerial Year: 2017







#### **945 S ROCHESTER RD** ROCHESTER HILLS, MI 48307-2762 (Property Address)

Parcel Number: 70-15-14-351-011



Item 1 of 1

f 1 1 Image / 0 Sketches

#### Property Owner: ALL-INVEST INC

#### **Summary Information**

- > Commercial/Industrial Building Summary
  - Yr Built: N/A # of Buildings: 1
  - Total Sq.Ft.: 5,409
- > Property Tax information found
- > 8 Invoices Found, Amount Due: 52.50
- > Assessed Value: \$253,080 | Taxable Value: \$226,270
- > 10 Building Department records found

#### **Important Message**

The City of Rochester Hills does not guarantee that information on this web site is accurate, timely or complete, although the City strives to meet those criteria. Please contact the following departments if you believe there are errors in the data; PropertyTaxes, Special Assessments, and Miscellaneous Receivables - Treasury Department 248-656-4675, Assessments - Assessing Department 248-656-4605, Permits - Building Department 248-656-4615. Any errors or omissions will not negate the taxes or special assessments that are due and payable. The official records are at the Rochester Hills City Hall for current year tax collections only. Payments made for delinquent taxes are not reflected on this website. To determine if a payment has been made after the current collection period, contact the Oakland County Treasurer at 248-858-0611 or click <a href="here">here</a> for the Access Oakland web site.

**All Special Assessment/Miscellaneous Receivables payments must be on separate checks.** Please call 248-656-4688 to check for water and/or sewer assessments. Please call GFL at 844-464-3587 to check for outstanding **Solid Waste account balances**. Please view the Winter tax bill for any tax assigned **road paving installments**. If you need to inquire about **false alarms charges** that may occur during the current month that have not yet been reported to or billed by the City Treasurer, you may contact the Sheriff's office at 248-537-3530. You may inquire about **weed control charges** that may occur during the current month that have not yet been reported to or billed by the City Treasurer, by contacting whiteb@rochesterhills.org. Our weed cutting season runs May 1 - Nov 1.

#### Owner and Taxpayer Information

Owner	ALL-INVEST INC	Taxpayer	SEE OWNER INFORMATION
	2383 LOCH CREEK WAY		
	BLOOMFIELD, MI 48304-3809		

#### General Information for Tax Year 2019

Property Class	201 COMMERCIAL	Unit	70 CITY OF ROCHESTER HILLS
School District	ROCHESTER 63260	Assessed Value	\$253,080
MAP#	No Data to Display	Taxable Value	\$226,270
USER NUM IDX	0	State Equalized Value	\$253,080
USER ALPHA 1		Date of Last Name Change	03/03/2004
USER ALPHA 3	0	Notes	Not Available
Historical District	No	Census Block Group	No Data to Display
USER ALPHA 2	No Data to Display	Exemption	No Data to Display

#### **Principal Residence Exemption Information**

No Data to Display

Principal Residence Exemption	June 1st	Final
2019	0.0000 %	0.0000 %

#### **Previous Year Information**

Homestead Date

Year	MBOR Assessed	Final SEV	Final Taxable
2018	\$239,990	\$239,990	\$220,970
2017	\$229,730	\$229,730	\$216,430
2016	\$222,790	\$222,790	\$214,500
2015	\$217,760	\$217,760	\$213,860
2014	\$210,500	\$210,500	\$210,500
2013	\$211,250	\$211,250	\$211,250
2012	\$219,180	\$219,180	\$219,180

Year	MBOR Assessed	Final SEV	Final Taxable
2011	\$247,580	\$247,580	\$247,580
2010	\$287,910	\$287,910	\$280,060
2009	\$309,310	\$309,310	\$280,910
2008	\$314,710	\$314,710	\$269,080
2007	\$290,720	\$290,720	\$263,040
2006	\$290,580	\$290,580	\$253,660
2005	\$281,040	\$281,040	\$245,560

#### **Land Information**

Zoning Code	BI	Total Acres	0.505
Land Value	\$137,500	Land Improvements	Not Available
Renaissance Zone	No	Renaissance Zone Expiration Date	No Data to Display
ECF Neighborhood	00006.COMM/ROCHRD	Mortgage Code	No Data to Display
Lot Dimensions/Comments	No Data to Display	Neighborhood Enterprise Zone	No

 Lot(s)
 Frontage
 Depth

 No lots found.
 Total Frontage: 0.00 ft
 Average Depth: 0.00 ft

#### **Legal Description**

T3N, R11E, SEC 14 PART OF SW 1/4 BEG AT PT DIST S 89-51-30 E 33 FT & N 195 FT FROM SW 1/4 COR, TH N 135 FT, TH E 162.50 FT, TH S 135 FT, TH W 162.50 FT TO BEG 0.50 AB203B

#### Land Division Act Information

Date of Last Split/Combine	No Data to Display	Number of Splits Left	Not Available
Date Form Filed	No Data to Display	Unallocated Div.s of Parent	Not Available
Date Created	No Data to Display	Unallocated Div.s Transferred	Not Available
Acreage of Parent	0.00	Rights Were Transferred	Yes
Split Number	0	Courtesy Split	No
Parent Parcel	No Data to Display		

#### Sale History

Sale Date	Sale Price	Instrument	Grantor	Grantee	Terms of Sale	Liber/Page
01/02/1997	\$525,000.00	WD	PERRAUT,CHARLES	#ALL INVEST INC	22A - VAC/NEW BLDG	17155:321
06/01/1995	\$128,333.00	WD	PERRAUT,GEORGE	PERRAUT,ELLIS,E	10 - SUBSEQ REMODEL	15499:298
11/21/1990	\$315,000.00	WD	FIRST OF AMERICA BK SE	PERRAUT, GEORGE, CHARLESETTA	01 - \$1.00 DEED	11652/395

#### Building Information - 5409 sq ft Office Buildings (Commercial)

5,409 sq ft	Estimated TCV	Not Available
Office Buildings	Class	С
1	Average Story Height	10 ft
0 ft	Identical Units	1
Not Available	Year Remodeled	Not Available
100%	Heat	Package Heating & Cooling
74%	Functional Percent Good	100%
100%	Effective Age	20 yrs
	Office Buildings 1 0 ft Not Available 100% 74%	Office Buildings Class Average Story Height Oft Identical Units Not Available Year Remodeled 100% Heat 74% Functional Percent Good

<sup>\*\*</sup>Disclaimer: BS&A Software provides BS&A Online as a way for municipalities to display information online and is not responsible for the content or accuracy of the data herein. This data is provided for reference only and WITHOUT WARRANTY of any kind, expressed or inferred. Please contact your local municipality if you believe there are errors in the data.

Copyright © 2019 BS&A Software, Inc.

#### 975 S ROCHESTER RD ROCHESTER HILLS, MI 48307-2743 (Property Address)

Parcel Number: 70-15-14-351-012



Item 1 of 1

1 Image / 0 Sketches

#### Property Owner: ROCHESTER AVON PARTNERS, LLC

#### **Summary Information**

- > Commercial/Industrial Building Summary
  - Yr Built: 1970 - # of Buildings: 1
  - Total Sq.Ft.: 1,407
- > Property Tax information found
- > 11 Invoices Found, Amount Due: 0.00
- > Assessed Value: \$191,730 | Taxable Value: \$181,680
- > 47 Building Department records found

#### **Important Message**

The City of Rochester Hills does not guarantee that information on this web site is accurate, timely or complete, although the City strives to meet those criteria. Please contact the following departments if you believe there are errors in the data; PropertyTaxes, Special Assessments, and Miscellaneous Receivables - Treasury Department 248-656-4675, Assessments - Assessing Department 248-656-4605, Permits - Building Department 248-656-4615. Any errors or omissions will not negate the taxes or special assessments that are due and payable. The official records are at the Rochester Hills City Hall for current year tax collections only. Payments made for delinquent taxes are not reflected on this website. To determine if a payment has been made after the current collection period, contact the Oakland County Treasurer at 248-858-0611 or click here for the Access Oakland web site.

All Special Assessment/Miscellaneous Receivables payments must be on separate checks. Please call 248-656-4688 to check for water and/or sewer assessments. Please call GFL at 844-464-3587 to check for outstanding Solid Waste account balances. Please view the Winter tax bill for any tax assigned road paving installments. If you need to inquire about false alarms charges that may occur during the current month that have not yet been reported to or billed by the City Treasurer, you may contact the Sheriff's office at 248-537-3530. You may inquire about weed control charges that may occur during the current month that have not yet been reported to or billed by the City Treasurer, by contacting whiteb@rochesterhills.org. Our weed cutting season runs May 1 - Nov 1.

#### Owner and Taxpayer Information

ROCHESTER AVON PARTNERS, Taxpayer SEE OWNER INFORMATION Owner

975 S ROCHESTER RD ROCHESTER HILLS, MI 48307-

2743

#### General Information for Tax Year 2019

Property Class	201 COMMERCIAL	Unit	70 CITY OF ROCHESTER HILLS
School District	ROCHESTER 63260	Assessed Value	\$191,730
MAP#	No Data to Display	Taxable Value	\$181,680
USER NUM IDX	0	State Equalized Value	\$191,730
USER ALPHA 1		Date of Last Name Change	08/08/2019
USER ALPHA 3	0	Notes	Not Available
Historical District	No	Census Block Group	No Data to Display
USER ALPHA 2		Exemption	No Data to Display

#### **Principal Residence Exemption Information**

**Homestead Date** No Data to Display

Principal Residence Exemption	June 1st	Final
2019	0.0000 %	0.0000 %

#### **Previous Year Information**

Year	MBOR Assessed	Final SEV	Final Taxable
2018	\$187,590	\$187,590	\$177,430
2017	\$182,130	\$182,130	\$173,790
2016	\$176,020	\$176,020	\$172,240
2015	\$171,730	\$171,730	\$171,730
2014	\$169,840	\$169,840	\$169,840
2013	\$175,600	\$175,600	\$175,600

Year	MBOR Assessed	Final SEV	Final Taxable
2012	\$187,190	\$187,190	\$187,190
2011	\$204,400	\$204,400	\$204,400
2010	\$229,080	\$229,080	\$229,080
2009	\$252,950	\$252,950	\$252,950
2008	\$253,790	\$253,790	\$253,790
2007	\$255,360	\$255,360	\$255,360
2006	\$247,220	\$247,220	\$247,220
2005	\$225,670	\$225,670	\$159,720

#### Land Information

Zoning Code	ВІ	Total Acres	0.504
Land Value	\$142,600	Land Improvements	Not Available
Renaissance Zone	No	Renaissance Zone Expiration	No Data to Display
		Date	
ECF Neighborhood	00020.GS,CONVMKT	Mortgage Code	No Data to Display
Lot Dimensions/Comments	No Data to Display	Neighborhood Enterprise	No
		Zone	

	Total Frontage: 0.00 ft	Average Depth: 0.00 ft
No lots found.		
Lot(s)	Frontage	Depth

#### **Legal Description**

T3N, R11E, SEC 14 PART OF SW 1/4 BEG AT PT DIST S 89-51-30 E 33 FT & N 60 FT FROM SW SEC COR, TH N 135 FT, TH E 162.50 FT, TH S 135 FT, TH W 162.50 FT TO BEG 0.51 AB203A

#### Land Division Act Information

Date of Last Split/Combine	No Data to Display	Number of Splits Left	Not Available
Date Form Filed	No Data to Display	Unallocated Div.s of Parent	Not Available
Date Created	No Data to Display	Unallocated Div.s Transferred	Not Available
Acreage of Parent	0.00	Rights Were Transferred	Yes
Split Number	0	Courtesy Split	No
Parent Parcel	No Data to Display		

#### Sale History

Sale Date	Sale Price	Instrument	Grantor	Grantee	Terms of Sale	Liber/Page
07/30/2019	\$2,060,000.00	РТА	SAFEWAY ACQUISITION CO LLC	ROCHESTER AVON PARTNERS, LLC	ARMS LENGTH EQUAL	
03/31/2005	\$497,450.00	WD	SHELL OIL CO	SAFEWAY ACQUISITION COMPANY LLC	ARMS LENGTH EQUAL	35438/076


#### Building Information - 1407 sq ft Markets - Convenience (Commercial)

Floor Area	1,407 sq ft	Estimated TCV	Not Available
Occupancy	Markets - Convenience	Class	С
Stories Above Ground	1	Average Story Height	11 ft
Basement Wall Height	0 ft	Identical Units	1
Year Built	1970	Year Remodeled	Not Available
Percent Complete	100%	Heat	Package Heating & Cooling
Physical Percent Good	74%	Functional Percent Good	100%
Economic Percent Good	100%	Effective Age	20 yrs

<sup>\*\*</sup>Disclaimer: BS&A Software provides BS&A Online as a way for municipalities to display information online and is not responsible for the content or accuracy of the data herein. This data is provided for reference only and WITHOUT WARRANTY of any kind, expressed or inferred. Please contact your local municipality if you believe there are errors in the data.


Copyright © 2019 BS&A Software, Inc.


15-14-351-011 HERITAGE GROUP




$$AREA \Rightarrow 11 \times 23 = 253$$
 $525 \times 73 = 3832.5$ 
 $51 \times 20 = 1020$ 
 $9.5 \times 32 = 304$ 
 $5409.5 5F$ 











## LICENSING AND REGULATORY AFFAIRS BUREAU OF FIRE SERVICES STORAGE TANK DIVISION

#### **FACILITY INSPECTION REPORT**

Owner Name & Address:

Location of Tanks:

Safeway Acquisitions Group LLC 8700 Brandt Dearborn, MI 48126 Express 100 Inc 975 S Rochester Rd Rochester, MI 48037 County - Oakland Facility ID - 00009055

ATTENTION: Steve Saad

A Reinspection was conducted on September 20, 2016, for the above-referenced facility for compliance with Part 211, Underground Storage Tank Regulations, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended (Act 451); the Michigan Underground Storage Tank Rules (MUSTR), 2008 AACS R 29.2101 et seq.; and the applicable sections of the rules for the Storage and Handling of Flammable and Combustible Liquids, 2014 AACS R 29.5601 et seq. The inspection showed that the tank(s) was de-tagged (approved/certified).

The existing compartment (diesel/premium) tank now has interstitial monitoring installed for the tank and piping. Inspector was informed that the double-wall flex piping only goes to the first dispenser and the rest of the underground fuel piping is single-wall fiberglass piping. As a result, yearly line testing will still be required.

The inspection and violations (if any) were discussed with Dan Jaber w/Dans Service at the time of the inspection.

If you have additional questions concerning this matter, please contact me.

Jerry Arnold	9/20/16

Jerry Arnold
Hazardous Materials Storage Inspector
Region 1
PO Box 30033
Lansing, MI 48909
Phone: (734) 891-1523

Phone: (734) 891-1523 Fax: (517) 332-1428

Email: arnoldj@michigan.gov

Date

Department of Licensing and Regulatory Affairs, Bureau of Fire Services, Storage Tank Division

#### REGISTRATION OF UNDERGROUND STORAGE TANKS

The information in this form is required under "Part 211, Underground Storage Tank Regulations, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended." Any owner who knowingly fails to notify or submits false information shall be subject to entire and or civil penalties not to exceed \$5,000 per day for each tank for which notification is not given or for which false information is submitted.

<del></del>	·				
NEW REGISTRATION	If sending P.O. Box 30	payment and form, ma 0033, Lansing, Mi 4890	ail to: LARA, Cashiers ( 9	Office UST/AS AU	6 12 201 FACILITY
M AMENDED INFORMATION	If sending   525 West A	payment and form OV Illegan, Lansing, MI 489	ERNIGHT: LARA, Cas 909	hiers Office U	ST/AST, (if known)
(for Registered USTs Only)		the FORM ONLY, mail on, P.O. Box 30033, La	to: LARA, Bureau of Finsing, MI 48909	re Services, S	Storage - 9055
NUMBER OF TANKS AT FACILITY:	2 1	NUMBER OF CONTINUATION SHEETS ATTACHED: 3			
I. OWNERSHI	P OF TANKS		II.	LOCATION	OF TANKS
IF THIS IS A NEW OWNER'S A		( - ,			SECTION I, PLEASE CHECK
OWNER NAME (Corporation/Individual, etc.) SAFEWHY ACQUISE		GROWP LLC	FACILITY NAME OR SITE IDE		-
8700 SRANOT			STREET ADDRESS (P.O. BO)	x Not Acceptable)	ROAD
DEARBORN	STATE	48126	ROCHESTER		MI LB037
COUNTRY (Please Specify)  USA OTHER			COUNTY		
		_	OAKLAND		
(313) 624-9911			AREA CODE & PHONE NUM (248) 601- (		
			_ <u>.</u>		RECEIVED
LATITUDE AND LONGITUDE of facility (if kno	own)				
LATITUDE (North).			LONGITUDE (West):		JUL 2 2 2016
		III. TYPE O	F OWNER		
FEDERAL X	•	IAL			BUREAU OF FIRE SERVICES
☐ STATE GOVERNMENT ☐	PRIVATE			·	
LOCAL GOVERNMENT AF	RE TANKS LOC	CATED ON LAND WITHIN	I A RESERVATION? 🔲 Y	ES 🔲 NO	
IF TANKS ARE LOCATED WITHIN A F	RESERVATION	N, DOES A NATIVE AMER	RICAN TRIBE OWN TANKS	37 🗌 YES 🖂	NO
IF TANKS ARE OWNED BY A TRIBE,	NAME OF TR	IBE:			
		IV. TYPE OF	FACILITY		
PUBLIC GAS STATION		☐ LOCAL GOVERNME		CONTRA	CTOR
PRIVATE GAS STATION		☐ STATE GOVERNME	NT	TRUCKIN	NG/TRANSPORT
☐ MARINE GAS STATION	1	FEDERAL/NON-MILI	ITARY	☐ UTILITIE	s
☐ PETROLEUM DISTRIBUTOR		☐ FEDERAL-MILITARY	<b>(</b>	RESIDEN	NTIAL
AIRLINE AND/OR AIRCRAFT OV		COMMERCIAL		FARM	<b>-</b>
AUTO DEALERSHIP		INDUSTRIAL		OTHER (	Explain)
RAILROAD		HOSPITAL			
		V. CONTAC	T PERSON		
JOE YASSIN		MAMAG	EMEAT	Area Code & Phi	995-3756
Class A operator: Name:  MORNE JANSEN!	MYMAY	EN OSCAL	R W. LARSON	Area Code & Phi	575-0920
Class B operator: Name: MERCI		Company ()(CA)	W LARSON	Area Code & Phi	one No. 620-0070
7.1.4	<u>-</u>	VI. CERTIF			
VI. CERTIFICATION  I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION SUBMITTED IN THIS FORM AND ALL ATTACHED DOCUMENTS AND THAT I HAVE VERIFIED THAT THE INFORMATION IS TRUE, ACCURATE, AND COMPLETE.					
NAME AND OFFICIAL TITLE OF OWNER OF	R OWNERS' AUT	THORIZED REPRESENTATIV	/E SIGNATURE	. /	DATE
MORNE JANSENNAN VIVIEN MORNE LEW DURCH 7-19-16					

Page 2 of 6

BFS-3821 (Rev 6/15)

VII. DESCRIPTION OF UNDERGROUND STORAGE TANKS								
(Complete the following pages for	r each tank	at this loca	tion. Copy	these page	s for additi	onal tanks i	if needed.)	
TANK IDENTIFICATION NUMBER	S	6						
STATUS OF TANKS (Check One)     CURRENTLY IN USE     TEMPORARILY OUT OF USE     AMENDMENT OF INFORMATION  (If tanks are removed/closed, complete Section VIII)		<b>X</b>	000	000	000	000	000	000
2 DATE OF INSTALLATION (Month/Day/Year)								
3. ESTIMATED TOTAL CAPACITY (Gallons)								
						•		
VIII. TANKS OUT-OF-USE OR CH							ection IX.)	
CLOSING OF TANK     A. ESTIMATED DATE LAST USED     (Month/Day/Year)						:		
B. ESTIMATED DATE TANK WAS REMOVED/CLOSED-IN-PLACE or CHANGE-IN-SERVICE (Month/Day/Year)								
C. TANK WAS REMOVED FROM GROUND								
<ul> <li>D. TANK FILLED WITH INERT</li> <li>MATERIAL (Sand, Concrete, etc.)</li> <li>DESCRIBE TYPE OF FILL USED</li> </ul>								<u> </u>
REASON TANK WAS NOT REMOVED (Specify in comments area)								
2. CHANGE-IN-SERVICE				0		0		
	IX	. SUBSTAN	NCE STORE	:D	<u></u>	÷=	···································	
1. SUBSTANCE CURRENTLY OR LAST STORED IN GREATEST QUANTITY								
BY VOLUME  GASOLINE  DIESEL  GASOHOL  KEROSENE  (Not For Consumptive Use On Premises) FUEL OIL  WASTE OIL  USED OIL  HAZARDOUS SUBSTANCE  HEATING OIL  MIXTURE  TANK HAS COMPARTMENTS  OTHER (Specify in comments area)	000000000000000	00000000000000	0000000000000000	000000000000000	000000000000000	000000000000	00000000000	000000000000000
(List substances in comments area) CERCLA NAME AND/OR CHEMICAL ABSTRACT SERVICE (CAS) NUMBER (if hazardous substance stored)								

**,** 

XI. CERTIFICATION OF COMPLIANCE								
TANK IDENTIFICATION NUMBER	5	6						
INSTALLATION     A. INSTALLER CERTIFIED BY TANK     AND PIPING MANUFACTURERS     B. INSTALLATION INSPECTED BY A         REGISTERED ENGINEER     C. INSTALLATION INSPECTED AND         APPROVED BY BFS     D. ANOTHER METHOD ALLOWED BY     BFS (Please Specify)		0 0	_ 					<u> </u>
the same of the sa	XII. TANK	and PiPING	RELEASE	DETECTION	1	J		~
1. TANK RELEASE DETECTION  A. MANUAL (Static) TANK GAUGING  B. TANK TIGHTNESS TESTING  C. INVENTORY CONTROL  D. AUTOMATIC TANK GAUGING  E VAPOR MONITORING  F. GROUNDWATER MONITORING  G. INTERSTITIAL MONITORING  DOUBLE WALLED TANK/PIPING  H INTER MONITORING/SECOND  CONTAINMENT  I. OTHER METHOD ALLOWED BY  BFS (Specify in comments area)  2. PIPING RELEASE DETECTION			000000000000	0000000000	0000000000	0000000000	000000000	000000000
A AUTOMATIC LINE LEAK DETECTORS B. INTERSTITIAL MONITORING DOUBLE WALLED PIPING C. INTERSTITIAL MONITORING SECOND CONTAINMENT D. LINE TIGHTNESS TESTING E. OTHER METHOD ALLOWED BY BFS (Specify in comments area)			00 0 00	00 0 00		00 0 00	00 0 00	00 0 00
	XIII. EI	NVIRONME	NTAL PROT	ECTION .				
1. OVERFILL PROTECTION DEVICE INSTALLED								
2. SPILL PROTECTION DEVICE INSTALLED								
3 HAVE YOU INSTALLED IMPRESSED CURRENT CATHODIC PROTECTION? A. YES B. NO	00	00	00				0	

COMMENTS AND/OR CLARIFICATIONS:	2	_
CORRESTION OF INFO	ORMATION) FOR	PROPERTY OWER
# S TANK RECEASE DETEC # 5 PIPING RECEASE DETE LEAK DETECTORS &	-	STITIAL MONITORINO STOMATIC LINE ESS TESTINOS.
# 6 TANK RECEASE DETEC # 6		TTIAL MONITORING
PIPING RELEASE DETECTORS & DOUBLE WALLED R	CTION - AUTOIN PINTERSTITIA PING .	NATIC LINE L MONITORING
PLANSE CONTACT ME ANY OUESTIONS.	E SNOUL II G	YOU HAVE
THANK YOU. MORNE.		
	Page 6 of 6	BFS-3821 (Rev 6/15)



• • • • • • • •

**MORNE VAN VUREN** 

10100 Dixle Hwy. Clarkston, MI 48348

www.larsonco.com

248.620.0070
Direct 248 575.0920
Fax 248.620.0071
Cell 810.217.0752
Email mvanvuren@larsonco.com



## LICENSING AND REGULATORY AFFAIRS BUREAU OF FIRE SERVICES STORAGE TANK DIVISION

#### **FACILITY INSPECTION REPORT**

Owner Name & Address:

Location of Tanks:

Khalil Saad 975 S. Rochester Rochester Hills, MI 48307 Express 100 Inc 975 S Rochester Rd Rochester, MI 48037 County - Oakland Facility ID - 00009055

ATTENTION: Steve Saad

A Reinspection was conducted on May 18, 2016, for the above-referenced facility for compliance with Part 211, Underground Storage Tank Regulations, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended (Act 451); the Michigan Underground Storage Tank Rules (MUSTR), 2008 AACS R 29.2101 et seq.; and the applicable sections of the rules for the Storage and Handling of Flammable and Combustible Liquids, 2014 AACS R 29.5601 et seq. The inspection showed that the facility is disapproved.

1 Release detection records shall be retained for 2 years for inventory and repairs to the release detection equipment and 5 years for tightness tests and performance claims. UST 280.34

Special Attention: Provide the last (2) months of inventory control documentation and monthly tank monitor printouts for review.

2 Interstitial or monthly monitoring shall be conducted in accordance with Section 280.44 (C).

Section 280.44(C)

Special Attention: NOTE: Tanks installed after July 2008 where required to be double-wall and interstitial monitored.

Pump liquid out of all existing tank sumps. The diesel & premium tank sumps need to be maintain liquid tight.

3 Registration shall be submitted within 30 days of tank or owner status change. UST 280.22(A)

Special Attention: Submit an amended registration form (BFS3821) to this office showing correct owner/operator and tank type/release detection methods.

4 Overfill protection. UST 280.20(C) Steve Saad 2

Special Attention: Provide written documentation to this office that the existing tanks have met the overfill protection requirements. Note the tank(s) checked, the type of overfill device installed for that tank(s), the person who confirmed the overfill device is installed and working properly, and the date that it was checked.

The existing drop tube for the regular tank appears to be short. Investigate and make repairs as needed.

Documentation shall be furnished to the district office identified below verifying that the violation(s), cited in this inspection report have been corrected. The documentation shall be provided by July 04, 2016. If the cited violation(s) are not corrected and/or certification of compliance is not provided by the date specified, a reinspection will be conducted. The owner or operator of this facility will be subject to civil and criminal provisions pursuant to Part 211 of Act 451, including and not limited to placement of tags to the tank(s) prohibiting delivery of product if the stated violations have not been corrected.

If you have additional questions concerning this matter, please contact me.

Jerry Arnold	5/19/16
<del></del>	<del> </del>

Date

Jerry Arnold Hazardous Materials Storage Inspector Region 1 PO Box 30033 Lansing, MI 48909

Phone: (734) 891-1523 Fax: (517) 332-1428

Email: amoldj@michigan.gov



## LICENSING AND REGULATORY AFFAIRS BUREAU OF FIRE SERVICES STORAGE TANK DIVISION

#### **FACILITY INSPECTION REPORT**

Owner Name & Address:

Location of Tanks.

Khalil Saad 975 S. Rochester Rochester Hills, MI 48307 Express 100 Inc 975 S Rochester Rd Rochester, MI 48037 County - Oakland Facility ID - 00009055

ATTENTION: Steve Saad

An Existing Facility Inspection was conducted on March 7, 2016, for the above-referenced facility for compliance with Part 211, Underground Storage Tank Regulations, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended (Act 451); the Michigan Underground Storage Tank Rules (MUSTR), 2008 AACS R 29.2101 et seq.; and the applicable sections of the rules for the Storage and Handling of Flammable and Combustible Liquids, 2014 AACS R 29.5601 et seq. The inspection showed that the facility is disapproved.

1 Release detection records shall be retained for 2 years for inventory and repairs to the release detection equipment and 5 years for tightness tests and performance claims. UST 280.34

Special Attention: Provide the last (2) months of inventory control documentation and monthly tank monitor printouts for review.

2 Pressurized piping shall be tested annually in accordance with Section 280.44(B). Section 280.41(B)(1)(II)

Special Attention: Provide documentation that the existing fuel pressure lines have been tested and PASSED a line tightness test within the last year.

3 Line leak detectors shall be tested annually. Section 280.44(A)

Special Attention: Provide documentation that the existing line leak detectors have been tested within the last year and are working properly.

4 An emergency shutoff valve with a fusible link shall be manually tested annually. UST 280.10(J) (FL/CL Part 3, Section 6.3.9.1)

Special Attention: Provide documentation that the existing impact valves have been tested within the last year and are working properly.

5 Interstitial or monthly monitoring shall be conducted in accordance with Section 280.44 (C).

Section 280.44(C)

2

Special Attention: NOTE: Tanks installed after July 2008 where required to be double-wall and interstitial monitored.

Pump liquid out of all existing tank sumps. The diesel & premium tank sumps need to be maintain liquid tight.

6 Registration shall be submitted within 30 days of tank or owner status change. UST 280.22(A)

Special Attention: Submit an amended registration form (BFS3821) to this office showing correct owner/operator and tank type/release detection methods.

7 Overfill protection. UST 280.20(C)

Special Attention: Provide written documentation to this office that the existing tanks have met the overfill protection requirements. Note the tank(s) checked, the type of overfill device installed for that tank(s), the person who confirmed the overfill device is installed and working properly, and the date that it was checked.

The existing drop tube for the regular tank appears to be short. Investigate and make repairs as needed.

Documentation shall be furnished to the district office identified below verifying that the violation(s), cited in this inspection report have been corrected. The documentation shall be provided by May 06, 2016. If the cited violation(s) are not corrected and/or certification of compliance is not provided by the date specified, a reinspection will be conducted. The owner or operator of this facility will be subject to civil and criminal provisions pursuant to Part 211 of Act 451, including and not limited to placement of tags to the tank(s) prohibiting delivery of product if the stated violations have not been corrected.

If you have additional questions concerning this matter, please contact me.

Jerry Arnold	3/7/16
Jerry Arnold	Date

Hazardous Materials Storage Inspector Region 1 PO Box 30033 Lansing, MI 48909

Phone: (734) 891-1523 Fax: (517) 332-1428

Email: amoldj@michigan.gov

From:Oscar W LARSON

248 620 0071

02/16/2015 13:15

SEP 02 2015 #166 P.015/015

Department of Licensing and Regulatory Affairs, Bureau of Fire Services, Storage Tank Division

REGISTRATION OF UNDERGROUND STORAGE TANKS
The information in this form is required under "Part 211, Underground Storage Tank Regulations, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended." Any owner who knowledge fails to notify or submits false information shall be subject to a miscienceanor and/or civil penalties not a exceed \$5,000 per day for each tank for which notification is not given or for which false information is submitted.

		If sending payment and	en or for which false into	uri estem de audomático ( Titratico la automático	misciemear.	or and/or civil penalies not		
	NEW REGISTRATION	P.O. Box 30033 1 ameles	orm. mail to: LARA,	Cashlers Office Lici	T/A C/T	······································		
	1_	If sending pinment and form, mail to: LARA, Cashlers Office UST/AST, P.O. Box 30033, Lansing, MI 48909				FACILITY		
	AMENDED INFORMATION	H sending payment and form OVERNIGHT: LARA, Cashlers Office UST/AST, 525 West Allegan, Lansing, Mi 48909			10 NUMBER			
	(for Registered USTs Only)	If sending the FORM ONLY, mail to: LARA, Bureau of Fire Services, Storage Tank Division, P.O. Box 30033, Lansing, M. 48900				(If known)		
		Tank Division, P.O. Box 30	Y mail to LARA, Bu	reau of Fire Service	e Storman	1		
	ANDEDCO	7	133, Lansing, M 4890	9	er Amaño			
	NUMBER OF TANKS AT FACILITY:	MUMBER OF COM	TINUATION SHEETS AT			00009055		
	IF THIS IS A NEW OWNERS AT				_,			
	IF THIS IS A NEW OWNER'S AT OWNER HAME (Corporation/Individual, etc.)	DORESS, PLEASE CHECK DO			N-OFFICINI	Company of the second		
	KHALIL S	FACILITY NAME O	FINFORMATION IS THE SAME AS SECTION I, PLEASE CHECK OF FACILITY NAME OR SITE DENTIFIER					
	MAI ING ADDRESS		$-1$ $K^{\{}$	K.B. minimort				
	975 S.F	ROSHESTER	STREET ADDRESS	(P.O. Box Not Acceptely	OV I			
		STATE ZIP 100		The second second second	eì	•		
	KOCHESTER HILL'S	MI 218307	CITY	<del></del>	STATE	ZIP		
	COUNTRY (Please Specify) USA OTHER	7	COUNTY		MI	1		
	AREA CODE & PHONE NUMBER		100	Kland				
	1248 1 60/-0050		AREA CODE & PHO	NE NUMBER				
)	TAX PAYER ID OR SOCIAL SECURITY NUMB							
•	LATITUDE AND LONGITUDE of facility (If know				•	· · · · · · · · · · · · · · · · · · ·		
i	LATITUDE (North):		<del>-</del>		<u> </u>			
			TONGULADE (Mac):			· · · · · · · · · · · · · · · · · · ·		
		A CHARLES AND A CONTRACTOR	Epigle of Explanation	E STATE OF THE	Section 1	-		
- }	THE STATE OF LINES.	COMMERCIAL				CONTRACT TO A STATE OF THE STAT		
	<b>5</b>	RIVATE						
- 1	IF TANKS ARE LOCATED HIS BULL	ANKS LOCATED ON LAND WIT	HIN A RESERVATIONS	Fives Class				
- 1	IF TANKS ARE LOCATED WITHIN A RESI IF TANKS ARE OWNED BY A TRIBE, NAM	ERVATION, DOES A NATIVE A	MERICAN TRIBE OWN T	ANKS FIVE FI				
F	end who will die an arrange of the state of			WARL TI LES TI	40			
		*****************************						
١,	PUBLIC GAS STATION PRIVATE GAS STATION	☐ LOCAL GOVERN	MELT.	200 Sept. 100	TO NAME OF THE	25.000 402.4025		
	PRIVATE GAS STATION  MARINE GAS STATION	D STATE GOVERN	MENT	CONTRACT	TOR			
- 1	PETROLEUM DISTRIBUTOR	☐ FEDERAL/NON-A	IN ITADY	TRUCKING.	/TRANSPOR	रा		
1	ARLINE AND/OR AIRCRAFT OWNER	☐ FEDERAL-MILITA	RY	☐ UTILITIES ☐ RESIDENTI				
1 1	J AUTO DEALERSHIP	COMMERCIAL   INDUSTRIAL		D FARM	AL.			
	I RAILROAD .	HOSPITAL		OTHER (Exp	otaln)	•		
				•				
N	ame VII all Const	NEW YORK WORK	<b>动的电影的影響系</b>		and the second second	Marie Company of the		
	KHALIL SAAD	. Job Title	resident	Area Code & Phone	No.			
G	252 A poetator: Name	Company	101000	1248 601	-005	'n		
<b> </b>	MORAY Jansen Van	VOCEN BU	10	Area Code & Phone I	Va.	<del></del>		
4	MIS B operator: Name:	Committee Committee	Lusson	248-5	49.3	6.10		
222	Morny Jansen Van Beristor Harrier Daniel Mer	Cicc 6 1.	1000	Area Code & Phone N	lo.	4113		
		CANCELLY AND	Corson	248-50	19.36	10		
10	ERTIFY UNDER PENALTY OF LAW THAT I H	AVE PERSONALLY EVALUATION	THE PURPLE SHAPE		NO WEST	70 TO 10 TO		
쑶	ERTIFY UNDER PENALTY OF LAW THAT I H TACHED DOCUMENTS AND THAT I HAVE VERS ME AND OFFICIAL TITLE OF DWINER OR DWINE	HED THAT THE INFORMATION IN T	THE ACCURATE AND THE	E INFORMATION SULL	MITED IN TI	HIS FORM AND ALL		
'	K Low Strand 111	A CHARLES WENESENTALL	E SIGNATURE , 2	PLETE.		THE PERSON ALL		
<u> </u>	IN WELL XILLY Who	L:L Saud	1 1/4	1 0.17 c	1	DATE		
		Page 2 of		wee Son	9/1	8/2/15		
			-	BFS-38	21 (Ray 8/14)			

# COMMENTS AND/OR CLARIFICATIONS: amended for name change of "B" operator only RETAIN THIS IMAGE RETAIN THIS IMAGE

MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY

1-3108/ 411

#### INTEROFFICE COMMUNICATION

DATE:

July 29, 2008

TO:

Christy Clark, RRD SE District Office 586-753-3809

FROM:

Marcia Poxson

WHMD-STSW-STU

517-373

SUBJECT:

Shell Service Station, 975 S Rochester Rd, Rochester, Oakland County, Facility

Number 00009055

We have received a request to close site evaluations following tank removal at the referenced facility. This site is a closed LUST facility, C-0214-96 and C-0252-96, both releases were closed under Type-I, Residential not restricted.

The submitted analytical data with the site assessment report indicates levels under MDL. This is a request for closure under IM-10 scenerio 3. Therefore, I need to know if the indicated levels with this report are less than what was indicated with the LUST site closure, to allow for clean closure under IM-10. A copy of the site assessment report is being sent for you to review.

Let me know, at your earliest convenience, if you concur with granting a clean closure for this site evaluation, or if you believe a new release should be generated.

Thank you for your attention to this matter.

Enclosure Cc Mr. Chris Conklin, DEQ WHMD – SE



## LICENSING AND REGULATORY AFFAIRS BUREAU OF FIRE SERVICES STORAGE TANK DIVISION

#### **FACILITY INSPECTION REPORT**

Owner Name & Address:

Safeway Acquisitions Group LLC 8700 Brandt Dearborn; MI 48126 Location of Tanks:

Express 100 Inc 975 S Rochester Rd Rochester, MI 48037 County - Oakland Facility ID - 00009055

Date

ATTENTION: Khalil Saad

A Reinspection was conducted on October 28, 2013, for the above-referenced facility for compliance with Part 211, Underground Storage Tank Regulations, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended (Act 451); the Michigan Underground Storage Tank Rules (MUSTR), 2008 AACS R 29.2101 et seq.; and the applicable sections of the rules for the Storage and Handling of Flammable and Combustible Liquids, 2003 AACS R 29.5101 et seq. The inspection showed that the facility is approved.

Inspector received an amended registration form (pg. #2 only) showing the new Operator A & B for this facility and will forward to Lansing.

If you have additional questions concerning this matter, please contact me.

Jerry Arnold

Hazardous Materials Storage Inspector

Lansing Office STD LARA 3101 Technology Boulevard

Suite H

PO Box 30033

Lansing, MI 48909 Phone: (734) 891-1523

Fax: (517) 332-1428

Email: arnoldj@michigan.gov



## LICENSING AND REGULATORY AFFAIRS BUREAU OF FIRE SERVICES STORAGE TANK DIVISION

#### **FACILITY INSPECTION REPORT**

Owner Name & Address:

Safeway Acquisitions Group LLC 8700 Brandt Dearborn, MI 48126 Location of Tanks:

K & B Mini Mart Inc. 975 S Rochester Rd Rochester, MI 48037 County - Oakland Facility ID - 00009055

ATTENTION: Niraj Petal

An Existing Facility Inspection was conducted on May 24, 2013, for the above-referenced facility for compliance with Part 211, Underground Storage Tank Regulations, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended (Act 451); the Michigan Underground Storage Tank Rules (MUSTR), 2008 AACS R 29.2101 et seq.; and the applicable sections of the rules for the Storage and Handling of Flammable and Combustible Liquids, 2003 AACS R 29.5101 et seq. The inspection showed that the facility is disapproved.

1 Every facility having 1 or more UST systems subject to MUSTR shall have a class A and class B operator.
UST 280.13

Special Attention : Provide this office with documentation showing that the new operator training requirement has been met.

2 Release detection records shall be retained for 2 years for inventory and repairs to the release detection equipment and 5 years for tightness tests and performance claims. UST 280.34

Special Attention: Monthly PASSING tank leak test results and/or sensors liquid status printouts from the existing tank monitoring system needs to be maintain for review by Inspector. Failure to provide this office with copies of the last two months of PASSING monthly tank leak test or sensor status printouts may result in a tank tightness test being ordered for all of the existing tanks.

At the time of the inspection the tank monitor showed T1: PROBE OUT. Investigate and make repairs as needed.

3 Pressurized piping shall be tested annually in accordance with Section 280.44(B). Section 280.41(B)(1)(II)

Special Attention: Provide documentation that the existing fuel pressure lines have been tested and PASSED a line tightness test within the last year.

4 Line leak detectors shall be tested annually. Section 280.44(A)

Special Attention: Provide documentation that the existing line leak detectors have been tested within the last year and are working properly.

5 An emergency shutoff valve with a fusible link shall be manually tested annually. UST 280.10(J) (FL/CL Part 3, Section 6.3.9.1)

Special Attention: Provide documentation that the existing impact valves have been tested within the last year and are working properly.

Replace existing damaged impact valve at dispenser #7/8. Replace missing bolts and tighten ALL loose bolts for the support brackets at dispenser #1/2 & #3/4.

6 Tight fitting hose connections shall be furnished on fill pipes of tanks greater than 1,000 gallons for class I liquids.

UST 280.10 (J) (FL/CL Part 2, Section 2.3.3.4.3)

Special Attention: Replace missing V/R cap at regular tank.

7 Dispenser hose shall not be longer than 18 feet and shall be listed. UST 280.10 (J) (FL/CL Part 3, Section 6.5.1)

Special Attention: Replace damaged fuel hose at dispenser #4 and worn out short "whip" fuel hose at dispenser #5 & #7.

8 The area beneath each dispenser shall be designed and maintained to contain lost product.

UST 280.10 (J) (FL/CL Part 3, Section 6.3.4.1)

Special Attention: Cleanout liquid and debris from ALL dispenser sumps and maintain.

9 Dispenser shall be in clear view of attendant and be able to communicate. UST 280.10(J) (FL/CL Part3, Section 9.4.5)

Special Attention: Provide a working intercom system so the Attendant can communicate with Customers.

At the time of the inspection, free product was found in the regular tank sump. It appeared to be contained in the sump and was remove. No leak was found. The source of the free product may have been generator by recent service work performed. Provide this office with a copy of the liquid waste manifest.

Inspector was informed that the facility name was incorrect and the current facility Operator did not received the recent record request.

The state database shows (1) tank. The facility has (2) tanks. The 8,000 gallon DW PermaTank compartment (diesel/premium) UST believe to have been installed in August 2008. Submit documentation to this office to confirm.

Documentation shall be furnished to the district office identified below verifying that the violation(s), cited in this inspection report have been corrected. The documentation shall be provided by June 10, 2013. If the cited violation(s) are not corrected and/or certification of compliance is not provided by the date specified, a reinspection will be conducted. The owner or operator of this facility will be subject to civil and criminal provisions pursuant to Part 211 of Act 451, including and not limited to placement of tags to the tank(s) prohibiting delivery of product if the stated violations have not been corrected.

If you have additional questions concerning this matter, please contact me.

Jerry Arnold

Hazardous Materials Storage Inspector

SE Michigan District Office

27700 Donald Court

Warren, MI 48092-2793 Phone: (586) 753-3848

Phone: (586) 753-38 Fax: (586) 753-3831

Email: arnoldj@michigan.gov

5/20/13

Date



## LICENSING AND REGULATORY AFFAIRS BUREAU OF FIRE SERVICES STORAGE TANK DIVISION

#### **FACILITY INSPECTION REPORT**

Owner Name & Address:

Safeway Acquisitions Group LLC 8700 Brandt Dearborn, MI 48126 Location of Tanks:

Express 100 Inc 975 S Rochester Rd Rochester, MI 48037 County - Oakland Facility ID - 00009055

ATTENTION: Niraj Petal

A Records Request was conducted on May 7, 2013, for the above-referenced facility for compliance with Part 211, Underground Storage Tank Regulations, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended (Act 451); the Michigan Underground Storage Tank Rules (MUSTR), 2008 AACS R 29.2101 et seq.; and the applicable sections of the rules for the Storage and Handling of Flammable and Combustible Liquids, 2003 AACS R 29.5101 et seq. The inspection showed that there was no action taken by the inspector.

This facility is schedule for an inspection in the near future. State records indicate the release detection requirements for the (1) regulated underground storage tank system is being met by utilizing an automatic tank gauging system along with monthly inventory control and yearly testing.

Provide copies to this office for review the last (2) available months of release detection documentation (monthly inventory record & monthly tank monitor test and/or sensor printouts).

Provide this office with yearly passing test results for the underground pressure fuel lines & line leak detector devices as needed.

Provide this office with documentation showing the existing Impact Valves, Overfill Prevention Devices (identify type), & electrical E-stop system have been checked within the last year and found to be in good working condition.

If the owner or operator information shown on this report is incorrect, or if the release detection methods have been changed, an amended registration form (EQP3821) will need to be submitted within 30 days.

If you have additional questions concerning this matter, please contact me.

Jerry Arnold

Hazardous Materials Storage Inspector

SE Michigan District Office

27700 Donald Court Warren, MI 48092-2793

Phone: (586) 753-3848 Fax: (586) 753-3831

Email: arnoldj@michigan.gov

Date

### REGISTRATION OF UNDERGROUND STORAGE TANKS

The information in this form is required under "Part 211, Underground Storage Tank Regulations, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as emended." Any owner who knowingly fails to notify or submits false information shall be subject to e misdemeanor and/or civil penalties not to exceed \$5,000 per day for each tank for which notification is not given or for which false information is submitted.

□ NEW REGISTRATION	If sending payment and form, mail to: Cashiers Office, DEQ, P.O. Box 30657, Lansing, MI 48909-8157				FACILITY ID NUMBER (If known)	
_	<u>If sendin</u>	g payment and form O\	/ERNIGHT, mail to: Ca	shiers Office, DEQ,		
AMENDED INFORMATION	i	t Allegan, 5 <sup>th</sup> Floor Sout	_		0000	
(for Registered USTs Only)	<u>If sendin</u> Remedia	If sending FORM ONLY, mall to: Storage Tanks & Contracts Unit, Remediation Division, DEQ, P.O. Box 30426, Lansing, MI 48909-7926		9055		
NUMBER OF TANKS AT FACILITY:	2_	NUMBER OF CONTINUATION SHEETS ATTACHED:				
. OWNERSH	P OF TAN	KS &	the resulting			
IF THIS IS A NEW OWNER'S A				THE SAME AS SECTION	II, PLEASE CHECK 🗍	
OWNER NAME (Corporation/Individual, etc.)  FACILITY NAME OR SITE IDENTIFIER						
Safeway Acquistre	<u>m Con</u>	npany UC	K&B Mini			
MAILING ADDRESS		. 5	STREET ADDRESS (P.O. B			
8700 Brandt				ochester state	710	
CITY	STATE	48126 1	Rochester H		48307	
Dearborn	INT	1 70104	COUNTY	1177   1411	1 1000	
COUNTRY (Please Specify)			( )			
☑ USA ☐ OTHER			Cakland			
AREA CODE & PHONE NUMBER			AREA CODE & PHONE NU			
(212 11. 14 ag 1)			(248)601-00	050		
T/4 ↓∪	MBER			F	RECEIVED	
L/	nown)		<del></del> -		OCT 26 2012	
LATITUDE (North):			LONGITUDE (West):		1	
1. 多,如" <b>就</b> 能,""安,在第二位是	સંત્રી અને લિય	III. TYPE	OF OWNER	क्षात्रमुक्ता प्रमुख्यान्त्रम् । स्टब्स्	DEO-FID UNIT	
	] COMME			1	DEC-ROKUNII	
STATE GOVERNMENT	-			L	<b>EXALEBED</b>	
	•	.OCATED ON LAND WITHI	N A RESERVATION? TY	′ES □NO	-1150	
. — ==					NOV 1 3 2012	
IF TANKS ARE LOCATED WITHIN A I			RICAN IRIBE OYYN IANNO	St 🗆 153 Millo	- 0,2012	
IF TANKS ARE OWNED BY A TRIBE,						
The contraction of the same of	State Little	WAR W. TYPE C	F FACILITY	the same of the same	Property of the second	
▼ PUBLIC GAS STATION		☐ LOCAL GOVERNM	ENT	☐ CONTRACTOR		
☐ PRIVATE GAS STATION		☐ STATE GOVERNM	ENT	☐ TRUCKING/TRAN	ISPORT	
☐ MARINE GAS STATION		☐ FEDERAL/NON-MI	LITARY	□ UTILITIES		
PETROLEUM DISTRIBUTOR		☐ FEDERAL-MILITAR	RY	RESIDENTIAL		
☐ AIRLINE AND/OR AIRCRAFT O	AIRLINE AND/OR AIRCRAFT OWNER					
☐ AUTO DEALERSHIP		☐ INDUSTRIAL		OTHER (Explain)		
.□ RAILROAD		☐ HOSPITAL				
V. CONTACT PERSON						
Name		Job Title		Area Code & Phone No.		
Class A operator; Name: Company Area Code & Phone No.						
Nimi Patal Saleman Acquisition Cr (845) 665_1174						
Class B operator: Name:  Class B operator: Name:  Company  Area Code & Phone No.						
Nirai Petal Safernay Acomsition Co. (845) 665-1174						
VI-CERTIFICATION						
I CERTIFY UNDER PENALTY OF LAW ATTACHED DOCUMENTS AND THAT I H.	THAT I HAVE	PERSONALLY EXAMINED	AND AM FAMILIAR WITH THE TRUE, ACCURATE, AND CO	IE INFORMATION SUBMIT	TED IN THIS FORM AND ALL	
NAME AND OFFICIAL TITLE OF OWNER	OR OWNERS	'AUTHORIZED	SIGNATURE///	11.11	DATE	
REPRESENTATIVE Kassem Beydown - Member /////						
	5	2	/X/	$\sim$ $_{/}$	EQP3821 (Rev B/12)	

# COMMENTS AND/OR CLARIFICATIONS: Amended Class A & B

6

EQP3821 (Rev 8/12)

# REGISTRATION OF UNDERGROUND STORAGE TANKS

NOV 1 4 2012

The information in this form is required under "Part 211, Underground Storage Tank Regulations, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended." Any owner who knowingly fails to notify or submits false information shall be subject to a misdemeanor and/or civil penalties not to exceed \$5,000 per day for each tank for which notification is not given or for which false information is submitted.

NEW REGISTRATION	If sending P.O. Box	payment and form, n 30657, Lansing, Mi 48	nail to: Cashlers Office, 909-8157	, DEQ,	FACILITY ID NUMBER (if known)	
MAMENDED INFORMATION	If sending 525 West	<u>f sending payment and form OVERNIGHT, mail to</u> : Cashiers Office, DEQ, 25 West Allegan, 5 <sup>th</sup> Floor South, Lansing, MI 48933				
(for Registered USTs Only)	If sending Remediat	f sending FORM ONLY, mail to: Storage Tanks & Contracts Unit, Remediation Division, DEQ, P.O. Box 30426, Lansing, MI 48909-7926				
NUMBER OF TANKS AT FACILITY:	4	NUMBER OF CONTINUA	ATION SHEETS ATTACHED	: <u> </u>		
I. OWNÉRSH	P OF TANK	(Shawara Area San 2	The State of the S			
IF THIS IS A NEW OWNER'S A	DDRESS, PL	EASE CHECK [	IF INFORMATION IS	THE SAME AS SECTION	II, PLEASE CHECK	
OWNER NAME (Corporation/Individual, etc.)			FACILITY NAME OR SITE ID			
Safeway Acquisition	m Com	pany uc	STREET ADDRESS (P.O. Bo	ov Not Acceptable)		
MAILING ADDRESS			975 Mack	ox Not Acceptable)		
8700 Brandt	LATATE	Tain	CITY	STATE	ZIP	
CITY	STATE	121P 48126	Detroit	M	48207	
Dearborn COUNTRY (Please Specify)	1 1001	1 (010-90	COUNTY			
☑ USA ☐ OTHER			Warne			
			AREA CODE & PHONE NUM	19ED		
AREA CODE & PHONE NUMBER			(313) 831-9			
(313) 1024-991			1(313) 831-7	66-		
	MBER				FIVED	
LATITUDE AND LONGITUDE OF TACITY (If ki	nown)		LONGTHE MACH	THE		
LATITUDE (North):		- 99	LONGITUDE (West):	\ <u></u>	<del>- 06 3012 / /</del>	
	Tall Viller	Sugar State of III. TYPE	OF OWNER # S	1 1 0	T 26 2012	
FEDERAL	] COMMER	RCIAL			DEQ-RD DRAGE TANKUNIT	
	7 PRIVATE				DEO HOKUNII	
			IN A RESERVATION?	ES NO \ SI	DRAGE	
IF TANKS ARE LOCATED WITHIN A	RESERVATIO	ON, DOES A NATIVE AME	RICAN TRIBE OWN TANKS	S? YES XNO		
IF TANKS ARE OWNED BY A TRIBE,						
			OF FACILITY SIESSEE	eralling are exist by track	· · · · · · · · · · · · · · · · · · ·	
· · · · · · · · · · · · · · · · · · ·	THE REAL PROPERTY.	WARRIED TO THE CONTENT	OF FACILITY OF THE	☐ CONTRACTOR		
PUBLIC GAS STATION		☐ LOCAL GOVERNI		TRUCKING/TRAN	ISPORT	
PRIVATE GAS STATION		☐ FEDERAL/NON-M		☐ UTILITIES		
MARINE GAS STATION  PETROLEUM DISTRIBUTOR		☐ FEDERAL-MILITA		RESIDENTIAL		
T	MANER	COMMERCIAL		☐ FARM		
	****	☐ INDUSTRIAL		OTHER (Explain)		
AUTO DEALERSHIP  RAILROAD		☐ HOSPITAL				
The second secon	and the second	- CONTA	CT PERSON - A COMPANY	AND THE SECOND STATE OF THE PERSON AND	en region de rens processos de	
Name	Service and the service of the servi	Job Title	NOTITE LIVER IN THE PARTY OF TH	Area Code & Phone No.		
Class A operator: Name:	·	Company		Area Code & Phone No.	<del></del>	
Minai Patal	_	Salanan Ac	ausitin Cu	(845) 665_	เเาฯ	
Class B operator: Name:		ompany	f-warran	Area Code & Phone No.		
Nivai Petal	ح	Safeway A	causition Co	(845) 665-	1174	
	ar of Arab	VILCER	1.50.0.12	A CONTRACTOR		
L CERTIFY LINDER PENALTY OF LAW	THAT I HAVE	PERSONALLY EXAMINED	AND AM FAMILIAR WITH TH	E INFORMATION SUBMIT	ED IN THIS FORM AND ALL	
ATTACHED DOCUMENTS AND THAT I HA	AVE VERIFIED	THAT THE INFORMATION I	S TRUE, ACCURATE, AND CO	MPLÉTE.		
NAME AND OFFICIAL TITLE OF OWNER	OR OWNERS'	AUTHORIZED	SIGNATURE////	1/1///	10/17/12	
REPRESENTATIVE Kassem	Beyde	oun-Membe		10 71 -	11-61-110	
	C/	2	11/ /k	<b>→</b> /	EQP3821 (Rev 8/12)	

# COMMENTS AND/OR CLARIFICATIONS: Amended Class A & B

# Konadu, Stella (DEQ)

From:

Amold, Jerry (DEQ)

Sent:

Wednesday, June 19, 2013 7:02 AM

To:

Konadu, Stella (DEQ)

Subject:

RE: FID#9055 - 975 S Rochester, Rochester, MI

ENTERED

(SMK)

Will do. Thanks

From: Konadu, Stella (DEO)

**Sent:** Tuesday, June 18, 2013 4:54 PM

To: Arnold, Jerry (DEQ); Block, James (DEQ)

Subject: RE: FID#9055 - 975 S Rochester, Rochester, MI

DEQ/RD

JUN 19 2013

Hello,

I have entered tank #6 information into the database, I use registration date of August 11, 2008, I will give the paper work to Jim Block to retroactively bill the site for 2008 thru 2013. Please have the owner complete registration form BSF (3821).

# **Thanks** Stella

From: Arnold, Jerry (DEQ)

Sent: Wednesday, June 12, 2013 1:49 PM

To: Konadu, Stella (DEQ) Cc: Wieber, Kevin (DEO)

Subject: FID#9055 - 975 S Rochester, Rochester, MI

Stella I have a facility that had a tank installed in 2008 but never registered.

Tank #6

8,000 gallon compartment (4/4) Prem/Diesel Double wall Composite

PermaTank

Pressure/Pressure

Double-wall flexible piping

Tank Release Detection

Automatic tank gauging & Inventory Control

Piping Release Detection

Automatic line leak detectors & Annual line testing

# Joury Arnold

**HMSI** 

Bureau of Fire Services Storage Tank Division 27700 Donald Court Warren, Michigan 48092

TX: 586-753-3848 Fax: 586-753-3831

Email: arnoldi@michigan.gov

www.michigan.gov/bfs

Year	Fees	Reg from	Reg to
2008	\$ 100.00	12/1/2007	11/30/2008
2009	\$ 100.00	12/1/2008	11/30/2009
2010	\$ 100.00	12/1/2009	11/30/2010
2011	\$ 100.00	12/1/2010	11/30/2011
2012	_+	12/1/2011	11/30/2012
2013	\$ 100.00	12/1/2012	11/30/2013
	\$ 600.00		

# 0009055

ENTERED

SMK

JUN 19 2013

DEQ/RD

# Dept of Licensing and Regulatory Affairs Bureau of Fire Services

# UNDERGROUND STORAGE TANK ANNUAL CERTIFICATION FEE INVOICE



# Under Authority of NREPA Act, 1994 PA 451, as amended, Sec 21102(8), Part 211 Failure to submit payment by the date due will result in a penalty as prescribed by law

see reverse side for financial responsibility information

Page 1

C0093656

Ref No: 00009055-55600

Owner Address Safeway Acquisitions Group LLC Tim McCafferty 8700 Brandt

Dearborn, MI 48126

Form: 50023

Owner Address Express 100 Inc 975 S Rochester Rd Rochester, MI 48037

Invoice Date:

Payment Due:

Invoice Number:

The owner of a storage tank system shall, upon registration or renewal of registration pay a certification fee for each tank and continue to pay a certification fee on storage tank(s) that have been closed or removed until notification to the LARA is provided on the required form BFS3821.

PLEASE REGISTER AND PAY ONLINE:

Visit: www.michigan.gov/business

One Stop Registration questions: (877) 766-1779

818723

June 19, 2013

June 19, 2013

UST Program Questions: (517) 241-9486

Invoice Item Quantity Unit Cost Total Cost 00009055 Tank #6 8,000 Gal Diesel, Premium Gasoline 6 \$100.00 \$600.00

The period of registration is from 12/1-11/30 for the years of 2008-2013 tank(s) must be close or removed before 12/1 of each year and notification of the closure or removal must be received by LARA by 11/30 of each year.

NOTE: This is for the years of 2008-2013 for Tank #6 only.

Payment Due: June 19, 2013

Total: \$600.00 |
Tax: \$0.00 |
Total Invoice: \$600.00 |

REGISTER & PAY ONLINE, visit www.michigan.go	ov/business			
MAKE CHECK OR MONEY ORDER PAYABLE TO: TO ENSURE PROPER CREDIT, SEND THIS PORTI				CE NO:
Dept of Licensing and Regulatory Affairs		ATIVICIAT TO:		8723
Cashiers Office - UST	C0093656	Ref No: 00009055-55600	RD	UST
PO Box 30657		For Cashier's Use Or	nlv:	
LANSING, MI 48909-8157			<u></u>	
(Please note or make any mailing corrections below)				
Owner Address				
Safeway Acquisitions Group LLC				
Tim McCafferty				
8700 Brandt				
Dearborn, MI 48126				

Total Due:

\$600.00

Department of Licensing and Regulatory Affairs, Bureau of Fire Services, Storage Tank Division

REGISTRATION OF UNDERGROUND STORAGE TANKS

The information in this form is required under "Part 211, Underground Storage Tank Regulations, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended." Any owner who knowingly fails to notify or submits false information shall be subject to a misdemeanor and/or civil penalties not to exceed \$5,000 per day for each tank for which notification is not given or for which false information is submitted.

MEW REGISTRATION  AMENDED INFORMATION (for Registered USTs Only)	P.O. Box If sendin Office, 42	If sending payment and form, mail to: LARA Cashiers Office - UST, P.O. Box 30657, Lansing, MI 48909-8157  If sending payment and form OVERNIGHT: LARA, Fire Services-UST, Cashiers Office, 425 West Ottawa Street, Lansing, MI 48933					
(101 Negistered 8013 Offiny)		g the FORM ONLY, ma sion, P.O. Box 30033, L		Fire Services, Storage	9 055		
NUMBER OF TANKS AT FACILITY: _	2	NUMBER OF CONTINUA	TION SHEETS ATTACHE	D:			
AND THE PROPERTY I. OWNERSH							
IF THIS IS A NEW OWNER'S A OWNER NAME (Corporation/Individual, etc.)		PLEASE CHECK	IF INFORMATION IS FACILITY NAME OR SITE I	THE SAME AS SECTION I, PI	LEASE CHECK [		
Safeway Acquisition	$\sim$	plic	9055	DENTI IER			
MAILING ADDRESS	100 - 10.		STREET ADDRESS (P.O. E	Box Not Acceptable)			
8700 Branat	CTATE	710	975 S. Roc	hester Kd			
Dearborn	M	48126	Rochester	STATE Z	18037		
COUNTRY (Please Specify)		iviey	COUNTY		1000		
☑ USA ☐ OTHER		<u>.                                    </u>	Oakland	•			
AREA CODE & PHONE NUMBER			AREA CODE & PHONE NU	MBER UST 52247	1-10-1 06/19/13		
(212) 7.74_9911	MBER		( )	<del>10208 328</del> 0			
Non	AIDEK						
ETTTOOL AND LONGITODE OF IBUILTY (If kn	own)			AY 2013 \$1	100		
LATTTUDE (North):			LONGITUDE (West):	ENTERF	:D		
在10年前,10日本中	Margaren en garrot	III. TYPE C	F OWNER				
☐ FEDERAL 📜		CIAL		JUL 0 5 20	113		
STATE GOVERNMENT							
_	PRIVATE			<b>'A</b>			
☐ LOCAL GOVERNMENT AF	RE TANKS LO	OCATED ON LAND WITHII		YES X NO			
LOCAL GOVERNMENT AF	RE TANKS LO	ON, DOES A NATIVE AME		YES X NO			
☐ LOCAL GOVERNMENT AF	RE TANKS LO	ON, DOES A NATIVE AME		YES X NO			
LOCAL GOVERNMENT AF IF TANKS ARE LOCATED WITHIN A F IF TANKS ARE OWNED BY A TRIBE,	RE TANKS LO RESERVATION NAME OF T	ON, DOES A NATIVE AME TRIBE: ND	RICAN TRIBE OWN TANK	YES XNO SS? YES XNO	· · · · · · · · · · · · · · · · · · ·		
LOCAL GOVERNMENT AF IF TANKS ARE LOCATED WITHIN A F IF TANKS ARE OWNED BY A TRIBE,  STATE OF TANKS AND THE TANKS A	RE TANKS LO RESERVATION NAME OF T	ON, DOES A NATIVE AME TRIBE: ND TRIBE: ND TRIBE IV. TYPE O	RICAN TRIBE OWN TANK F FACILITY	YES X NO SS? YES X NO OTHER THE STATE OF THE	PAID		
LOCAL GOVERNMENT AF IF TANKS ARE LOCATED WITHIN A F IF TANKS ARE OWNED BY A TRIBE,  PUBLIC GAS STATION PRIVATE GAS STATION	RE TANKS LO RESERVATION NAME OF T	ON, DOES A NATIVE AME TRIBE: ND INVESTIGATION IV. TYPE O LOCAL GOVERNME	F FACILITY	YES X NO  SS? YES X NO  CONTRACTOR  TRUCKING/TRANSEDS	· · · · · · · · · · · · · · · · · · ·		
LOCAL GOVERNMENT AF IF TANKS ARE LOCATED WITHIN A F IF TANKS ARE OWNED BY A TRIBE,  PUBLIC GAS STATION PRIVATE GAS STATION MARINE GAS STATION	RE TANKS LO RESERVATION NAME OF T	ON, DOES A NATIVE AME RIBE: ND LOCAL GOVERNME STATE GOVERNME FEDERAL/NON-MIL	F FACILITY  THE TOTAL THE TRANSPORT THE TRAN	YES MO  SS? YES MO  CONTRACTOR  TRUCKING/TRANSQSE  UTILITIES	PAID Remediation Division		
LOCAL GOVERNMENT AF IF TANKS ARE LOCATED WITHIN A F IF TANKS ARE OWNED BY A TRIBE,  PUBLIC GAS STATION PRIVATE GAS STATION	RE TANKS LORESERVATION NAME OF T	ON, DOES A NATIVE AME TRIBE: ND INVESTIGATION IV. TYPE O LOCAL GOVERNME	F FACILITY  THE TOTAL THE TRANSPORT THE TRAN	YES MO  SS? YES MO  CONTRACTOR  TRUCKING/TRANSQSE  UTILITIES	PAID		
LOCAL GOVERNMENT AF IF TANKS ARE LOCATED WITHIN A F IF TANKS ARE OWNED BY A TRIBE,  PUBLIC GAS STATION PRIVATE GAS STATION MARINE GAS STATION PETROLEUM DISTRIBUTOR	RE TANKS LORESERVATION NAME OF T	ON, DOES A NATIVE AME RIBE: NO LOCAL GOVERNME STATE GOVERNME FEDERAL/NON-MIL FEDERAL-MILITAR	F FACILITY  THE TOTAL THE TRANSPORT THE TRAN	YES MO  KS? YES MO  CONTRACTOR  TRUCKING/TRANSPIR  UTILITIES  RESIDENTIAL	PAID Remediation Division		
LOCAL GOVERNMENT AF IF TANKS ARE LOCATED WITHIN A F IF TANKS ARE OWNED BY A TRIBE,  PUBLIC GAS STATION PRIVATE GAS STATION MARINE GAS STATION PETROLEUM DISTRIBUTOR AIRLINE AND/OR AIRCRAFT OV	RE TANKS LORESERVATION NAME OF T	ON, DOES A NATIVE AME RIBE: NO LOCAL GOVERNME STATE GOVERNME FEDERAL/NON-MIL FEDERAL-MILITAR COMMERCIAL	F FACILITY  THE TOTAL THE TRANSPORT THE TRAN	YES MO  SS? YES MO  CONTRACTOR  TRUCKING/TRANSQSE  UTILITIES  RESIDENTIAL  FARM	PAID Remediation Division		
LOCAL GOVERNMENT AF  IF TANKS ARE LOCATED WITHIN A F  IF TANKS ARE OWNED BY A TRIBE,  PUBLIC GAS STATION  PRIVATE GAS STATION  MARINE GAS STATION  PETROLEUM DISTRIBUTOR  AIRLINE AND/OR AIRCRAFT OV  AUTO DEALERSHIP	RE TANKS LORESERVATION NAME OF THE PROPERTY OF	ON, DOES A NATIVE AME RIBE: NO LOCAL GOVERNME STATE GOVERNME FEDERAL/NON-MIL FEDERAL-MILITAR COMMERCIAL INDUSTRIAL HOSPITAL	F FACILITY  F FACILITY  ENT  ITARY	YES MO  SS? YES MO  CONTRACTOR  TRUCKING/TRANSQSE  UTILITIES  RESIDENTIAL  FARM	PAID Remediation Division JUN 1 7 2013		
LOCAL GOVERNMENT AF IF TANKS ARE LOCATED WITHIN A F IF TANKS ARE OWNED BY A TRIBE,  PUBLIC GAS STATION PRIVATE GAS STATION MARINE GAS STATION PETROLEUM DISTRIBUTOR AIRLINE AND/OR AIRCRAFT OV AUTO DEALERSHIP RAILROAD	RE TANKS LORESERVATION NAME OF THE PROPERTY OF	ON, DOES A NATIVE AME RIBE: NO LOCAL GOVERNME STATE GOVERNME FEDERAL/NON-MIL FEDERAL-MILITAR COMMERCIAL INDUSTRIAL HOSPITAL	F FACILITY  F FACILITY  ENT  ITARY	YES MO  SS? YES MO  CONTRACTOR TRUCKING/TRADISOS PRESIDENTIAL FARM OTHER (Explain)  Area Code & Phone No.	PAID Remediation Division JUN 1 7 2013		
LOCAL GOVERNMENT AF  IF TANKS ARE LOCATED WITHIN A F  IF TANKS ARE OWNED BY A TRIBE,  PUBLIC GAS STATION  PRIVATE GAS STATION  MARINE GAS STATION  PETROLEUM DISTRIBUTOR  AIRLINE AND/OR AIRCRAFT OV  AUTO DEALERSHIP  RAILROAD  Name  Daniel Daber	RE TANKS LORESERVATION NAME OF THE PROPERTY OF	DN, DOES A NATIVE AMERIBE: NO IV. TYPE O  LOCAL GOVERNME STATE GOVERNME FEDERAL/NON-MIL FEDERAL-MILITAR COMMERCIAL INDUSTRIAL HOSPITAL Job Title	F FACILITY  F FACILITY  ENT  ITARY	YES MNO SS? YES MNO CONTRACTOR TRUCKING/TRANSROF UTILITIES RESIDENTIAL FARM OTHER (Explain) Area Code & Phone No. 313 — 680 — 90	PAID Remediation Division JUN 1 7 2013		
LOCAL GOVERNMENT AF  IF TANKS ARE LOCATED WITHIN A F  IF TANKS ARE OWNED BY A TRIBE,  PUBLIC GAS STATION  PRIVATE GAS STATION  MARINE GAS STATION  PETROLEUM DISTRIBUTOR  AIRLINE AND/OR AIRCRAFT OV  AUTO DEALERSHIP  RAILROAD	RE TANKS LORESERVATION NAME OF THE PROPERTY OF	ON, DOES A NATIVE AMERIBE: NO IV. TYPE O  LOCAL GOVERNME STATE GOVERNME FEDERAL/NON-MIL FEDERAL-MILITAR COMMERCIAL INDUSTRIAL HOSPITAL V. CONTAC	F FACILITY  F FACILITY  ENT  ITARY	YES MO  SS? YES MO  CONTRACTOR TRUCKING/TRADISOS PRESIDENTIAL FARM OTHER (Explain)  Area Code & Phone No.	PAID Remediation Division JUN 1 7 2013		
LOCAL GOVERNMENT AF  IF TANKS ARE LOCATED WITHIN A F  IF TANKS ARE OWNED BY A TRIBE,  PUBLIC GAS STATION  PRIVATE GAS STATION  MARINE GAS STATION  PETROLEUM DISTRIBUTOR  AIRLINE AND/OR AIRCRAFT OV  AUTO DEALERSHIP  RAILROAD  Name  Daniel Jobey  Class A operator: Name:	RE TANKS LORESERVATION NAME OF THE PROPERTY OF	DN, DOES A NATIVE AMERIBE: NO IV. TYPE O  LOCAL GOVERNME STATE GOVERNME FEDERAL-MILITAR COMMERCIAL INDUSTRIAL HOSPITAL V. CONTAC Job Title  Company	F FACILITY  F FACILITY  ENT  ITARY	YES MNO  SS? YES MNO  CONTRACTOR TRUCKING/TRANSQOF UTILITIES RESIDENTIAL FARM OTHER (Explain)  Area Code & Phone No.  Area Code & Phone No.	PAID Remediation Division JUN 1 7 2013		
LOCAL GOVERNMENT AF  IF TANKS ARE LOCATED WITHIN A F  IF TANKS ARE OWNED BY A TRIBE,  PUBLIC GAS STATION  PRIVATE GAS STATION  MARINE GAS STATION  PETROLEUM DISTRIBUTOR  AIRLINE AND/OR AIRCRAFT OV  AUTO DEALERSHIP  RAILROAD  Name  Daniel Daber	RE TANKS LORESERVATION NAME OF THE PROPERTY OF	DN, DOES A NATIVE AMERIBE: NO IV. TYPE O  LOCAL GOVERNME STATE GOVERNME FEDERAL/NON-MIL FEDERAL-MILITAR COMMERCIAL INDUSTRIAL HOSPITAL Job Title	F FACILITY  F FACILITY  ENT  ITARY	YES MNO SS? YES MNO CONTRACTOR TRUCKING/TRANSROF UTILITIES RESIDENTIAL FARM OTHER (Explain) Area Code & Phone No. 313 — 680 — 90	PAID Remediation Division JUN 1 7 2013		
LOCAL GOVERNMENT AF  IF TANKS ARE LOCATED WITHIN A F  IF TANKS ARE OWNED BY A TRIBE,  PUBLIC GAS STATION  PRIVATE GAS STATION  MARINE GAS STATION  AIRLINE AND/OR AIRCRAFT OV  AUTO DEALERSHIP  RAILROAD  Name  Daniel  Class A operator: Name:  Class B operator: Name:	RE TANKS LORESERVATION NAME OF THE PROPERTY OF	DN, DOES A NATIVE AMERIBE: NO  LOCAL GOVERNME STATE GOVERNME FEDERAL/NON-MIL FEDERAL-MILITAR COMMERCIAL INDUSTRIAL HOSPITAL COMPANY  Company	F FACILITY  F FACILITY  INT  ITARY  Y  T PERSON	YES NO  SS? YES NO  CONTRACTOR TRUCKING/TRANSQOF UTILITIES RESIDENTIAL FARM OTHER (Explain)  Area Code & Phone No.  Area Code & Phone No.	PAID Remediation Division JUN 1 7 2013		
LOCAL GOVERNMENT AF  IF TANKS ARE LOCATED WITHIN A F  IF TANKS ARE OWNED BY A TRIBE,  PUBLIC GAS STATION  PRIVATE GAS STATION  MARINE GAS STATION  PETROLEUM DISTRIBUTOR  AIRLINE AND/OR AIRCRAFT OV  AUTO DEALERSHIP  RAILROAD  Name  Class A operator: Name:  Class B operator: Name:	RE TANKS LORESERVATION NAME OF THE PROPERTY OF	DN, DOES A NATIVE AMERIBE: NO  LOCAL GOVERNME STATE GOVERNME FEDERAL/NON-MIL FEDERAL-MILITAR COMMERCIAL INDUSTRIAL HOSPITAL Company Company VI. CERTIL	F FACILITY  F FACILITY  INT  ITARY  Y  T PERSON  CATION  ID AM FAMILIAR WITH THE	YES NO  SS? YES NO  CONTRACTOR TRUCKING/TRADISQOR UTILITIES RESIDENTIAL FARM OTHER (Explain)  Area Code & Phone No.  Area Code & Phone No.	PAID Remediation Division JUN 1 7 2013  1 40 - 05		
LOCAL GOVERNMENT AF  IF TANKS ARE LOCATED WITHIN A F  IF TANKS ARE OWNED BY A TRIBE,  PUBLIC GAS STATION  PRIVATE GAS STATION  MARINE GAS STATION  PETROLEUM DISTRIBUTOR  AIRLINE AND/OR AIRCRAFT OV  AUTO DEALERSHIP  RAILROAD  Name  Class A operator: Name:  Class B operator: Name:	RE TANKS LORESERVATION NAME OF THE PROPERTY OF	DN, DOES A NATIVE AMERIBE: NO  LOCAL GOVERNME STATE GOVERNME FEDERAL/NON-MIL FEDERAL-MILITAR COMMERCIAL INDUSTRIAL HOSPITAL Company Company VI. CERTIFERSONALLY EXAMINED AN	F FACILITY  F FACILITY  INT  ITARY  Y  T PERSON  CATION  D AM FAMILIAR WITH THE RUE, ACCURATE, AND CAME	YES NO  SS? YES NO  CONTRACTOR TRUCKING/TRADISQOR UTILITIES RESIDENTIAL FARM OTHER (Explain)  Area Code & Phone No.  Area Code & Phone No.	PAID Remediation Division JUN 1 7 2013 1 40 - 93		
LOCAL GOVERNMENT AF  IF TANKS ARE LOCATED WITHIN A F  IF TANKS ARE OWNED BY A TRIBE,  PUBLIC GAS STATION  PRIVATE GAS STATION  MARINE GAS STATION  PETROLEUM DISTRIBUTOR  AIRLINE AND/OR AIRCRAFT OV  AUTO DEALERSHIP  RAILROAD  Name  Class A operator: Name:  Class B operator: Name:	RE TANKS LORESERVATION NAME OF THE PROPERTY OF	DN, DOES A NATIVE AMERIBE: NO  LOCAL GOVERNME STATE GOVERNME FEDERAL/NON-MIL FEDERAL-MILITAR COMMERCIAL INDUSTRIAL HOSPITAL Company Company VI. CERTIFERSONALLY EXAMINED AN	F FACILITY  F FACILITY  INT  ITARY  Y  T PERSON  CATION  D AM FAMILIAR WITH THE RUE, ACCURATE, AND CAME	YES NO  SS? YES NO  CONTRACTOR TRUCKING/TRADISQOR UTILITIES RESIDENTIAL FARM OTHER (Explain)  Area Code & Phone No.  Area Code & Phone No.	PAID Remediation Division JUN 1 7 2013  1 40 - 05		
LOCAL GOVERNMENT AF  IF TANKS ARE LOCATED WITHIN A F  IF TANKS ARE OWNED BY A TRIBE,  PUBLIC GAS STATION  PRIVATE GAS STATION  MARINE GAS STATION  PETROLEUM DISTRIBUTOR  AIRLINE AND/OR AIRCRAFT OV  AUTO DEALERSHIP  RAILROAD  Name  Class A operator: Name:  Class B operator: Name:	RE TANKS LORESERVATION NAME OF THE PROPERTY OF	DN, DOES A NATIVE AMERIBE: NO  LOCAL GOVERNME STATE GOVERNME FEDERAL/NON-MIL FEDERAL-MILITAR COMMERCIAL INDUSTRIAL HOSPITAL Company Company VI. CERTIFERSONALLY EXAMINED AN	F FACILITY  F FACILITY  ITARY  T PERSON  T PERSON  T AMILIAR WITH THE RUE, ACCURATE, AND COM  /E SIGNATURE	YES NO  SS? YES NO  CONTRACTOR TRUCKING/TRADISQOR UTILITIES RESIDENTIAL FARM OTHER (Explain)  Area Code & Phone No.  Area Code & Phone No.	PAID Remediation Division  JUN 1 7 2013  1 40 - 93  THIS FORM AND ALL  DATE  5 129 13		

# Department of Licensing and Regulatory Affairs, Bureau of Fire Services, Storage Tank Division

P.O. Box 30033, Lansing, MI 48909 Phone 517-335-7211, Fax 517-332-1428



# INSTRUCTIONS FOR FORM BFS-3821, REGISTRATION OF UNDERGROUND STORAGE TANKS (UST)

### A. SUMMARY OF HOW A UST IS REGISTERED

All regulated tanks are registered by completing BFS-3821 and submitting it with a check or money order payable to the "State of Michigan" to cover the \$100 per tank registration fee. Tanks are not considered registered until fees are paid.

Mail the registration form and check or money order to: LARA, CASHIERS OFFICE - UST, P.O. Box 30657, Lansing, MI 48909-8157.

Overnight delivery: LARA, Fire Services-UST, Cashiers Office, 425 West Ottawa Street, Lansing, MI 48933.

### B. HOW DO I REPORT A RELEASE?

To report a release of product from a UST, send a FAX to 517-332-1428.

### C. WHAT LAW REQUIRES REGISTRATION OF USTs?

Part 211, Underground Storage Tank Regulations, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended, requires that owners register USTs that are being used, or have been used, to store regulated substances, unless the USTs have been properly closed or removed and notification provided to the Bureau of Fire Services, Department of Licensing and Regulatory Affairs. Owner means any person who owns, or owned at the time of release, a UST used for storage, use, or dispensing of regulated substances.

## D. WHAT USTS ARE INCLUDED?

A UST system means a tank or combination of tanks which is, was, or may have been used to contain an accumulation of "regulated substances" as defined in Section 21101(g) of Part 211, and whose volume (including connected underground piping) is ten (10) percent or more beneath the ground. Regulated substance includes petroleum and hazardous substances as defined in the federal Comprehensive Environmental Response, Compensation and Liability Act, 1980 PL 96-510.

### E. WHAT UST SYSTEMS ARE EXCLUDED FROM REGISTRATION?

- . Tanks that have been properly closed.
- 2. Farm or residential tanks of 1,100 gallons or less capacity used for storing motor fuel for non-commercial purposes.
- 3. A tank used exclusively for storing heating oil for consumptive use on the premises where the tank is located.
  - Pipeline (including gathering lines).
- 6. Surface impoundments, pits, ponds, or lagoons.
- 7. A stormwater or wastewater collection system.
- 8. Flow-through process tanks.
- Liquid traps or associated gathering lines directly related to oil or gas production and gathering operations.
- 10. Storage tanks situated in an underground area (such as a basement, cellar, mineworking, drift, shaft or tunnel) if the storage tank is situated on or above the surface of the floor.
- Any pipe connected to an exempt UST (described above).
- 12. USTs holding hazardous wastes listed under Subtitle C of the Solid Waste Disposal Act, Title II of Public Law 89-272, or a mixture of such hazardous waste and other regulated substances.
- 13. Wastewater treatment tank system that is part of a wastewater facility regulated under the federal water pollution control act.
- 14. Equipment that contains regulated substances for operational purposes such as hydraulic lift tanks and electrical equipment tanks.
- 15. USTs with a capacity of 110 gallons or less.
- 16. USTs that contain a DEMINIMUS concentration of regulated substances.
- 17. An emergency spill or overflow containment UST that is expeditiously emptied after use.

# F. WHEN SHOULD A UST BE REGISTERED?

- Owners who plan to install UST(s) shall submit to the Bureau of Fire Services (BFS), Storage Tank Division, the form NOTICE OF PROPOSED
  INSTALLATION OF UNDERGROUND STORAGE TANKS (BFS-3820), with a complete set of plans at least 45 days prior to use. When installation is
  approved, a copy of BFS-3821 will be given to the owner by the BFS Inspector. The owner completes BFS-3821 and returns it with the appropriate fees
  to the BFS as indicated on page 1 of the form. Please refer to BFS-3820 for more details.
- Owners of a new UST system shall register their UST system by submitting BFS-3821 to the Bureau of Fire Services, Storage Tank Division, before the
  system is put into operation. Owners must supply an installation date and the installer's certification must be completed and signed. A \$100 per tank fee
  is due with BFS-3821 whenever new tanks are being registered.
- Owners who discover tanks on their premises shall register the tanks by submitting BFS-3821 with \$100 per tank registration fee and shall properly close
  the tanks.
- 4. Owners who discover additional tanks at the time of a tank removal project shall register the tanks immediately and seek permission to waive the 30-day notice for removal. They may then remove the tank.
- Any change in information submitted with the registration of the UST must be reported to the Bureau of Fire Services, Storage Tank Division, on BFS-3821 within 30 days of the change.



VII. DESCRIPTION OF UNDERGROUND STORAGE TANKS.								
TANK IDENTIFICATION NUMBER	5	6		1,000				Ţ.
CURRENTLY IN USE TEMPORARILY OUT OF USE AMENDMENT OF INFORMATION (If tanks are removed/closed, complete Section VIII)	<b>1</b> 000	<b>Ø</b> 000		000	000			
2. DATE OF INSTALLATION (Month/Day/Year)								
3. ESTIMATED TOTAL CAPACITY (Gallons)								
					V. Sur			
VIII. TANKS OUT-OF-USE OR CHARLES OF THE ASSESSMENT							Section IX.)  JA	
CLOSING OF TANK     A. ESTIMATED DATE LAST USED     (Month/Day/Year)				_				
B. ESTIMATED DATE TANK WAS REMOVED/CLOSED-IN-PLACE or CHANGE-IN-SERVICE (Month/Day/Year)								
C. TANK WAS REMOVED FROM GROUND D. TANK FILLED WITH INERT								
MATERIAL (Sand, Concrete, etc.)  •DESCRIBE TYPE OF FILL USED  •REASON TANK WAS NOT REMOVED								
(Specify in comments area)								
HANGE-IN-SERVICE								
And the state of t	XI SILLIA	C. SUBSTAI	NCE STORE	ED Jijiya i				
SUBSTANCE CURRENTLY OR LAST     STORED IN GREATEST QUANTITY     BY VOLUME								
GASOLINE DIESEL GASOHOL KEROSENE (Not For Consumptive Use On Premises) FUEL OIL WASTE OIL	800000	N	000000	00000	00000	000000	000000	
USED OIL HAZARDOUS SUBSTANCE HEATING OIL MIXTURE TANK HAS COMPARTMENTS				0000				
OTHER (Specify in comments area) (List substances in comments area) CERCLA NAME AND/OR CHEMICAL ABSTRACT SERVICE (CAS) NUMBER (if hazardous ance stored)					 			
				i .		· I		

		ATION THAT IS PROVIDED IN SECTION X through 2	XIII IS TRUE TO THE	
BEST OF MY BE	LIEF AND KNOWLEDGE.		أ ار	
INSTALLER:	Ghada Beydown		5/29/13	
1	NAME PRINTED	SIGNATURE	DATE	
, .	President	_ Safeway Acquisition	<b>~</b>	
•	TITLE	O COMPANY		_

		INSTALLA	TION DETA	AL SERVICES			en migrami i and an h-filter are general are suite in language manga are suite in suite in language manga are suite in suite in language manga are suite in language in language manga are suite in language in la	B. St. Leninger. Die St. Leninger. Die Grandschaft
TANK IDENTIFICATION NUMBER								
1. MATERIAL OF CONSTRUCTION (Mark All That Apply)  ASPHALT COATED OR BARE STEEL CATHODICALLY PROTECTED STEEL EPOXY COATED STEEL COMPOSITE (Steel With Fiberglass) FIBERGLASS REINFORCED PLASTIC LINED INTERIOR DOUBLE WALLED POLYETHYLENE TANK JACKET CONCRETE EXCAVATION LINER UNKNOWN OTHER (Specify in comments area) HAS TANK BEEN REPAIRED?	00000000000000		000000000000	000000000000	00000000000	000000000000	00000000000	00000000000
2. PIPING MATERIAL (Mark Ali That Appiy)  BARE STEEL GALVANIZED STEEL FIBERGLASS REINFORCED PLASTIC COPPER CATHODICALLY PROTECTED DOUBLE WALLED FLEXIBLE PIPING ENVIROFLEX UNKNOWN	0000000000	000000000	000000000	000000000	000000000		000000000	000000000
3. PIPING (Type) (Mark All That Apply) SUCTION: NO VALVE AT TANK SUCTION: VALVE AT TANK PRESSURE (Remote) HAS PIPING BEEN REPAIRED?			0000		0000			

A CERTIFICATION OF COMPLIANCE THE TRUE TO A SECOND OF COMPLIANCE THE PROPERTY OF THE PROPERTY								
TANK IDENTIFICATION NUMBER								
INSTALLATION     A. INSTALLER CERTIFIED BY TANK     AND PIPING MANUFACTURERS     B. INSTALLATION INSPECTED BY A     REGISTERED ENGINEER     C. INSTALLATION INSPECTED AND     APPROVED BY BFS     D. ANOTHER METHOD ALLOWED BY     BFS (Please Specify)								
	XII. TANK	and PIPING	S RELEASE	DETECTION				
1. TANK RELEASE DETECTION A. MANUAL (Static) TANK GAUGING B. TANK TIGHTNESS TESTING C. INVENTORY CONTROL D. AUTOMATIC TANK GAUGING E. VAPOR MONITORING F. GROUNDWATER MONITORING G. INTERSTITIAL MONITORING DOUBLE WALLED TANK/PIPING H. INTER MONITORING/SECOND CONTAINMENT I. OTHER METHOD ALLOWED BY BFS (Specify in comments area)  PING RELEASE DETECTION AUTOMATIC LINE LEAK DETECTORS								
<ul> <li>B. INTERSTITIAL MONITORING DOUBLE WALLED PIPING</li> <li>C. INTERSTITIAL MONITORING SECOND CONTAINMENT</li> <li>D. LINE TIGHTNESS TESTING</li> <li>E. OTHER METHOD ALLOWED BY BFS (Specify in comments area)</li> </ul>	0 0 0							
a gaine data des a manor programa de la compania d a manor de la compania del compania de la compania del compania de la compania del compania	XIII. EI	NVIRONMEI	NTAL PROT	ECTION		Carlotte of Recorded Carlotte of Carlotte	graden (z. 1821) Braden (z. 1841) z Kraji in 1887 Braden (z. 1887) z Kraji in 1887 Braden (z. 1887) z Kraji in 1887 Braden (z. 1888)	HEROTO E PRESENTATION CATORIO E ROPE PAR ENTE SECURIO E PAR ENTE CATORIO E PAR ENTE
OVERFILL PROTECTION DEVICE INSTALLED	Ø	Ø		表現は見いの2.20mのである。11.40mの利益的	E E E E E E E E E E E E E E E E E E E			L SAMA STATE
2. SPILL PROTECTION DEVICE INSTALLED	Ø	Ø						
3. HAVE YOU INSTALLED IMPRESSED CURRENT CATHODIC PROTECTION? A. YES B. NO			0	0				

# COMMENTS AND/OR CLARIFICATIONS:



# STATE OF MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY LANSING



May 30, 2008

Safeway Acquisitions Group LLC 8700 Brandt Dearborn, MI 48126

Dear Owner/Operator:

SUBJECT: Nonsubmittal of Financial Responsibility (i.e. Pollution Insurance) for Underground

Storage Tanks

The Department of Environmental Quality, Waste and Hazardous Materials Division (WHMD), has not received proof of financial responsibility (FR) or the FR documentation received was inadequate for the underground storage tanks (USTs) located at Shell Service Station, 975 S Rochester, Rochester, Michigan, Facility Number 00009055.

Pursuant to Rule 61, Section 280.90, of the Michigan Underground Storage Tank Rules, 1999 AACS, R 29.2161 <u>et seq.</u>, owners/operators of petroleum USTs are required to provide proof of FR for taking corrective action and for compensating third parties for bodily injury and property damage arising from a release by petroleum USTs.

You were notified of this requirement on September 25, 2007, in your annual UST billing.

If the WHMD does not receive proof of FR within 30 days of receipt of this letter, your USTs are subject to red tagging and as such cannot be filled. Further, you may be subject to escalated enforcement action.

If you have previously submitted FR to the WHMD and are in receipt of this letter, you must resubmit. Also, be sure the correct address of where the USTs are located, which are covered under the FR mechanism, is noted on the document or as an attachment. Please include a copy of this letter with your submittal to the address below or you may fax your submittal to 517-335-2245 or email to wieberk@michigan.gov.

If you have any questions, please contact me or visit our Web site at www.michigan.gov/deq.

Sincerely.

Kevin Wieber, HMSI Specialist

Storage Tank Unit

Storage Tank and Solid Waste Section Waste and Hazardous Materials Division

517-335-7260

1	FACILITY NUMBER: UUUUUU55	0
ر.	100#.7008-01	22

INTENT OF REMOVAL, CLOSURE OR CHANGE-IN-SERVICE OF UNDERGROUND STORAGE TANKS
This information is required pursuant to Part 211, Underground Storage Tenk Regulations, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as arrended.

An owner/operator who fails to notify is subject to a misdeinsenfor and/or civil permittee, not to exceed \$5,000 per day for each bank.

INSTRUCTIONS: NOTICES WILL ONLY BE ACCEPTED ON THIS FORM. YOUR UST MUST BE REGISTERED PRIOR TO SUBMITTAL OF THIS FORM. Please type or print clearly. ALL information must be completed. See reverse side for additional information. If you have questions, call 517-335-2690, Monday through Friday between 8:00 am - 5:00 pm

information. If you have question	one, call 57/-335-25	SO, MOROSS UNO	lugn Filday between 8,00 am -				
I. OWNERS	HIP OF TANKS		II. LOCATION OF TANKS				
PLEASE CHECK IF	NEW OWNER'S ADDRE	ss	PLEASE CHECK IF SAME AS SECTION I FACILITY NAME OF COMPANY SITE IDENTIFIER				
NAME OF OWNER (CORPORATION, INDIVID			SHELL SERVICE STATION				
SAFEWAY ACQUISITIONS	GROUP, LLC		STREET ADDRESS (P O Box Not Accoptab				
STREET ADDRESS 8700 BRANDT STREET			975 S ROCHESTER				
2111	TATE ZIP CO hìgan 4812		ROCHESTER	MI 48037			
COUNTY WAYNE	Pilanwo		COUNTY	TOWNSHIP			
AREA CODE & TELEPHONE NUMBER 313-624-9911			CONTACT PERSON FOR LOCATION SAM BEYDOUN	AREA CODE & TELEPHONE NUMBER (313) 742-7981			
		TANK IN	FORMATION				
TANK NUMBER AS INDICATED	PRODUCT LAST	SIZE OF TANK		ICTION TO BE TAKEN			
ON UST INVOICE	STORED IN TANK	(GALLONS)	REMOVAL, CHANGE	IN-SERVICE, CLOSE IN PLACE			
L 2	Gasoline	10,000	CLO	SE IN PLACE			
() 3	Gasoline	6,000		<del>SE IN PLACE</del>			
(1, 5	Gasoline	10,000	10 0000157	SE-IN-PLACE			
				<u> </u>			
Comments:		<u> </u>					
Notification Submitted by (Print Nam Hussein Younes	ne)		Company American Tank, Inc.				
Signature		i.	Date	Area Code & Telephone Number			
		:	6/4/2008	(313) 945-1800			
THIS IS NOT A REGISTRA	ATION FORM. AN I	AMENDED REGI TED TANKS FRO	ISTRATION FORM, EQP3821, OM THE BILLING CYCLE	MUST BE FILED TO REMOVE THE			
		WHMD	USEONLY				
		MILIAND ADD	ROVAL NOTICE				
Approval is given to perfor	m the indicated ac	tivity at the abo	ove facility location. Action i	ndicated above may commence on			
or after 7 7 200	8,	1					
Expiration Date: 12	5/2008	If action	is not taken by the expiration	on date, you must submit another			
notification.	,		· .				
Authorizing Signature	ALIV		Date 61808				
familis Col	WW 0		Date Confirmation Mailed to Ow	mer Entry Date			
Mail White and Canary Copies To:			DSG Collintration Mallact to Out	Look			
WASTE AND HAZARDOUS DEPARTMENT OF ENVIRO			1 6118108	1 6/18/00			
P D BOX 30157	HANNEY FULL MANDERS		1, 1	1 -,			
			• • • • • • • • • • • • • • • • • • •				

Marly 6-11-08



MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY - WASTE AND HAZARDOUS MATERIALS DIVISION

## UNDERGROUND STORAGE TANK PLAN REVIEW REPORT

This information is required under Part 211, Underground Storage Tank Regulations, of the Natural Resources and Environmental Protection Act, Act 451 of the Public Acts of 1994, being Sections 324.21101 to 324.21113 of the Michigan Compiled Laws Annotated. Any owner who knowingly fails to notify or submits false information shall be subject to a misdemeanor and/or civil penalties not to exceed \$5000 per day for each tank for which notification is not given or for which false information is submitted.

PRELIMINAR	X FINAL	DATE June 06, 2008	TANK NUMBER(S) 6		FACILITY NUMBER 00009055	REFERENCE # PR-0170-08
ARCHITECT/ENGINEER	/INSTALLER		PROJECT:	Shell Service Sta	ation	
American Tank, In 10101 Ford Road Dearborn , MI 481	•		ADDRESS:	975 S Rochester Rochester, MI 4		
			COUNTY:	Oakland		

Following a review of the submitted underground storage tank installation - pre-registration information, no major deficiencies were noted.

Hazardous Materials Storage Inspector Douglas Pentzien of the Department of Environmental Quality office in SE Michigan District Office, telephone number 586-753-3847, must be notified to schedule inspections NOT LESS THAN SEVEN CALENDAR DAYS BEFORE INSTALLATION of the UST system as required in the Michigan Underground Storage Tank Rules. This installation may not be placed into service until Department of Environmental Quality personnel have conducted a final inspection, or if the inspection is not made within two working days of the scheduled installation date, excluding Saturdays, Sundays, and holidays, the UST system may be covered from sight and a notarized affidavit shall be submitted by the owner to this office attesting to the fact that the installation complies with applicable rules.

The Michigan Underground Storage Tank Rules, 1999 AACS R 29.2101 et seq., Rule 63, Section 280.93, requires owners or operators of petroleum underground storage tanks to provide evidence of financial responsibility at the time of inspection.

Provide certification of compliance with the National Electrical Code at final inspection.

If this system is not installed within one year, please contact this office for possible resubmittal of plans.

Pursuant to Part 211, Underground Storage Tank Regulations, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended (NREPA), it is the owner's responsibility that a Registration for Underground Storage Tanks (Form EQP3821) accompanied by a check for the \$100.00 per tank fee be forwarded to this office after the tank has been installed and prior to use.

This review is based upon submitted information, and is not considered a permit. Approval of a tank installation plan by the department of Environment Quality, does not relieve an owner or installer from having to meet the requirements of other state and local government laws, including zoning laws. The Hazardous Materials Storage Inspector may find additional deficiencies during site inspections.

If you have questions concerning this matter, please contact the Storage Tank Unit at (517) 335-2690 between the hours of 10:00 a.m. - 12:00 p.m. and 1:00 p.m. - 3:00 p.m.

R. Jeff Tanner, Engineer Storage Tank Unit

cc: Douglas Pentzien, DEQ



SAFEWAY ACQUISITIONS GROUP, LLC

FACILITY STREET ADDRESS (PO BOX NOT ACCEPTABLE)

FACILITY NAME

976 S ROCHESTER RD.

MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY - WASTE AND HAZARDOUS MATERIALS DIVISION P O Box 30157 Lansing, MI 48909-7657

6

# NOTICE OF PROPOSED INSTALLATION OF UNDERGROUND STORAGE TANKS

Pre-Registration for Underground Storage Tanks

This information is required under Part 211, Underground Storage Tank Regulations, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended, being Sections 324,21101 through 324,21113 of the Michigan Compiled Laws Annotated. A person who violates Part 211 or a rule promulgated under Part 211, or who knowlingly submits false information shall be subject to a misdemeaner and/or civil penalties not to exceed \$5000 per day for each tank for which notification is not given or for which false information is submitted.

Which Islas Information is submitted.

INSTRUCTIONS: This "Notice" must be completed and submitted to the Waste & Hazardous Materials Division (WHMD) a minimum of 45 days prior to Installation of the underground storage tank system. THE UST SYSTEM SHALL NOT BE BROUGHT INTO USE UNTIL A REGISTRATION FOR INSTALLATION FOR INTERPRETATION FOR EOP3821, IS COMPLETED AND SUBMITTED TO THE WHMD ALONG WITH THE \$100.00 PER TANK REGISTRATION FEE. Complete the required information in accordance with the Michigan Underground Storage Tank Rules (MUSTR), 1999 AACS R 29.2101 at seq. and the Storage and Handling of Flammable and Combustible Liquids (FL/CL) Rules, 2003 AACS R 29.5101 at seq. Parts 2 and 3 for underground installations as cited below. The manufacturer and part number must be indicated next to the appropriate Item. The item numbers correspond to the Typical Underground Storage Tank Installation diagram attached. This form is not intended to list all of the requirements that may be applicable. Mail the completed form to Waste and Hazardous Materials Division, P.O. Box 30167, Lansing, Michigan 48909-7657. Please direct any questions to the Storage Tank Unit at 517-335-7211 or e-mail DEQ-STD-TANKS@michigan.gov. FACILITY NUMBER NEW ASSIGNED TANK NUMBER(S)

CONTACT PERSON (AT LOCATION)

	TOCHESTER TO		COUNTY			STATE	ZIP CODE		
CITY			WAYNE	ma W	Sand	Mi	48037		
	ESTER		STREET ADD	DESE.	NICKAN CV		AREA CODE & TELEPHONE NUMBER		
	ER'S NAME			10101 Ford Rd. (313) 945-1800					
AMER	ICAN TANK, INC.		1	70 000					
CITY			STATE MICHIGA	N.			48126		
DEAR	BORN		MICHIGA	TEM					
Item		MANUFACTURER & PAI	DT NO	NO.	DESCRIPTIO	N	MANUFACTURER & PART NO.		
No.	DESCRIPTION	1-8,000, 126" split 4/4 tan	k to			1	f necessary per the manufacturers		
1.	TANK DESIGN AND	contain gas & diesel All t	ha tanks	5,	ANCHORING OF Section 2.3.3.5 of	TANK:   . ] FL/Ci   J	ecommendations		
	CONSTRUCTION:	will be double wall perma	tanke	l	Part 2. In areas su	bject			
	Section 280.20(a). 280.20(d), 280.32 &		THING	[ [	to flooding or high table. NOTE: Tie-	water			
	Section 2.2 of FLICI.	from the Clawson Tank	•		Straps.	COOPER _			
	Part 2. Concrete:	Company.	<b></b>	i i		-			
	Steel- UL58; Fihamians - UL 1315.			1		] -			
	Compsion protection -			1		1.			
ĺ	ACT 100. Dimension, Capacity & Contents.								
<b></b>	Capacity & Darison			-	CORROSION	1.	N/A		
2.	BURIAL DEPTH	Minimum 36" with 8" con	icrete.	6,	PROTECTION FO	OR .			
1	COVER: Section 2.3.3.2 of	MINIMAN SO WHEN AND		ŀ	TANK:	_			
	FLICL Part 2.			}	Section 280.20(a) & Section 2.2.6.1 of FLICL				
1	Minimum 2' or 1' earth			1	Part 2 Fiberoissa	tanks.			
L	& 4° neinforced			1	steel tanks with compo	athodic			
	vehicular traffic.			1	i themsenous comba				
1	Minimum 3' or 16" earth & 6" concrete or			1	acceptable.	1			
1	8 sental with			<b></b>	<u> </u>	<del></del> -}-	N/A		
<b>—</b>		Pea Stone		7.	MONITORING O	r	N/A		
3.	BACKFILL	ì <del></del>			CATHODIC	ļ			
1	SURROUNDING			}	PROTECTION: Section 280.31.	Test			
1	TANK:			1	station wires to g	בחשמון			
-	Section 2.3.3.2 of FL/CL Part 2.			1	surface for acces	u,			
l l	Minimum 6° sand or	\		1	ì	]			
1	nes graval-steet:			1	}	Ì			
1	minimum 12 pea gravel fiberulass.			<del></del> -	<del> </del>		APT Double Wall		
		See Attached Site Plan		8.	PIPING MATER		XP1.755SC.		
4.	TANK LOCATION: Section 280,20(d) &			1	Section 280-20() 280-20(d), 280-3	b), 1	W. 11151001		
1	Becking 2 9.3.1 of			ļ	Section 3-3 of F	UCL			
1	FLICL Part 2, 10' from basement wall, pit or			Ī	Part 2. Single 0	r double-			
1	omperty line; also to			1	unilled steel, fiber	marevial.			
Į.	surved (ASCIS			1	Metallic giping 9	inalibe .			
	transmitted by building foundation-tank			1	cathodically pro- and dialectricall	tect60 v kolehod			
1	outside 45 degrae				SIM DIGIESGINES	,			
1	angle.			<u> </u>	<u> </u>				

\*Please Note-#8 Revised

00009055

(313) 624-9911

AREA CODE & TELEPHONE NUMBER

EQP3820 (REV 8/2003)

Page 1 of 3

# NOTICE OF PROPOSED INSTALLATION OF UNDERGROUND STORAGE TANKS (continued)

Pre-Registration for Underground Storage Tanks

Item No.	DESCRIPTION	MANUFACTURER & PART NO.	NO.	DESCRIPTION	MANUFACTURER & PART NO.
9.	CORROSION PROTECTION FOR PIPING: Section 280.20(b). Metallic piping (including flexible connectors) requires cathodic protection; and dielectric couplings at tank and dispenser to isolate the piping.	Non-Metallic	15.	OVERFILL PROTECTION: Section 280.20(c) (1) (ii). Audible elemm or tlow restricted when tank is 80% full, or an automatic shutoff of flow into the tank when the tank is 95% tull.	OPW 61 & OPW SOC
10.	RELEASE DETECTION FOR TANK & PIPING: Section 280.40(e), Section 280.41 & Section 280.42. Must be able to detect a release from any portion of the tank and piping.	Model No. 10847390-107  Model No. 10847390-107  Monitor No. 10847390-107	16.	SPILL PROTECTION AROUND FILL PIPE: Section 280.20(c), Equipment to prevent release of product to the environment when the transfer hase is detached from the fill pipe. Sealed to prevent entry of product into the ground.	OPW No. 1
11.	VENT PIPING: Section 2.3.3.3 of FLICL Part 2. Steel above ground; cutlet above snow level, minimum 12 feet above grade, and 3 feet above roof line.	12" Steel above grade FRP below grade	17.	AREA BENEATH & AROUND DISPENSER: Section 6.3.4, Section 9.2 of FL/CL Pert 3. Prevent leaks and splits from resching groundweter, surface water, and subsurface soits.	Dispenser containment sump
12.	EMERGENCY SHEAR/FIRE VALVE: Section 6.3.9 and 6.3.10 of FL/CL Part 3. Required on submerged pumping systems, rigidly anchored. Sucilon systems require check valve or pressure regulating valve under the dispenser.	OPW10R	18.	PROTECTION AGAINST COLLISION: Section 6.3.4 of FUCL Part 3, Raised concrete island or cresh posts. NOTE: Local ordinances may be more stringent.	
13.	EMERGENCY BREAKAWAY DEVICE: Section 6.5.2 of FLICL Part 3, Installed on each hose that dispenses a liquid. Designed to ratain liquid on both sides of the breakaway point.	OPW66	19.	DISPENSING DEVICE AND NOZZLE: Section 6.8 of FL/CL Part 3, Must be listed and identified as to product it dispenses, Splaxh guard required on nozzle.	OPW 11B/ Wayne Dispenser 590.
14.	LOCATION OF DISPENSER: Section 6.2.1, 8.3.4, 6.3.5 & 9-4 of FL/CL Part 3. 10' from property lines, combustible building walls, and building openings. In clear view of attendant. Within 100' of emergency shutoff switch for self- sarve.		20.	HOLD OPEN DEVICE ON NOZZLE: Section 6.6 of FL/CL Part 3. Allowed. Self-service Heeds special feature of nozzia that prevents resumption of flow once pump is stopped.	OPW IIB

A plot plan showing structures, roads, railroads, property lines, and easements within 25 feet of the UST system. Section 280.22 - attach to this form. The location of all applicable drinking water wells and surface water intakes within 2000 feet of the UST system. Section 280.22 - attach to this form. 21.

22. A diagram of the UST system. Section 280 22 - attach to this form.

EQP3820 (REV 8/2003)



# STATE OF MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY WASTE AND HAZARDOUS MATERIALS DIVISION

# FACILITY INSPECTION REPORT

Owner Name & Address:

Safeway Acquisitions Group LLC 8700 Brandt Dearborn, MI 48126

Location of Tanks:

KLIN MAR D , TOW MNR Oil Inc. 975 S Rochester Rochester, MI 48037 County - Oakland Facility ID - 00009055

ATTENTION: Safeway Acquisitions Group LLC

An Existing Facility Inspection was conducted on February 22, 2007, at the above-subject facility for compliance with Part 211, Underground Storage Tank Regulations, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended (Act 451), the Michigan Underground Storage Tank Rules (MUSTR), 1999 AACS R 29,2101 et seg. and the applicable sections of the rules for the Storage and Handling of Flammable and Combustible Liquids, 2003 AACS R 29,5101 et seg. The inspection showed that the facility is disapproved.

1 Registration shall be submitted within 30 days of tank or owner status change. UST 280.22(A)

Special Attention: Register tanks in new owners name. Form left on site and will be picked up in 2 days.

2 Owner shall display proof of valid registration certificate at the facility. UST 280.22(H)

Special Attention: Display when new one is sent.

3 Dispenser shall be in clear view of attendant and be able to communicate. UST 280.10(J) (FL/CL Part3, Section 9.4.5)

Special Attention: Install intercom.

4 An emergency shutoff valve with a fusible link shall be manually tested annually. UST 280.10(J) (FL/CL Part 3, Section 6.3.9.1)

Special Attention: Perform or submit yearly required tests.

5 Dispenser violation. UST 280.10 (J) (FL/CL Part 3, Section 6.1)

Special Attention: Section 3.1.1 Replace badly cracked hose on #4, #5, #8 pumps.

6 Each dispensing nozzle shall be equipped with a device to prevent splashing of liquid during the dispensing operation. UST 280.10 (J) (FL/CL Part 3, Section 6.6.6)

Special Attention: Replace splash guard on #3, #6 pumps.

EQP 3816e (Rev. 04/2002)

7 Following signage required in all dispensing areas: "No Smoking" "Stop Motor" "Unlawful to Dispense Gasoline into an Unapproved Container". UST 280.10 (J) (FL/CL Part 3, Section 9.2.5.4)

Special Attention: Install proper signage at pumps 1/2 and 3/4...

8 Signage required in dispensing areas: "Person shall remain outside their vehicle in view of nozzle"

UST 280.10 (J) (FL/CL Part 3, Section 9.2.5.4)

Special Attention: Install proper signage at pumps 1/2 and 3/4...

9 Miscellaneous Violations UST 280.10 (J) (FL/CL RULES)

Special Attention: Section 280.21(3)(b)(1)(i)
Submit tank lining certificates to prove when the tanks need their 10 year internal inspection or the 10 year internal tank inspection will be required now. If a 10 year internal inspection has been performed submit this also.

The inspection and violations (if any) were discussed with Ahmed Elbeeb at the time of the inspection.

Documentation shall be furnished to the district office identified below verifying that the violation(s), cited in this inspection report have been corrected. The documentation shall be provided by April 23, 2007. If the cited violation(s) are not corrected and/or certification of compliance is not provided by the date specified, a reinspection will be conducted. The owner or operator of this facility will be subject to civil and criminal provisions pursuant to Part 211 of Act 451, including and not limited to placement of tags to the tank(s) prohibiting delivery of product if the stated violations have not been corrected.

If you have additional questions concerning this matter, please contact me.

Douglas Kutzura

Hazardous Materials Storage Inspector

SE Michigan District Office

27700 Donald Court

Warren, MI 48092-2793 Phone: (586) 753-3843

Fax: (586) 753-3831

Date

# DEQ MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY - WASTE AND HAZARDOUS MATERIALS DIVISION AUTOMOTIVE SERVICE STATION CHECKLIST The Hazardous Metallale States a Inspector shall complete this checklist and attach it to an inspection report, one to be retained in the

	PERSON ON SITE:	e o	ione #	سسند م <i>دووس</i>		سيء بي	42	FACILITY TYPE Public I Priva			
	hmad Ellead		y 15	<u>රැයි *</u> ERATIO		CTION	70	Public 1/ ( iiva	162		
SECTION	<i></i>	CODE		PASS	<u>Si</u>	ECTION	1 1511	of of an eletrotics	CODE	VIO I	PAS
<b>6.</b> 7	Emergency power disconnect	\$93		1/	1 . L	280,22h		y proof of registration	\$63	1	1
9.2.5.2	Fire extinguisher, 100 feet	\$59	<u> </u>	1/	J [_	280.22a	_	ration submitted 30 days	S62	سنا	\$
9.4.5	Dispenser in view and communicate	\$92	1	1	سار ل	280.22a		ty registered & fees paid	\$61 U70	1	7
280.93	Financial Responsibility	U92	<u> </u>	1	T <u>L</u> '	3.2.1	Electric	aneous violation	\$50	丰	丰
	•	•		PEC	DRDS	<del></del>	iviisceii	allebus violatori	1 330	<u> </u>	1_
280.34	Maintenance records	1 865	)	1120		280.34	Relea	se det records (2yrs & 5 yrs)	S67	T-	٦.
280.44a	Line leak detector tested	U95	╁			280.315		sted 6 months & 3 years	U30	+	+
	Line tightness test - pressure	U88	<del></del>	1	. [_	280.31c		ssed current, 60 day log	S35	+	╁
280.41b(1)	Line test - suction every 3 years	U89	-	1		280.34	1 1	dic protection records*	564	<del> </del> -	╁
280.41b	Emergency valve tested	\$94	<del>                                     </del>	NA		NOTE-		es CP upgrade testing results		ــــــــــــــــــــــــــــــــــــــ	
3.9.1.	Gen. Record Keeping Violation	S60	10	<del>  </del>	L						
280.34	Gelf Kerold Keehing Aloistich	1 000	RELE	LASE D	ETEC	TION					
280.40	Release detection for tanks	U71	T	1. 7	/	80.43e	Vapor	monitoring (approval req.)	U73	11	T
80.43a	Inventory control (not stand alone)	S42	<del>}</del>	1	ノ <u> </u> -	80.43f	1	lwater monit. (Stand alone)	U74	#	#
80.43b	Manual gauging (less then 550)	S43	-		. ட	80.43g	į.	ial monitoring (Stand alone)	U75 /	#	H
	Tank tightness testing	544	<u> </u> .	NA	<u> </u>	80,43h	1	(Stand alone)	U93//	1-/	1
80,430	<u> </u>	U72	-			80.43h	Other	(0.11.1-1.1-1.1-1.1-1.1-1.1-1.1-1.1-1.1-1	549		+/
80.43d	Automatic tank gauging	0/2	Dieb	ENSER	1		0		1 - 7	<u> </u>	L.
.1	Dispenser violation	\$10				5.2.	Breaka	way on hose	S15	Γ	Te
.2.3.	Dispenser loc. (10' prop & openings)	S11	1	1	6.	3.4.1.	Contair	ment under dispenser	.817		1
.3.4.	Disp. Protected; damage/secured	S13		V	6.	3.9.	Emerge	ency valve installed	S18		1
5.1.	Dispenser hose 18 feet or less	1 514		-	- 6.	1.1.	Automa	tic self-closing nozzle	S19		L
6.6.	Splash guard on nozzle	S91				4.4.	Operati	ng instructions posted	S25		1,
2,5,4,	No smoking, stop motor, container	S22			6.	3.3.	1	es only with handle removed	S12		1
2.5.4.	Remain out of vehicle in view	S23			6.	3,5.		Disp. 20 feet from fuel oil	• поле		N
	Trende in view	1	ERGRO	T CIVIC	l _	SECTIO	<u> </u>			<u></u>	900
IO.20	Tank misc. violation	S30		2		3.3.4.	Locatio	n of fill pipe & identified	U46		L
O.20s	Spill containment - Testing request	U51	1		3.	7.2.1.	Vent pi	oes, 12 feet Class 1 liquid	U32		1
O.20c	Spill containment - Inoperative	U101			3.	7.2.4.	Vent pi	oes, Class II & IIIA	U33		L
3.3.4,3,	Tight fitting hose conn (1,000 & up)	U44	<del> `</del>		2.	3.3.4.	Drop tu	be: 6 inches of tank bottom	U45		Î
,	Overfill prevention - Testing request	U52	$\vdash$	-	2.	2.3.1	Tanks F	Proper design & Construction	U12		V
	Overfill Prevention - Inoperative	U102			28	0.20	Cathodi	c protection for tanks	U29	7	
			PIP	NG SE	CTIO	1					_
0.40	Release detection for piping	U71			280	).44c		al.(monthly) monitoring	U94		PP.
D.44a	Line leak detector installed	U76		V	3.2	.2.	Pipe leal		U62		v
0.20	Cathodic protection for piping	U29			280	205	Piping st	nall be approved material	U61		V
c Canatalati	ion & OTO O Dining	Material	A.	Do.	M	7 }	Has	GPS readings been taken	Nes	:	
< Constructi			-	6	Ι.	<u> </u>	_	or Model <u>7 25' 352</u>	5//	1	
ng; Suction	Pressure Sump S	ensors: Y	es	_ No	1	اa. س	nk ivionit e-	or Moner 7 23 000	V-200	TEXA	<u> </u>
MENTS:	#16 Splenk 3			Tra	د میرو	<u>e Coa</u>	da,	internal			
2	May #5 48			K.	<u> </u>	nogia	ليا ك	and the same			
	1-2 3-4 Lin	1		0		o		U			



# STATE OF MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY WASTE AND HAZARDOUS MATERIALS DIVISION

# **FACILITY INSPECTION REPORT**

Owner Name & Address:

Safeway Acquisitions Group LLC 8700 Brandt Dearborn, MI 48126 Location of Tanks:

OCT 1 7 2007

Shell Service Station N 975 S Rochester Rochester, MI 48037 County - Oakland Facility ID - 00009055

ATTENTION: Safeway Acquisitions Group LLC

A Site Investigation was conducted on October 3, 2007, for the above-referenced facility for compliance with Part 211, Underground Storage Tank Regulations, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended (Act 451); the Michigan Underground Storage Tank Rules (MUSTR), 1999 AACS R 29.2101 et seq.; and the applicable sections of the rules for the Storage and Handling of Flammable and Combustible Liquids, 2003 AACS R 29.5101 et seq. The inspection showed that the tank(s) was tagged.

If you have additional questions concerning this matter, please contact me.

Douglas Pentzien

Hazardous Materials Storage Inspector

SE Michigan District Office

27700 Donald Court

Warren, MI 48092-2793

Phone: 586-753-3847

Fax: 586-753-3831

Email:

Date



# STATE OF MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY WASTE AND HAZARDOUS MATERIALS DIVISION

# **FACILITY INSPECTION REPORT**

Owner Name & Address:

Safeway Acquisitions Group LLC 8700 Brandt Dearborn, MI 48126 Location of Tanks:

Shell Service Station 975 S Rochester Rochester, MI 48037 County - Oakland Facility ID - 00009055

KIN AUG 30 2007

ATTENTION: Safeway Acquisitions Group LLC

A Reinspection was conducted on August 17, 2007, for the above-referenced facility for compliance with Part 211, Underground Storage Tank Regulations, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended (Act 451); the Michigan Underground Storage Tank Rules (MUSTR), 1999 AACS R 29.2101 et seq.; and the applicable sections of the rules for the Storage and Handling of Flammable and Combustible Liquids, 2003 AACS R 29.5101 et seq. The inspection showed that the tank(s) was de-tagged.

1 Miscellaneous Violations UST 280.10 (J) (FL/CL RULES)

Special Attention: Section 280.21(3)(b)(1)(i)

Perform internal inspections on 2 lined tanks as discussed.

Tanks will be red-tagged if internal inspections are not completed by September 14, 2007

The inspection and violations (if any) were discussed with Sam Beydoun at the time of the inspection.

Documentation shall be furnished to the district office identified below verifying that the violation(s), cited in this inspection report have been corrected. The documentation shall be provided by September 14, 2007. If the cited violation(s) are not corrected and/or certification of compliance is not provided by the date specified, a reinspection will be conducted. The owner or operator of this facility will be subject to civil and criminal provisions pursuant to Part 211 of Act 451, including and not limited to placement of tags to the tank(s) prohibiting delivery of product if the stated violations have not been corrected.

If you have additional questions concerning this matter, please contact me.

Douglas Kutzura

Hazardous Materials Storage Inspector

SE Michigan District Office

27700 Donald Court

Warren, MI 48092-2793

Phone: 586-753-3843 Fax: 586-753-3831

Email: kutzurad@michigan.gov

Date



# EMK JUL 1 3 2020.

June 8, 2005

Kevin Wieber HMSI Specialist Waste and Hazardous Materials Division State of Michigan Department of Environmental Quality 525 West Allegan Street Lansing, MI 48909-7741

Dear Mr. Wieber:

The following Shell facilities, including underground storage tanks (UST), have been sold to the parties indicated below. Shell Oil Product US is not the Owner or Operator of the USTs at these locations.

# 3015 CROOKS, TROY, MI:

Sold to Big Beaver and Crooks Limited, LLC, 2989 Crooks Rd, Troy, MI 48084

Attn: Jon Sherer. Date sold: 5/17/05.

# 2600 EAST JEFFERSON, DETROIT, MI:

Sold to Dannaoui Brothers Enterprises, LLC; Ghassan Dannaoui, 2600 E. Jefferson, Detroit, Ml. Date sold: 2/11/05.

# 39621 ANN ARBOR RD., PLYMOUTH, MI:

Sold to Faisal & Sons Investments, Inc., Faisal Y. Daoud, 39621 Ann Arbor, Plymouth, MI 48170. Date sold: 12/16/04.

The following sites were sold to Safeway Acquisition Company, LLC, Attn: Kassem Beydoun, President, 8700 Brandt, Dearborn, MI 48126. Date sold: 3/31/05.

3240 WASHTENAW ANN ARBOR
1800 PLYMOUTH ANN ARBOR
2500 JACKSON RD ANN ARBOR
3690 MAPLE BLOOMFIELD HILLS
24932 VAN DYKE CENTER LINE
16850 CANAL RD CLINTON TOWNSHIP
20800 GRATIOT EASTPOINTE
5624 TELEGRAPH RD DEARBORN HEIGHTS
18701 MACK DETROIT
3600 E DAVISON DETROIT
31324 W 10 MI RD FARMINGTON
39200 GRAND RIVER FARMINGTON HILLS
37500 12 MILE RD FARMINGTON HILLS

JUL 1 2 2005





17500 MACK GROSSE POINTE 36420 PLYMOUTH LIVONIA 1849 E 11 MILE MADISON HEIGHTS 15450 W 9 MILE OAK PARK 205 N. OPDYKE PONTIAC 975 S ROCHESTER ROCHESTER HILLS 2980 WALTON ROCHESTER HILLS 2260 CROOKS ROCHESTER HILLS 32961 GRATIOT ROSEVILLE 19617 10 MILE ROAD ROSEVILLE 735 S MAIN ROYAL OAK 51015 VAN DYKE SHELBY TOWNSHIP 25826 SOUTHFLD/10 1/2 MI SOUTHFIELD 22222 GREATER MACK AVE SAINT CLAIR SHORES 40375 UTICA STERLING HEIGHTS 3990 ROCHESTER TROY 2039 E BIG BEAVER TROY 11229 HALL UTICA 3950 E 10 MILE WARREN 28851 HOOVER WARREN 13610 E 13 MI WARREN 6495 ORCHARD LK WEST BLOOMFIELD 28055 S WIXOM ROAD WIXOM

If you need additional information please let me know.

Sincerely,

Theresa Geijer

**HSSE** Compliance Coordinator Shell Oil Products US - Chicago 603 East Diehl Road, Suite 103

Naperville, IL 60563

630-364-9274



# STATE OF MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY LANSING



June 11, 2003

Shell Oil Products US 603 E Diehl Rd Suite 103 Naperville, IL 60563

Dear Owner/Operator:

SUBJECT: Nonsubmittal of Financial Responsibility (i.e. Pollution Insurance) for

**Underground Storage Tanks** 

The Department of Environmental Quality, Waste and Hazardous Materials Division (WHMD), has not received proof of financial responsibility (FR) for the underground storage tanks (USTs) located at Shell Service Station, 975 S Rochester/Avon, Rochester, Michigan, Facility Number 00009055.

Pursuant to Rule 61, Section 280.90, of the Michigan Underground Storage Tank Rules, 1999 AACS, R 29.2161 et seq., owners/operators of petroleum USTs are required to provide proof of FR for taking corrective action and for compensating third parties for bodily injury and property damage arising from a release by petroleum USTs.

You were notified of this requirement on January 6, 2003, in your annual UST billing.

If the WHMD does not receive proof of FR within 30 days of receipt of this letter, your USTs are subject to red tagging and as such cannot be filled. Further, you may be subject to escalated enforcement action.

If you have previously submitted FR to the WHMD and are in receipt of this letter, you must resubmit. Also, be sure the location(s) covered under the FR mechanism are noted on the document or as an attachment. Please include a copy of this letter with your submittal to the address below or you may fax your submittal to the number listed below.

If you have any questions, please contact me or visit our website at www.michigan.gov/deq.

Sincerely,

Kevin Wieber, HMSI Specialist

Waste and Hazardous Materials Division

517-335-7260

FAX: 517-335-2245

UNDERGROUND STORAGE TANK DIVISION DNRS MICHIGAN DEPARTMENT OF NATURAL RESOURCES O BOX 30157 ANSING MI 48909-7657

SEE ABOVE

# REGISTRATION FOR UNDERGROUND STORAGE TANKS

This information is required under 1994 PA 451. Any owner who knowingly falls to notify or submits false information shall be subject to a misdemeanor and/or civil penalties not to exceed \$5,000 per day (or each tank for which notification is not given or for which false information is submitted.

CONSIDERED REGISTERED UI	NTIL THE ONR. US ADE PAYABLE TO	T DIVISION F THE "STATE (	ias received yo of michigan". Th	E ADDRESS, NEW TANKS ARE NOT DUR COMPLETED FORM AND A IE ANNUAL REGISTRATION FEE FOR
TYPE OF NOTIFICATION: INEW REGISTRA	TION IN AME	NDED INFO.	FACILITY NUMBER	(II known)
NO. OF TANKS AT FACILITY NO. OF CONTINUATION SHEETS ATTACHE		9-25-98	000	1
I. OWNERSHIP OF TANKS			II. LOCAT	TON OF TANKS
IF THIS IS A NEW OWNER'S ADDRESS, PLEAS	SE CHECK (T)	IF INFO	RMATION SAME A	S SECTION I. PLEASE CHECK
OWNER NAME (Corporation/individual, ele.)			E OR SITE IDENTIFIE	
EQUILON ENTERPRISE		SHE	LESS (P.O. BOX NOI A	ICE STATION
17370 LAUREL PK N.	#200	975	ROCHEST	ER /AUDIV -
LIVONIA STATE	48152	CITY ROCK	4ESTER	STATUL 1248307
COUNTY WAYNE TOWNSHIP -	_	COUNTY	AKLAND	TOWNSHIP
TELEPHONE (Including Area Gode)		TELEPHONE (	Including Area Code) 656-00	80 9
TAX P				SEP CO
		·	IV. INDIAN L	ANDS COLUMN
☐ FEDERAL GOVERNMENT ☐ COMMERCIAL ☐ STATE GOVERNMENT ☐ PRIVATE ☐ LOCAL GOVERNMENT	OTHER INC	ian trust i Cowned by	Ands.	IN INDIAN RESERVATION OR ON N NATION: TRIBE: OR INDIVIDUAL
	V. TYPE OF	FACILITY	· · · · · · · · · · · · · · · · · · ·	
☑ GAS STATION	LOCAL GOVERN		*	CONTRACTOR
<del>-</del>	] STATE GOVERN			☐ TRUCKING/TRANSPORT
	FEDERALINON-A			□ υπυπεs
	T FEDERAL-MILITA			☐ RESIDENTIAL
_ <del>_</del>	COMMERCIAL			C FARM
	INDUSTRIAL			OTHER (Explain)
VI.	CONTACT PERS	ON FOR LO	CATION	
JEROME P. CAVALUZZI	HEALTH SAI	ETYEN	V. ANALYS	TELEPHONE (Including Area Code)
	/II. FINANCIAL F	ESPONSIBI	LITY	
I HAVE MET THE FINANCIAL RESPONSIBILITY R	EQUIREMENTS AS	REQUIRED	IN THE UST RULE	S 🔂 (Check All Herns Selow That Apply)
_	] GUARANTEE			MUSTFA FUND
<b>—</b> · · · · · · · · · · · · · · · · ·	מאספ צופאנט.[			TRUST FUND
<del></del>	LETTER OF CAE	דום		OTHER METHOD ALLOWED
FOR INFORMATION ABOUT MUSTFA ELIGIBILITY CALL	1-800-468-7832	<u>-</u>	<u> </u>	
	VIIL CERT			
I CERTIFY UNDER PENALTY OF LAW THAT I HAVE THIS AND ALL ATTACHED DOCUMENTS, AND THA OBTAINING THE INFORMATION. I BELIEVE THAT I	T Based on My 11	NOUIRY OF T	HOSE INDIVIDUAL	s immediately responsible for
NAME AND OFFICIAL TITLE OF OWNER OR OWNERS"	SIGNATURE	A	/1	DATE 21 98

IX. DESCRIPTION OF UNDER	GROUND	STORAGE	TANKS (C	omplete Fo	r Each Tai	nk At This	Location	
TANK IDENTIFICATION NUMBER	# 5 1	- 2	. 3	<del>#</del>	<b>‡</b>	<del>3</del> 1	<u></u>	*
1. STATUS OF TANKS (Check One)  CURRENTLY IN USE  TEMPORARILY OUT OF USE **  AMENDMENT OF INFORMATION  "Also Contenue Section X	DICH .	DOO		מממ	טפט		000	000
(If tance are removemental, common page 1, Section XI	5/46	12/72	12 72			1	· · · · · · · · · · · · · · · · · · ·	
2. CATE OF INSTALLATION  3. ESTIMATED TOTAL CAPACITY (Gailons)	TOM	IOM	GM					
4. MATERIAL OF CONSTRUCTION (Mark All That Apply) ASPHALT COATED OR BARE STEEL CATHODICALLY PROTECTED STEEL EPOXY COATED STEEL COMPOSITE (Steel With Fiberglass) FIBERGLASS REINFORCED PLASTIC LINED INTERIOR DOUBLE WALLED POLYETHYLENE TANK JACKET CONCRETE EXCAVATION LINER UNKNOWN OTHER (Please Specify)		00000000000	proopaooo	apapapapap	موموموموم	00000000000	ممعممهمه	00000000000
HAS TANK BEEN REPAIRED?								
5. PIPING MATERIAL (Mark All That Apply)  BARE STEEL  GALVANIZED STEEL  FIBERGLASS REINFORCED PLASTIC  COPPER  CATHODICALLY PROTECTED  OCUBLE WALLED  SECONDARY CONTAINMENT  UNKNOWN  OTHER (Please Specify)	00000000	ممحممومه		0000000	00000000		00000000	
6. PIPING (Type) (Mark All That Apply) SUCTION: NO VALVE AT TANK SUCTION: VALVE AT TANK PRESSURE (Remote) PRESSURE (Gravity Fed) HAS PIPING BEEN REPAIRED?	00000	00000	00800	00000	0000	00000	0000	, bbaaa
7. SUBSTANCE CURRENTLY OR LAST STORED IN GREATEST QUANTITY BY VOLUME GASOLINE DIESEL GASOHOL KEROSENE (New For Communities Use On Processor FUEL OIL USED OIL OTHER (Please Specify)	000000	อออออส	00000	aaaaaa	00000	aaaaaa	apaaaa	aaaaaa
HAZARDOUS SUBSTANCE COMPREHENSIVE ENVIRONMENTAL RESPONSE COMPENSATION & LIABILITY ACT (CERCLA) NAME AND/OR CHEMICAL ABSTRACT SERVICE (CAS) NUMBER	200	AL A	e alu	o ve	0			

	V T/	MINC	<u> </u>	ae uc	6 0	2 044	MAGE	124 40		752						
TANK IDENTIFICATION NUMBER	X. 14	INKS (	201	OF US	E U!	1 UHA	1400	114.2	I#		#		#		*	
1. CLOSING OF TANK							<u> </u>		1					········	1	
A. ESTIMATED DATE LAST USED (Month/Day/Year)	-		-   -	<del></del>	.		-		-   -		-   -		-   -		-   -	
B. ESTIMATED DATE TANK REMOVED CLOSED IN PLACE (Month/Day/Year							-		.		-   -		-		-   _	
C. TANK WAS REMOVED FROM GROUND D. TANK FILLED WITH INERT	)		٠							0				0	7	0
MATERIAL (Sand, Concrete, etc.)  DESCRIBE TYPE OF FILL USED  AND REASON TANK WAS NOT  REMOVED	-															
E. CHANGE IN SERVICE																
REMINDER: A SITE ASSES	SMEN	T MUS	TBE	COMP	ETE	D, UNL	ESS	YOU F	EPOF	TAC	ONFI	RMED	RELE	ASE		
XI. CERTIFICATION OF CO	MPL	ANCE	(Cor	npiete	For	All Ne	w Ai	nd Up	grade	ed Ta	nks A	t Thi	s Loc	ation	)	
1. INSTALLATION A. INSTALLER CERTIFIED BY TANK		-		_		<b>-</b>		<b></b>		<b>a</b>		<b>3</b>				
AND PIPING MANUFACTURERS B. INSTALLER CERTIFIED OR				_		<u> </u>	1	<u> </u>						_		
LICENSED BY THE UST DIVISION  C. INSTALLATION INSPECTED BY A  REGISTERED ENGINEER		<u> </u>				<u> </u>	1			_ _					}	
D. INSTALLATION INSPECTED AND APPROVED BY UST DIVISION					í											
E. ANOTHER METHOD ALLOWED BY UST DIVISION (Please Specify)			_							<del></del>		<u>-</u>	<u> </u>		_	
2. RELEASE DETECTION	TANI	K PIPE	TANK	PIPE	TANK	PIPE		PIPE		PIPE		PIPE		PPE		PIP
A. MANHAL (SMIC) TANK GAUGING B. TANK TIGHTNESS TESTING																
C. INVENTORY CONTROL			3		3			j					١ŏ			
D. AUTOMATIC TANK GAUGING	v		<b>T</b>		ਹੈ/					{				_		_
E. VAPOR MONITORING																
F. GROUNDWATER MONITORING				1 1											l ~	
	1 -			=												] _
G. INTERSTITIAL MONITORING DOUBLE WALLED TANKPIPING									ſ			_	•		0 0	
G. INTERSTITIAL MONITORING DOUBLE WALLED TANKPIPING H. INTERSTITIAL MONITORING				G												
G. INTERSTITIAL MONITORING DOUBLE WALLED TANK/PIPING H. INTERSTITIAL MONITORING SECONDARY CONTAINMENT	-													0 0		
G. INTERSTITIAL MONITORING DOUBLE WALLED TANKPIPING H. INTERSTITIAL MONITORING SECONDARY CONTAINMENT I. AUTOMATIC LINE LEAK DETECTORS				G												
G. INTERSTITIAL MONITORING DOUBLE WALLED TANKPIPING H. INTERSTITIAL MONITORING SECONDARY CONTAINMENT I. AUTOMATIC LINE LEAK DETECTORS J. LINE TIGHTNESS TESTING K. OTHER METHOD ALLOWED BY														áa o o		0 0 0
G. INTERSTITIAL MONITORING DOUBLE WALLED TANKPIPING H. INTERSTITIAL MONITORING SECONDARY CONTAINMENT I. AUTOMATIC LINE LEAK DETECTORS J. LINE TIGHTNESS TESTING K. OTHER METHOD ALLOWED BY UST DIVISION (Specify)  3. SPILL AND OVERFILL PROTECTION A. OVERFILL DEVICE INSTALLED														ا مفه ه		
G. INTERSTITIAL MONITORING DOUBLE WALLED TANKPIPING H. INTERSTITIAL MONITORING SECONDARY CONTAINMENT I. AUTOMATIC LINE LEAK DETECTORS J. LINE TIGHTNESS TESTING K. OTHER METHOD ALLOWED BY UST DIVISION (Specify) I. SPILL AND OVERFILL PROTECTION														ا مفه ه		
G. INTERSTITIAL MONITORING DOUBLE WALLED TANK/PIPING H. INTERSTITIAL MONITORING SECONDARY CONTAINMENT I. AUTOMATIC LINE LEAK DETECTORS J. LINE TIGHTNESS TESTING K. OTHER METHOD ALLOWED BY UST DIVISION (Specify)  S. SPILL AND OVERFILL PROTECTION A. OVERFILL DEVICE INSTALLED B. SPILL DEVICE INSTALLED CURRENT CATHODIC PROTECTION?														ا مفه ا		
G. INTERSTITIAL MONITORING DOUBLE WALLED TANKPIPING H. INTERSTITIAL MONITORING SECONDARY CONTAINMENT I. AUTOMATIC LINE LEAK DETECTORS J. LINE TIGHTNESS TESTING K. OTHER METHOD ALLOWED BY UST DIVISION (Specify)  SPILL AND OVERFILL PROTECTION A. OVERFILL DEVICE INSTALLED B. SPILL DEVICE INSTALLED HAVE YOU INSTALLED IMPRESSED														ا مفه ا		
G. INTERSTITIAL MONITORING DOUBLE WALLED TANKPIPING H. INTERSTITIAL MONITORING SECONDARY CONTAINMENT I. AUTOMATIC LINE LEAK DETECTORS J. LINE TIGHTNESS TESTING K. OTHER METHOD ALLOWED BY UST DIVISION (Specify)  B. SPILL AND OVERFILL PROTECTION A. OVERFILL DEVICE INSTALLED B. SPILL DEVICE INSTALLED CURRENT CATHODIC PROTECTION? A. YES B. NO	<b>N</b> C	ONCEF		G INST										ا مفه ا		
G. INTERSTITIAL MONITORING DOUBLE WALLED TANK/PIPING H. INTERSTITIAL MONITORING SECONDARY CONTAINMENT I. AUTOMATIC LINE LEAK DETECTORS J. LINE TIGHTNESS TESTING K. OTHER METHOD ALLOWED BY UST DIVISION (Specify)  S. SPILL AND OVERFILL PROTECTION A. OVERFILL DEVICE INSTALLED B. SPILL DEVICE INSTALLED CURRENT CATHODIC PROTECTION? A. YES B. NO  LEDGE: 1 CERTIFY THE INFORMATIC	<b>N</b> C	ONCEF		G INST										ا مفه ا		
G. INTERSTITIAL MONITORING DOUBLE WALLED TANK/PIPING H. INTERSTITIAL MONITORING SECONDARY CONTAINMENT I. AUTOMATIC LINE LEAK DETECTORS J. LINE TIGHTNESS TESTING K. OTHER METHOD ALLOWED BY UST DIVISION (Specify)  3. SPILL AND OVERFILL PROTECTION A. OVERFILL DEVICE INSTALLED B. SPILL DEVICE INSTALLED CURRENT CATHODIC PROTECTION? A. YES B. NO LEDGE: I CERTIFY THE INFORMATIC	N CC	ONCEF		G INST			THA		PROV					ا مفه ا		

- 3 -

EQP-3021 (Rev. 11/95)

AMENDED TO UPDATE RELEASE DETECTION

AND SPILL OVER FILL PROTECTION INFORMATION.

ALSO AMENDED OWNER TAX PAYER I.D. # AND

ZIP CODE FOR FACILITY ADDRESS.

-4-

<u>ã</u>

UNDERGROUND STORAGE TANK DIVISION DNR WICHIGAN DEPARTMENT OF NATURAL RESOURCES PO BOX 30157
LANSING MI 48909-7657

# REGISTRATION FOR UNDERGROUND STORAGE TANKS

This information is required under 1994 PA 451. Any owner who knowingly fails to notify or submits false information shall be subject to a misdemeanor and/or civil penalties not to exceed \$5,000 per day for each tank for which notification is not given or for which false information is submitted.

PR-3821 (10/94)

			<u> </u>							
INSTRUCTIONS:	COMPLETE THIS	FOAM AND SE? FOISTEBED UNT	ND TO THE ONE	I, UST DIVISION :	ON, AT THE ABOVE A IAS RECEIVED YOUR	DORESS. NEW TANKS . COMPLETED FORM AN	ARE NOT			
	CHECK OR MON	EY ORDER MAD	E PAYABLE TO	THE "STATE	OF MICHIGANT. THE	ANNUAL REGISTRATION	FEE FOR			
	EACH TANK REG	HTIW CERETEL	THE ONA, UST	DIVISION IS						
TYPE OF NOTIFIC	CATION: 🔲 NI	EW REGISTRATIO	ON X AME	NDED INFO.	FACILITY NUMBER (II K	nown)	Ì			
NO. OF TA	ANKS AT FACILITY		WK JUN 03	1000	non C	1055	}			
NO. OF C	ONTINUATION SHE	ETS ATTACHED	mi JOM OF	1930			1			
	I. OWNERSHIP	OF TANKS			IL LOCATIO	N OF TANKS				
IF THIS IS A NEW OWNER'S ADDRESS, PLEASE CHECK   IF INFORMATION SAME AS SECTION I, PLEASE CHECK    CWNER NAME (Corporation/individual_etc.)   FACILITY NAME OR SITE IDENTIFIER										
SHELL OIL COMPANY SHELL SERVICE STATION										
MAILING ADDRESS				STREET ADDI	RESS (P.O. Box Not Acce	minhia) /				
17370	LAURELF	7K N. #	<i>+200</i>	975	BOCHESTE	R /HUUN				
CITY LIVO	VIA	STATE	<sup>27</sup> 48152	CITYBOO	HESTER	STATE ZIP	8037			
	HYNE	TOWNSHIP	-	COUNTY	ALIDAID	TOWNSHIP				
		<u> </u>		TEL EDUCATE	(Including Area Code)					
TELEPHONE (Includit	53 4300			(810)		?O				
TAX P		BEA								
	77/05 AS AU/US				IV. INDIAN LAN	ne	<del></del>			
	TYPE OF OWNE	<u>n                                    </u>			14. INDIAN CAN	<u> </u>				
TEDERAL GO	VERNMENT 🕱 C	JAIOREMMO				INDIAN RESERVATION	OR ON			
STATE GOVE	_	RIVATE		DIAN TRUST		was Tion of Me	Mantal			
☐ FOCYF GOAE	RNMENT		\ <del>-</del>		NATIVE AMERICAN	nation. Tribe, or inc	NAIDOWE			
			TRIBE OR	NATION:						
			V. TYPE O	F FACILITY						
GAS STATIO	N	а	LOCAL GOVER	MENT		CONTRACTOR	•			
T PETROLEUM		_	STATE GOVERN			TRUCKING/THANSP	ORT			
AIR TAXI (AI		_	FEDERALINON-			עוועוונא ב				
AIRCRAFT C		_	FEDERAL-MILIT	ARY		☐ RESIDENTIAL				
AUTO DEAL	ERSHIP	_	COMMERCIAL			FARM				
☐ RAILROAD		Ц	INOUSTRIAL			OTHER (Explain)				
L		·								
		VI. C	ONTACT PER	SON FOR L	OCATION					
NAME JEROM	E P. CAV	ALUZZI	HEALTH SA	FETY & EI	VV. ANALYST	(313) 953	Area Gode) -4341			
			II. FINANCIAL	RESPONSI	BILITY					
I HAVE MET TH	IE FINANCIAL RES	PONSIBILITY RE	QUIREMENTS A	S REQUIRED	IN THE UST RULES	(Check All Items Belov	That Apply)			
SELF INSUF			GUARANTEE			MUSTFA FUND				
COMMERCIA			SURETY BOND			TRUST FUND	,			
C RISK RETEN	ITION GROUP		LETTER OF CA	IEDIT		OTHER METHOD AL	-TOMED			
FOR INFORMATIO	N ABOUT MUSTFA E	MIGIBILITY CALL 1	-800-468-7832							
				TIFICATION						
THIS AND ALL A	TTACHED DOCUME	NTS. AND THAT	BASED ON MY	INCUIRY OF	D AM FAMILIAR WITH THOSE INDIVIDUALS IN IS TRUE. ACCURA	THE INFORMATION SUI IMMEDIATELY RESPON TE AND COMPLETE.	BMITTED IN ISIBLE FOR			
NAME AND OFFICIA	L TITLE OF OWNER		SIGNATURE		)	DATE	7			
AUTHORIZED REPF	GEE ABOVE	2	Ceron	100	ara ()	15/2	9/96			
	シェア へいりせん	-	・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・	$\sim$	VIII VII ANI	1 - 1 - 0				

IX. DESCRIPTION OF UNDER	GROUND	STORAGE	TANKS (C.	omplete Fo	r Each Ta	nk At This	Location)	
	+ 5	+21	# 3	#	#	#	#	# <sup>**</sup>
1. STATUS OF TANKS (Check One)  CURRENTLY IN USE  TEMPORARILY OUT OF USE **  AMENDMENT OF INFORMATION		900		0 0 0	000		000	000
"Also Complete Section X (If tanks are removed/closes), complete page 3, Section X)	,							
2. CATE OF INSTALLATION	51961	1272	1272					ì
3. ESTIMATED TOTAL CAPACITY (Gallons)	IOM	IOM	6M					
4. MATERIAL OF CONSTRUCTION (Mark All That Apply) ASPHALT COATED OR BARE STEEL	а	<b>12</b>	<b>a</b>	ถ	a	_		
CATHODICALLY PROTECTED STEEL EPOXY COATED STEEL		001			001	000		و و و و
COMPOSITE (Steel With Fiberglass) FIBERGLASS REINFORCED PLASTIC LINED INTERIOR DOUBLE WALLED		aaaac		0000	000			
POLYETHYLENE TANK JACKET CONCRETE EXCAVATION LINER	ممم	امممم		000	000		000000	وموموم
UNKNOWN OTHER (Please Specify) HAS TANK SEEN REPAIRED?		<u> </u>				0 0		
-5. PIPING MATERIAL (Mark Ali That Apply)  BARE STEEL  GALVANIZED STEEL  FIBERGLASS REINFORCED PLASTIC  COPPER  CATHODICALLY PROTECTED  DOUBLE WALLED  SECONDARY CONTAINMENT  UNKNOWN  OTHER (Please Specify)	00000000	000000000	ookooboo	0000000	0000000	00000000	0000000	
6. PIPING (Type) (Mark All That Apply) SUCTION: NO VALVE AT TANK SUCTION: VALVE AT TANK PRESSURE (Remote) PRESSURE (Gravity Fed) HAS PIPING BEEN REPAIRED?	00000	00000	aomaa	00000	00000	00000	0000	00000
7. SUBSTANCE CURRENTLY OR LAST STORED IN GREATEST QUANTITY SY VOLUME GASOLINE OIESEL GASOHOL KEROSENE (Not For Consumptive Use On Premises) FUEL OIL USED OIL OTHER (Please Specify)	000000	000000	00000	000000	000000	00000	000000	aoooo
HAZARDOUS SUBSTANCE COMPREHENSIVE ENVIRONMENTAL RESPONSE COMPENSATION & LIABILITY ACT (CERCLA) NAME AND/OR CHEMICAL ABSTRACT SERVICE (CAS) NUMBER		122	20 200					

ROCHESTER | AVON

ONE MICHIGAN DEPARTMENT OF NATURAL RESOURCES - UNDERGROUND STORAGE TANK DIVISION

X.	TANK	S QU	T OF	USE	OR C	HAN	ge in	SER	IVICE							Į
TANK IDENTIFICATION NUMBER	# 4		# ]		#		#		#	]	#		#		#	
1. CLOSING OF TANK A. ESTIMATED DATE LAST USED (Month/Day/Year)	4/1	5/96	4/15	194												
ESTIMATED DATE TANK REMOVED/ CLOSED IN PLACE (Month/Day/Year)	<u>5/1</u>	190	5/1	196												
C. TANK WAS REMOVED FROM GROUND D. TANK FILLED WITH INERT MATERIAL (Sand, Concrete, etc.)	<u>C</u>							ī		·		1				
DESCRIBE TYPE OF FILL USED AND REASON TANK WAS NOT REMOVED E. CHANGE IN SERVICE		  ]		   ]		 		   ]		   ]		_				{
REMINDER: A SITE ASSESSA	MENT I	MUST	BE C	OMPL	ETED.	UNLE	SS YO	OU RE	PORT	A CC	NFIRA	MED R	ELEA	SE		
XI. CERTIFICATION OF COM  1. INSTALLATION	FLIAI	40E (	Comp	tere	ror A	11 MG	w wuc	ı upç	i adec	ı ıan	NO AL	1 1112	roca	uon)		
A. INSTALLER CERTIFIED BY TANK AND PIPING MANUFACTURERS	<b>Ş</b> ≨		<b>}</b> E		<u>`</u> [2	*		]	כ	ָ ָנ		1	_	]		ם !
3. INSTALLER CERTIFIED OR LICENSED BY THE UST DIVISION C. INSTALLATION INSPECTED BY A				_				_	ے ا							
REGISTERED ENGINEER  0. INSTALLATION INSPECTED AND APPROVED BY UST DIVISION					אַ	1 2				_				i		
E. ANOTHER METHOD ALLOWED BY UST DIVISION (Please Specify)																
					_											
2. RELEASE DETECTION	TANK	PIPE	TANK	PIPE	TANK	PIPE	TANK	PIPE	TANK	PIPE	TANK	PIPE	TANK	PIPE	TANK	PIPE
A. MANUAL (State) TANK GAUGING	131.	PIPE	771	PIPE	邳	PIPE	a	PIPE		PIPE		PIPE		PIPE		PIPE
A. MANUAL (State) TANK GAUGING B. TANK TIGHTNESS TESTING	<b>E</b>	PIPE		PIPE	图探	PIPE	00	PIPE		PIPE	00	PIPE	00	PIPE	00	PIPE
A. MANUAL (State) TANK GAUGING B. TANK TIGHTNESS TESTING C. INVENTORY CONTROL	阿阿阿	PIPE	田安村	PIPE	四国河	PIPE	ممم	PIPE	000	PIPE	000	PIPE	مام	PIPE	000	PIPE
A. MANUAL (State) TANK GAUGING B. TANK TIGHTNESS TESTING	西阿阿口		日母母母		10日日日		مممم		مومو		0000	!	ممنعم		aaaa	
A. MANUAL (State) TANK GAUGING B. TANK TIGHTNESS TESTING C. INVENTORY CONTROL D. AUTOMATIC TANK GAUGING	阿阿阿	PE C	田安村	PIPE	四国河	PIPE	ممم	PIPE	000	P1PE	000	PIPE	مام	PIPE	000	PIPE
A. MANUAL (State) TANK GAUGING B. TANK TIGHTNESS TESTING C. INVENTORY CONTROL D. AUTOMATIC TANK GAUGING E. VAPOR MONITORING F. GROUNDWATER MONITORING G. INTERSTITIAL MONITORING	四回四國國國	0 0	四日日母母母	00	០០០២២២	00	ممممم	00	000000	00	00000	00	ممممم	00	وممومو	00
A. MANUAL (State) TANK GAUGING B. TANK TIGHTNESS TESTING C. INVENTORY CONTROL D. AUTOMATIC TANK GAUGING E. VAPOR MONITORING F. GROUNDWATER MONITORING G. INTERSTITIAL MONITORING OOUBLE WALLED TANK/PIPING H. INTERSTITIAL MONITORING	口口四四四	00 W	0 DDCB49		០០២២២		000000 0	٥	00000	000	00000		ممقمم	0	0 00000	
A. MANUAL (State) TANK GAUGING B. TANK TIGHTNESS TESTING C. INVENTORY CONTROL D. AUTOMATIC TANK GAUGING E. VAPOR MONITORING F. GROUNDWATER MONITORING G. INTERSTITIAL MONITORING DOUBLE WALLED TANK/PIPING H. INTERSTITIAL MONITORING SECONDARY CONTAINMENT	四回四國國國	ם ע סם	四日日母母母	00 0 0	០០០២២២	0000	ممممم	00 0 0	000000	0000	00000	000	ممممم	0000	وممومو	00 0 0
A. MANUAL (SIELLE) TANK GAUGING B. TANK TIGHTNESS TESTING C. INVENTORY CONTROL D. AUTOMATIC TANK GAUGING E. VAPOR MONITORING F. GROUNDWATER MONITORING G. INTERSTITIAL MONITORING OOUBLE WALLED TANK/PIPING H. INTERSTITIAL MONITORING SECONDARY CONTAINMENT I. AUTOMATIC UNE LEAK DETECTORS	阿阿阿口口口 段	מום מי םם	0 DDCB49		0 000889	90000	000000 0	00 0 00	000000	00 0 00	000000 0	00 0 00	ه معمومه	00 0 00	0 00000	00 0 00
A. MANUAL (SIZE) TANK GAUGING B. TANK TIGHTNESS TESTING C. INVENTORY CONTROL D. AUTOMATIC TANK GAUGING E. VAPOR MONITORING F. GROUNDWATER MONITORING G. INTERSTITIAL MONITORING OOUBLE WALLED TANK/PIPING H. INTERSTITIAL MONITORING SECONDARY CONTAINMENT	阿阿阿口口口 段	ם ע סם	0 DDCB49	00 0 0	0 000889	0000	000000 0	00 0 0	000000	0000	000000 0	000	ه معمومه	000	0 00000	00 0 0
A. MANUAL (State) TANK GAUGING B. TANK TIGHTNESS TESTING C. INVENTORY CONTROL D. AUTOMATIC TANK GAUGING E. VAPOR MONITORING F. GROUNDWATER MONITORING G. INTERSTITIAL MONITORING OOUBLE WALLED TANKIPIPING H. INTERSTITIAL MONITORING SECONDARY CONTAINMENT I. AUTOMATIC UNE LEAK DETECTORS J. LINE TIGHTNESS TESTING	阿阿阿口口口 段	מום מי םם	0 DDCB49		0 000889	90000	000000 0	00 0 00	000000	00 0 00	000000 0	00 0 00	ه معمومه	00 0 00	0 00000	00 0 00
A. MANUAL (State) TANK GAUGING B. TANK TIGHTNESS TESTING C. INVENTORY CONTROL D. AUTOMATIC TANK GAUGING E. VAPOR MONITORING F. GROUNDWATER MONITORING G. INTERSTITIAL MONITORING OOUBLE WALLED TANK/PIPING H. INTERSTITIAL MONITORING SECONDARY CONTAINMENT I. AUTOMATIC UNE LEAK DETECTORS J. LINE TIGHTNESS TESTING K. OTHER METHOD ALLOWED BY	超超过00 数 0	מום מי םם	新安岛000 0 0			90000		00 0 00		00 0 00		00 0 00	000000 0 0	00 0 00		00 0 00
A. MANUAL (State) TANK GAUGING B. TANK TIGHTNESS TESTING C. INVENTORY CONTROL D. AUTOMATIC TANK GAUGING E. VAPOR MONITORING F. GROUNDWATER MONITORING G. INTERSTITIAL MONITORING OOUBLE WALLED TANKIPIPING H. INTERSTITIAL MONITORING SECONDARY CONTAINMENT I. AUTOMATIC UNE LEAK DETECTORS J. LINE TIGHTNESS TESTING K. OTHER METHOD ALLOWED BY UST DIVISION (Specify) 3. SPILL AND OVERFILL PROTECTION A. OVERFILL DEVICE INSTALLED B. SPILL DEVICE INSTALLED	超超过00 数 0	व्यक्त व व	新安岛000 0 0	वाष्ट्र व व व				00 0 000		00 0 000		00 0 000	000000 0 0	00 0 000		00 0 000
A. MANUAL (State) TANK GAUGING B. TANK TIGHTNESS TESTING C. INVENTORY CONTROL D. AUTOMATIC TANK GAUGING E. VAPOR MONITORING F. GROUNDWATER MONITORING G. INTERSTITIAL MONITORING OOUBLE WALLED TANKPIPING H. INTERSTITIAL MONITORING SECONDARY CONTAINMENT I. AUTOMATIC LINE LEAK DETECTORS J. LINE TIGHTNESS TESTING K. OTHER METHOD ALLOWED BY UST DIVISION (Specify) 3. SPILL AND OVERFILL PROTECTION A. OVERFILL DEVICE INSTALLED B. SPILL DEVICE INSTALLED 4. HAVE YOU INSTALLED IMPRESSED CURRENT CATHODIC PROTECTION?				मिल विक्रिय व व व		MA MAND 0 00		00 0 000		00 0 000		00 0 000				00 0 000
A. MANUAL (State) TANK GAUGING B. TANK TIGHTNESS TESTING C. INVENTORY CONTROL D. AUTOMATIC TANK GAUGING E. VAPOR MONITORING F. GROUNDWATER MONITORING G. INTERSTITIAL MONITORING OOUBLE WALLED TANKPIPING H. INTERSTITIAL MONITORING SECONDARY CONTAINMENT I. AUTOMATIC UNE LEAK DETECTORS J. LINE TIGHTNESS TESTING K. OTHER METHOD ALLOWED BY UST DIVISION (Specify)  3. SPILL AND OVERFILL PROTECTION A. OVERFILL DEVICE INSTALLED B. SPILL DEVICE INSTALLED 4. HAVE YOU INSTALLED IMPRESSED CURRENT CATHODIC PROTECTION? A. YES		व्यक्त व व														
A. MANUAL (State) TANK GAUGING B. TANK TIGHTNESS TESTING C. INVENTORY CONTROL D. AUTOMATIC TANK GAUGING E. VAPOR MONITORING F. GROUNDWATER MONITORING G. INTERSTITIAL MONITORING OOUBLE WALLED TANKIPIPING H. INTERSTITIAL MONITORING SECONDARY CONTAINMENT I. AUTOMATIC UNE LEAK DETECTORS J. LINE TIGHTNESS TESTING K. OTHER METHOD ALLOWED BY UST DIVISION (Specify) 3. SPILL AND OVERFILL PROTECTION A. OVERFILL DEVICE INSTALLED 9. SPILL DEVICE INSTALLED CURRENT CATHODIC PROTECTION? A. YES B. NO						MA MAD D D D										
A. MANUAL (State) TANK GAUGING B. TANK TIGHTNESS TESTING C. INVENTORY CONTROL D. AUTOMATIC TANK GAUGING E. VAPOR MONITORING F. GROUNDWATER MONITORING G. INTERSTITIAL MONITORING OOUBLE WALLED TANKPIPING H. INTERSTITIAL MONITORING SECONDARY CONTAINMENT I. AUTOMATIC UNE LEAK DETECTORS J. LINE TIGHTNESS TESTING K. OTHER METHOD ALLOWED BY UST DIVISION (Specify)  3. SPILL AND OVERFILL PROTECTION A. OVERFILL DEVICE INSTALLED B. SPILL DEVICE INSTALLED 4. HAVE YOU INSTALLED IMPRESSED CURRENT CATHODIC PROTECTION? A. YES B. NO PLEDGE: I CERTIFY THE INFORMATI THE BEST OF MY BELLEF	図図図□□□ 図 □ WAND	ONCE ON		THE PART OF THE SECTION OF THE SECTI		MA MAD D D D										
A. MANUAL (State) TANK GAUGING B. TANK TIGHTNESS TESTING C. INVENTORY CONTROL D. AUTOMATIC TANK GAUGING E. VAPOR MONITORING F. GROUNDWATER MONITORING G. INTERSTITIAL MONITORING OOUBLE WALLED TANKPIPING H. INTERSTITIAL MONITORING SECONDARY CONTAINMENT I. AUTOMATIC LINE LEAK DETECTORS J. LINE TIGHTNESS TESTING K. OTHER METHOD ALLOWED BY UST DIVISION (Specify) 3. SPILL AND OVERFILL PROTECTION A. OVERFILL DEVICE INSTALLED 9. SPILL DEVICE INSTALLED CURRENT CATHODIC PROTECTION? A. YES B. NO PLEDGE: I CERTIFY THE INFORMATI	Si Bi	O D D D D D D D D D D D D D D D D D D D	中 D D D D D D D D D D D D D		TALL STALL	DO DO DO DE SE LA			PRO IRE						TRUE	
A. MANUAL (State) TANK GAUGING B. TANK TIGHTNESS TESTING C. INVENTORY CONTROL D. AUTOMATIC TANK GAUGING E. VAPOR MONITORING F. GROUNDWATER MONITORING G. INTERSTITIAL MONITORING OOUBLE WALLED TANKPIPING H. INTERSTITIAL MONITORING SECONDARY CONTAINMENT I. AUTOMATIC UNE LEAK DETECTORS J. LINE TIGHTNESS TESTING K. OTHER METHOD ALLOWED BY UST DIVISION (Specify)  3. SPILL AND OVERFILL PROTECTION A. OVERFILL DEVICE INSTALLED B. SPILL DEVICE INSTALLED 4. HAVE YOU INSTALLED IMPRESSED CURRENT CATHODIC PROTECTION? A. YES B. NO PLEDGE: I CERTIFY THE INFORMATI THE BEST OF MY BELIEF INSTALLER: MANUAL	Si Bi	ONCE ON	中 D D D D D D D D D D D D D			DO DO DO DE SE LA	DOCUCIO DO SE		PRO						TRUE	

	ai Ž	4,of 4
COMMENTS AND/OR CLARIFICATIONS TO THE UST DIVISION STAFF:	\	÷,
REPLACED IOM REGULARTANK (STEEL WITH LIMING	_)	<del></del> -
WITH IOM DWEG TINK		
PREPPED TANKS FOR STAGETE VAPOR RECC	NERY	
·		
REPLACED STEEL LINES WITH SWFG		
AND FOR FUTURE ELECTRONIC MONITORING, REPLACED STEEL LINES WITH SWFG		

Facility No: 0-009055

Comp No: 042396

Page 01 of 01

# Department of Environmental Quality Underground Storage Tank Division

MAY 01 1996

### INSPECTION REPORT

Type of Inspection Performed: TANK INSTALLATION

Type of Facility: PUBLIC AUTOMOTIVE SERVICE STATION

Number of Tanks:

1

Contact Person: BILL BOGAN

Telephone Number: (810) 620-0070

OWNERSHIP OF TANKS

Owner Name: SHELL OIL CO

Address:

17370 LAUREL PK NORTH

SUITE 200

LIVONIA, MI 48152

LOCATION OF TANKS

Name: SHELL SERVICE STATION

Address: 975 S ROCHESTER/AVON

ROCHESTER, MI 48037

County: OAKLAND

THE UST SYSTEM(S) AT THIS FACILITY WERE INSPECTED USING THE MICHIGAN UNDERGROUND STORAGE TANK RULES AND APPLICABLE SECTIONS OF THE 1992 MICHIGAN FLAMMABLE AND COMBUSTIBLE LIQUID RULES. THE FOLLOWING VIOLATIONS, IF ANY, WERE NOTED. THE SITE CONTACT PERSON WAS VERBALLY ADVISED OF THE VIOLATIONS AT THE TIME OF INSPECTION.

1. TANKS SUBJECT TO BUOYANT FORCES SHALL HAVE PROVISIONS MADE TO PREVENT THE TANK FROM FLOATING.

UST 280.10 (J) (FL/CL PART 2, SECTION 2-6.6.1)

<<< End of Cited Violations >>>

# COMMENTS:

Inspection Status: SITE DISAPPROVED

Date of Inspection://

0/4/23/96

Date Compliance is Required: 04/28/96

Signature:

DOUGLAS PENTZIÈN

AUTHORITY: 1994 PA 451

1941 PA 207

COMPLIANCE: Required

PENALTY: Misdemeanor, Civil Penalties

SOUTHEAST MICHIGAN DISTRICT OFFICE

38980 SEVEN MILE ROAD LIVONIA, MI 48152

(313) 432-1253

# DNR UNDERGROUND STORAGE TANK DIVISION MICHIGAN-DEPARTMENT OF NATURAL RESOURCES PO BOX 30157 LANSING MI 48909-7657

Commercial of Section 1888 and a

UNDERGROUND STORAGE TANK PLAN REVIEW REPORT
This information is required under authority of Act 423, P.A. 1984, as amended. Failure to comply with the provisions of this Act may result in a misdemeanor and/or Civil penalties.

PRELIMINARY K FINÁL	DATE April 23, 1996	NUMBER OF TAN	iks · 5	FACILITY NUMBER 0-009055
ARCHITECT/E Matthew E. Koziel Oscar W. Larson Compa 10100 Dixic Highway Clarkston, MI 48348		ADDRESS: 9	Shell Oil Company 975 South Rochest Rochester, MI 483 Oakland	er Road
THE INFORMATION SUBMITTED FOR THE A	ABOVE PROJECT HAS BEEN REVIEWED	FOR COMPLIANCE	WITH THE APPLICAB	LE ADMINISTRATIVE RULES AS
HUJOATED ABOVE AND TO.	ACCEPTABLE AS SUBMIT	TTED	ACCEPTAB	BLE AS NOTED BELOW
· ·	SEE COMMENTS BELOW	1	UNACCEP-	TABLE AS NOTED BELOW
deficiencies were noted. Ho Hazardous Materials Storage telephone number (313) 432 installation of the UST syste personnel have conducted The Michigan Undergroun underground storage tank Provide certification of comp NOTICE: THE UST REG MAINTAIN POLLUTION OCCURRENCE.  If this system is not installed	nd Storage Tank Rules, Section is to provide evidence of financial pliance with the National Electrical PULATORY ACT REQUIRES IN LIABILITY INSURANCE Will within one year, please contact to	ring requirement of the control of t	nts are met. Environmental Quant less than seven y not be placed in es owners or oper y at final inspection. IO INSTALL OR NOT LESS THAN essible resubmittal	nality office in Livonia, n calendar days before to service until DEQ raters of petroleum on.  REMOVE USTS TO N ONE MILLION PER
Pursuant to Public Act 451 of by a check for the \$100.00 p	of 1994, Part 211, it is the owner's er tank fee be forwarded to this o	s responsibility to ffice after the tar	that a tank registra ink has been instal	tion form accompanied led and prior to use.
If you have any questions, p 10:00 a.m 12:00 p.m. and	olease contact the Technical Revie 1:00 p.m 3:00 p.m.	ew Unit at (517)	373-8168 between	the hours of
PGF:s c: DEQ Livonia		Peh GAM Peter G. Funkho Technical Review	ouser	

DISTRIBUTION;

WHITE - UST DIVISION
CANARY - USTD FIELD OFFICE
PINK - ARCHITECT/ENGINEER

DECISTRATI	ON COD LINDS	EDCDOUND STODAGE TANKS DAG	OT A				
REGISTRATION FOR UNDERGROUND STORAGE TANKS - PART A  FM 23 (9-94) PAGE 1 Notice of Proposed Installation of Underground Storage Tanks							
IMPLEMENTING AGENCY:  MICHIGAN STATE POLICE — FIRE MARSHAL DIVISION  Name of Facility  Shell Oil Company							
Address (Location of facility) (P O Box not acceptable) 975 South Rochester Road		Contact Person (at location) Todd Tageson	Telephone (include area code) (313) 953-4344				
City Rochester,		Zip Code <b>48307</b>					
Name of Submitter Oscar W. Larson Company							
City Clarkston,	State <b>MI</b>		Zip Code <b>48348</b>				
INSTRUCTIONS Part A of this registration form must be comploid 45 days prior to installation of the undergroup of completion of Part A attach the requimichigan State Police, Fire Marshal Division, Pauestions concerning Part A, please call the Technology.	system. to both copies of Part A and mail to: Insing, Michigan 48909. If you have any	Facility # 0009055 New Assigned Tank #					
questions concerning Part A, please call the Technical Review Unit between the hours of 10:00 a.m.—  12:00 p.m. or 1:00 p.m.—3:00 p.m. at 517 322-1935.  Part B of the registration form must be completed and submitted to the State Fire Marshal prior to use of the underground storage tank system, accompanied by the registration fee of \$100.00 per tank.  The following information must be attached to Part A of this form upon submittal  1. A plot plan showing structures, roads, railroads, property lines, easements, within 25' of the UST system. Section 280.22.  2. The location of all drinking water wells within 2000 feet of UST. Section 280.22.  3. A diagram of the UST system. Section 280.22.							
Please complete the required information in conjunction with the Michigan Underground Storage Tank Rules (MUSTR) and the State Flammable and Combustible Liquids Rules (FL/CL) Parts 2 & 3 for underground installations as cited below. The manufacturer and part number must be indicated next to the appropriate item. This form is for review purposes only. It is not intended to list all of the requirements that may be applicable.							

DETAILED INFORMATION/DATA WILL ASSIST IN EXPEDITING THE REVIEW PROCESS

ITEM NO	. DESCRIPTION	MANUFACTURER & PART NO.	ITEM NO. DESCR	IPTION MA	NUFACTURER & PART NO.
*	TANK DESIGN AND CONSTRUCTION: Section 280.20 (a), 280.20 (d), 280.32 & Section 2-2 of FL/CL. Concrete; Steel - UL58; Fiberglass - UL 1316. Dimension, Capacity & Contents.	One (1) 10,000 gallon double wall Xerxes fiberglass UST, for gasoline.	7. TANK LOCA  Section 280  Section 2-4  FL/CL, 10' f  basement s  property lift  avoid loads  transmitted  building fo  tank outsid  degree and	0.20 (d) & See 1 of from wall, pit or ne; also to d by undation- le 45	attached.
*	BURIAL DEPTH COVER: Section 2-4.2 of FL/CL, Minimum 2' or 1' earth & 4" concrete - no vehicular traffic. Minimum 3' or 18" earth & 6" concrete or 8" asphalt with vehicular traffic.	Minimum 48" with 6" reinforced concrete pad.	8. ANCHORIN TANK: Section 2-6 FL/CL. In at subject to f or high wa' NOTE: Tie- straps.	i.6.3 of N/A leas N/A leas leas leas leas leas leas leas leas	
*	BACKFILL MATERIAL SURROUNDING TANK: Section 2-4.2 of FL/CL Minimum 6" sand or pea gravel- steel; minimum 12" pea gravel- fiberglass.	Pea stone minimum 24" around tanks.	9. CORROSIO PROTECTIC TANK: * Section 28 Section 2-4 {Except Sec 2-4,3,1. Fit tank, steel cathodic pi composite tanks, are acceptable	DN OF  D. 20 (a) & Fin  1.3 of FL/CL ction perglass tank with rotection, steel	erglass UST
			10. MONITORI CATHODIC PROTECTIO Section 280 station - wi surface for	O.31. Test N/A	

ORIGINAL & YELLOW PINK

Fire Marshaf Div. HQ Owner

AUTHORITY: COMPLIANCE; PENALTIES:

1984 PA 423, as amended Required Any owner who knowingly falls to notify or submits false information shall be subject to a misdemeanor and/or civil penalties not to exceed \$5,000 per day for each tank for which notification is not given or for which false information is submitted.

TEM NO		MANUFACTURER & PART NO.	ITEM N		MANUFACTURER & PART NO.
	CORROSION PROTECTION FOR PIPING: Section 280.20 (b) (2) & 280.20 (b) (4). Steel - cathodic protection or other approved means, or fiberglass. NOTE: Dielectric couplings at tank and dispenser to isolate tank and piping.	Piping to be single wall FRP.	14.	PIPING MATERIAL: Section 280.20 (b), 280.20 (d), 280.32 & Section 3-3 of FL/CL. Steel, fiberglass or other approved material. Single or double-walled.	Single wall FRP product and vent piping.
*	AROUND FILL PIPE: Section 280.20 (c) (1) (i). Sealed to prevent entry of product into ground.  RELEASE DETECTION	OPW #1 spill tub.	*	PROTECTION: Section 280.20 (c) (1) (ii). Audible alarm sounding or flow restricted when tank is 90% full, or an automatic shut-off of flow into the tank when the tank is 95% full.	OPW 61-S0
*	FOR TANK & PIPING: Section 280.40 (a),	TANK: Inventory control		······································	
	Section 280.41 & Section 280.42. Must be able to detect a release from any	with monitoring, reconciliat  PIPING: Pressurized line	ion. 16.	VENT PIPING: Section 2.4.5 of FL/CL. Steel; outlet above snow level	Minimum 12' above grade
	portion of the tank and piping	leak detectors.		and minimum 12 feet above grade.	
	OTHER REQU	IREMENTS UNDER MICHIGAN'S FLAMM	ABLE &	COMBUSTIBLE LIQUIDS I	RULES (FL/CL) PÄRT 3
17.	EMERGENCY SHUT- OFF VALVE:	OPW 10R series.	21.		To be posted by the own
	OLL AMEAE!		1	WARNINGS: Section 9-9, & Section 9-5.5 of FL/CL, Required at self-serve stations.	: 0 p - 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
*	Section 4.3.6 of FL/CL. Required on submerged pumping systems, rigidly anchored. Suction systems require check valve under			WARNINGS: Section 9-9, & Section 9-5.5 of FUCL, Required at	per State regulations.
	Section 4.3.6 of FL/CL. Required on submerged pumping systems, rigidly anchored. Suction systems require		. 22.	WARNINGS: Section 9-9, & Section 9-5.5 of FL/CL. Required at self-serve stations.  HOLD OPEN DEVICE ON NOZZLE: Section 9-1 OF FL/CL.	
	Section 4.3.6 of FL/CL. Required on submerged pumping systems, rigidly anchored. Suction systems require check valve under the dispenser. (Slip joint coupling	See attached.		WARNINGS: Section 9-9, & Section 9-5.5 of FL/CL. Required at self-serve stations.  HOLD OPEN DEVICE ON NOZZLE:	per State regulations.
	Section 4.3.6 of FL/CL. Required on submerged pumping systems, rigidly anchored. Suction systems require check valve under the dispenser. (Slip joint coupling prohibited)  LOCATION OF DISPENSER: Section 4-1.1 of FL/CL. 10' from property lines; building walls of combustible construction; openings to buildings with noncombustible	See attached.		WARNINGS: Section 9-9, & Section 9-5.5 of FL/CL. Required at self-serve stations.  HOLD OPEN DEVICE ON NOZZLE: Section 9-1 OF FL/CL. Allowed Pre-pay self-service needs special feature of nozzle that prevents resumption of flow once pump is stopped.  FIRE EXTINGUISHER AT SERVICE STATION: Section 9-8 of FL/CL.	Nozzles to be OPW 11B.  Fire extinguishers
	Section 4.3.6 of FL/CL. Required on submerged pumping systems, rigidly anchored. Suction systems require check valve under the dispenser. (Slip joint coupling prohibited)  LOCATION OF DISPENSER: Section 4-1.1 of FL/CL. 10' from property lines; building walls of combustible construction; openings to buildings with noncombustible walls.  DISPENSING DEVICE AND NOZZLE:	See attached.  OPW 11B nozzles with	*	WARNINGS: Section 9-9, & Section 9-5.5 of FL/CL. Required at self-serve stations.  HOLD OPEN DEVICE ON NOZZLE: Section 9-1 OF FL/CL. Allowed. Pre-pay self-service needs special feature of nozzle that prevents resumption of flow once pump is stopped.  FIRE EXTINGUISHER AT SERVICE STATION:	Nozzles to be OPW 11B.
18.	Section 4.3.6 of FL/CL. Required on submerged pumping systems, rigidly anchored. Suction systems require check valve under the dispenser. (Slip joint coupling prohibited)  LOCATION OF DISPENSER: Section 4-1.1 of FL/CL. 10' from property lines; building walls of combustible construction; openings to buildings with noncombustible walls.  DISPENSING DEVICE		*	WARNINGS: Section 9-9, & Section 9-5.5 of FL/CL. Required at self-serve stations.  HOLD OPEN DEVICE ON NOZZLE: Section 9-1 OF FL/CL. Allowed. Pre-pay self-service needs special feature of nozzle that prevents resumption of flow once pump is stopped.  FIRE EXTINGUISHER AT SERVICE STATION: Section 9-8 of FL/CL. Minimum 4A-20BC rating, within 75 of dispensers, fill pipe, and service area.	Nozzles to be OPW 11B.  Fire extinguishers will be installed with
18.	Section 4.3.6 of FL/CL. Required on submerged pumping systems, rigidly anchored. Suction systems require check valve under the dispenser. (Slip joint coupling prohibited)  LOCATION OF DISPENSER: Section 4-1.1 of FL/CL. 10' from property lines; building walls of combustible construction; openings to buildings with noncombustible walls.  DISPENSING DEVICE AND NOZZLE: Section 4-2.2, & Section 4-2.6 of FL/CL. Must be listed and identified as to product it dispenses. Section 9-1.6 of FL/CL Splash guard	OPW 11B nozzles with	23.	WARNINGS: Section 9-9, & Section 9-5.5 of FL/CL. Required at self-serve stations.  HOLD OPEN DEVICE ON NOZZLE: Section 9-1 OF FL/CL. Allowed. Pre-pay self-service needs special feature of nozzle that prevents resumption of flow once pump is stopped.  FIRE EXTINGUISHER AT SERVICE STATION: Section 9-8 of FL/CL. Minimum 4A-20BC rating, within 75' of dispensers, fill pipe, and service area.  AREA BENEATH & AROUND DISPENSER: Section 4-2.12, & Section 9-6 of FL/CL. Prevent leaks & spills	Nozzles to be OPW 11B.  Fire extinguishers will be installed with 75' of dispenser by the owner.  Containment Technologic
18.	Section 4.3.6 of FL/CL. Required on submerged pumping systems, rigidly anchored. Suction systems require check valve under the dispenser. (Slip joint coupling prohibited)  LOCATION OF DISPENSER: Section 4-1.1 of FL/CL. 10' from property lines; building walls of combustible construction; openings to buildings with noncombustible walls.  DISPENSING DEVICE AND NOZZLE: Section 4-2.2, & Section 4-2.6 of FL/CL. Must be listed and identified as to product it dispenses. Section 9-1.6 of FL/CL	OPW 11B nozzles with	23.	WARNINGS: Section 9-9, & Section 9-9, & Section 9-5.5 of FL/CL. Required at self-serve stations.  HOLD OPEN DEVICE ON NOZZLE: Section 9-1 OF FL/CL. Allowed. Pre-pay self-service needs special feature of nozzle that prevents resumption of flow once pump is stopped.  FIRE EXTINGUISHER AT SERVICE STATION: Section 9-8 of FL/CL. Minimum 4A-20BC rating, within 75' of dispensers, fill pipe, and service area.  AREA BENEATH & AROUND DISPENSER: Section 4-2.12, & Section 9-6 of FL/CL.	Nozzles to be OPW 11B.  Fire extinguishers will be installed with 75' of dispenser by the owner.

UNDERGROUND STORAGE TANK DIVISION DARAMICHIGAN DEPARTMENT OF NATURAL RESOURCES PO BOX 30157
LANSING MI 48809-7657

## REGISTRATION FOR UNDERGROUND STORAGE TANKS

This information is required under 1994 PA 451. Any owner who knowingly falls to notify or submits false information shall be subject to a misdemeanor and/or civil penalties not to exceed \$5,000 per day for each tank for which notification is not given or for which false information is submitted.

PR-3821 (10/94)

	Pi	13: 15 fores	ach tank for which	notification is no	t given or for which false in	formation is submitted.
INSTRUCTIONS: COMPLETE THIS FORM AND SEND TO THE DNR. UST DIVISION, AT THE ABOVE ADDRESS. NEW TANKS ARE NOT CONSIDERED REGISTERED UNTIL THE ONR. UST DIVISION HAS RECEIVED YOUR COMPLETED FORM AND A CHECK OR MONEY ORDER MADE PAYABLE TO THE "STATE OF MICHIGAN". THE ANNUAL REGISTRATION FEE FOR EACH TANK REGISTRATION FEE FOR						
TYPE OF NOTIFICA	ITION: NE	W REGISTRATIO	AME X NC	NDED INFO.	FACILITY NUMBER (II kit	own)
	IKS AT FACILITY		941.012 20.00 N	0 4860	0009	055
NO. OF CO	SHE NOITAUNITM	ETS ATTACHED	amy MAKT	2 1996		
	. OWNERSHIP	OF TANKS			II. LOCATION	OF TANKS
	W OWNER'S ADI		CHECK [			CTION I. PLEASE CHECK
OWNER NAME (CORPORATE)	ation/individual, etc.)	MPANY		SHE!	E OR SITE IDENTIFIER	STATION
MAILING ADDRESS	AURELF	16 N. +	<i>‡200</i>	975 K	ICCO ID O day Alat Access	4V0N
CITY LIVON	IA	STATE	48152	ROC	HESTER	STATE 1 48037
CCUNTY WA	YNE	TOWNSHIP	•	COUNTY	KLAND	TOWNSHIP
TELEPHONE (Including	Area Code)	Ò			Including Area Code) -656-008	30
TAX	and accommodate	NOCO.	<del></del>			
				1	IV. INDIAN LAND	
III. T	YPE OF OWNE	н			IV. INDIAN CANE	
☐ FEDERAL GOV	· —	OMMERCIAL		e located o Dian Trust		ndian reservation or on
☐ STATE GOVERI	<del></del>	RIVATE				ATION, TRIBE, OR INDIVIDUAL.
COOKE GOVER	MEN I	•	TRISE OR	NATION:		
			V. TYPE O	F FACILITY		
S GAS STATION		П	LOCAL GOVER			CONTRACTOR
PETROLEUM			STATE GOVERN	IMENT		THUCKING/THANSPORT:
AIR TAXI (AIR	LINE)		FEDERAL/NON-			ייייייייייייייייייייייייייייייייייייי
AIRCRAFT OV			FEDERAL-MILIT	ARY		] RESIDENTIAL
AUTO DEALE	RSHIP	_	COMMERCIAL INDUSTRIAL			☐ FARM ☐ OTHER (Explain)
☐ RAILROAD		Ц	MDOSTHIAL		,	
<u> </u>		VI. C	ONTACT PERS	SON FOR LO	OCATION	
NAMEJEROME	P. CAV		IOR TITLE		VV. ANALYST	TELEPHONE (Including Area Code), (313) 953-4341
			I. FINANCIAL	RESPONSIE	BILITY	
l .				S REQUIRED	IN THE UST RULES	(Check All Items Below That Apply)
SELF INSURA		_	GUARANTEE			MUSTFA FUND
COMMERCIAL		_	SURETY BOND			TRUST FUND OTHER METHOD ALLOWED
☐ RISK RETENT	TON GHOUP I ABOUT MUSTFA E	- <del>-</del>	LETTER OF CR			7 OTHER METHOD ACCORDS
TOA WE CHINATION	7.000			TIEICATION		
VIII. CERTIFICATION  I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION SUBMITTED IN THIS AND ALL ATTACHED DOCUMENTS, AND THAT BASED ON MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION. I BELIEVE THAT THE SUBMITTED INFORMATION IS TRUE. ACCURATE AND COMPLETE.						
NAME AND OFFICIAL	TITLE OF OWNER		SIGNATURE	Granario	()	DATE
AUTHORIZED REPRE	EE ABOVE	<u>'</u>	Suo	Ne C	avalupe	2/4/96

IX. DESCRIPTION OF UNDER	GROUND	STORAGE	TANKS (C	omplete Fo	or Each Ta	nk At This	Location)	
	#	#2	13	#4	#	#	# <u>,</u>	*
1. STATUS OF TANKS (Check One)  CURRENTLY IN USE  TEMPORARILY OUT OF USE "  AMENDMENT OF INFORMATION	800				0 0 0	مام	000	000
"Also Complete Section X  (If tanks are removed/closed, complete page 3, Section X)	,	-						
2. DATE OF INSTALLATION	12/12	12/12	12/12	12/79				
3. ESTIMATED TOTAL CAPACITY (Gallons)	101	IOM	6M	1191				
4. MATERIAL OF CONSTRUCTION (Mark All That Apply)  ASPHALT COATED OR BARE STEEL  CATHODICALLY PROTECTED STEEL  EPOXY COATED STEEL  COMPOSITE (Steel With Fiberglass)  FIBERGLASS REINFORCED PLASTIC  LINED INTERIOR  DOUBLE WALLED  POLYETHYLENE TANK JACKET  CONCRETE  EXCAVATION LINER  UNKNOWN  OTHER (Please Specify)	Na a a a a a a a a a a	o o o o o o o o o o o o		8000000000	0000000000	0000000000	000000000	00000000000
HAS TANK BEEN REPAIRED?								
5. PIPING MATERIAL (Mark All That Apply)  BARE STEEL GALVANIZED STEEL FIBERGLASS REINFORCED PLASTIC COPPER CATHODICALLY PROTECTED DOUBLE WALLED SECONDARY CONTAINMENT UNKNOWN OTHER (Please Specify)		00000000	0000000	0000000	00000000	0000000	00000000	0000000
6. PIPING (Type) (Mark All That Apply) SUCTION: NO VALVE AT TANK SUCTION: VALVE AT TANK PRESSURE (Remote) PRESSURE (Gravity Fed) HAS PIPING BEEN REPAIRED?	00800	00800	00000	00000	0000	0000	00000	aaaaa
7. SUBSTANCE CURRENTLY OR LAST STORED IN GREATEST QUANTITY BY VOLUME GASOLINE DIESEL GASOHOL KEROSENE (Not For Consumptive Use On Pramises) FUEL OIL USED OIL OTHER (Please Specify)	<u> </u>	00000	00000	Rooop	00000	00000	00000	000000
HAZARDOUS SUBSTANCE COMPREHENSIVE ENVIRONMENTAL RESPONSE COMPENSATION & LIABILITY ACT (CERCLA) NAME AND/OR CHEMICAL ABSTRACT SERVICE (CAS) NUMBER		700	DE DE	e al	ove			

\* DNR MICHIGAN DEPARTMENT OF NATURAL RESOURCES - UNDERGROUND STORAGE TANK DIVISION

X.	TANK	s ou	TOF	USE	OR C	HAN	GE IN	SER	VICE							
· TANK IDENTIFICATION NUMBER	#	<del></del>	#		#		#		#		#		#		#	
1. CLOSING OF TANK A. ESTIMATED DATE LAST USED (Month/Day/Year)									-							
8. ESTIMATED DATE TANK REMOVED/ CLOSED IN PLACE (Month/Day/Year)														_		
C. TANK WAS REMOVED FROM GROUND D. TANK FILLED WITH INERT MATERIAL (Sand, Concrete, etc.)		3		1				T I				- 1				
DESCRIBE TYPE OF FILL USED AND REASON TANK WAS NOT REMOVED E. CHANGE IN SERVICE		   ]		 				 		_		   ]				
REMINDER: A SITE ASSESSI	KENT	WIIST	BE C	OMPL	ETED.	UNLE	SS YO	OU RE	PORT	A CO	NEIR	AED F	ELFA			
XI. CERTIFICATION OF COM	PLIA	YUE (	Comp	rete	ror A	II Ne	w And	upg	radeo	, tan	IA SA	1 1113	roca	(10H)		
1. INSTALLATION A. INSTALLER CERTIFIED BY TANK AND PIPING MANUFACTURERS		]		] -		ן : נ	Ľ			I	<u> </u>	1		]		נ
8. INSTALLER CERTIFIED OR LICENSED BY THE UST DIVISION C. INSTALLATION INSPECTED BY A		_										_				
D. INSTALLATION INSPECTED AND APPROVED BY UST DIVISION	<u>ן</u> כ	] _	[		ָ ב	_			-	i		_	-			
E. ANOTHER METHOD ALLOWED BY UST DIVISION (Please Specify)												<del></del>				
2. RELEASE DETECTION	}	PIPE	TANK	PIPE		PIPE		PIPE	<del> </del>	PIPE	TANK	PIPE		PIPE	TANK	PIPE
A. MANUAL (SIAN) TANK GAUGING B. TANK TIGHTNESS TESTING							اما			ه د						
C. INVENTORY CONTROL  D. AUTOMATIC TANK GAUGING												<u> </u>				Į
E. VAPOR MONITORING F. GROUNDWATER MONITORING												  -  -				
G. INTERSTITIAL MONITORING DOUBLE WALLED TANK/PIPING																
H. INTERSTITIAL MONITORING				_			] _			_		[ _		_		_
SECONDARY CONTAINMENT  I. AUTOMATIC UNE LEAK DETECTORS																
J. LINE TIGHTNESS TESTING K. OTHER METHOD ALLOWED BY					-		<del>                                     </del>									
UST DIVISION (Specify)	<u> </u>		<del>  -</del>		=				<u> </u>				<u> </u>			
3. SPILL AND OVERFILL PROTECTION A. OVERFILL DEVICE INSTALLED B. SPILL DEVICE INSTALLED				]		]. ]				] ]		<u> </u>		] 		
4. HAVE YOU INSTALLED IMPRESSED CURRENT CATHODIC PROTECTION?																
A. YES B. NO	1			<u>-</u>			F	<u> </u>		<u> </u>		<u> </u>		<u> </u>		
PLEDGE: I CERTIFY THE INFORMAT THE BEST OF MY BELIEF					STAL	LATIC	HT N	I TA	S PRO	VIDE	D IN	SECT	ION :	XI IS	THUE	TO
INSTALLER: NAME PE	RINTED		<u> </u>				SI	GNATU	IAE					DAT	E	
POSITION				·			CC	MPAN	Y .			<del></del>				

COMMENTS AND/OR CLARIFICATIONS TO THE UST DIVISION STAFF:	
amended to show tanks Construction	1 as Sted
amended to show tanks construction inspead of fiberglass (were incorrectle	1 rear Sterod
and to show tanks nour lined with Ail	beralass.
	7

Note: Change in Owner's address Only!!

Please type or print in ink all items except the signatures in Section VIII & XI. This form must be completed for each location containing underground storage tanks. If more than eight (8) tanks are owned at this location, please photocopy page 2 and 3, and staple continuation sheets to the form. Make a copy of the completed registration form and file with your records for future reference. If amending a notification on tile, it is sufficient to complete and highlight only those areas applicable. However, page 1 must always be


REGISTRATION FOR UNDERGROUND	STORAG	E TANKS	FACILITY NUMBER (if known)
IMPLEMENTING AGENCY:	0009055		
MICHIGAN STATE POLICE FIRE MARSHAL DI	STATE USE ONLY		
TYPE OF NOTIFICATION:   NEW REGISTRATION	A DATE RECEIVED		
NO. OF TANKS AT FACILITY	AMEN	16 1992	B. DATE ENTERED INTO COMPUTER
NO. OF CONTINUATION SHEETS ATTACHED	•	· O BUL	C. DATA ENTRY CLERK HITTIALS
I. OWNERSHIP OF TANKS			II. LOCATION OF TANKS
IF THIS A NEW OWNER'S ADDRESS, PLEASE CHECK	K DK	IF INFO	DAMATION SAME AS SECTION I, PLEASE CHECK
Shell Oil Company	•	Shall	Servine Station
17370 Laurel Park N.	#200		21-8070-0712 A-C
MAILING ADDRESS		Marc	us N. Campbell
Livonia MI 48	1152	975 (	Rochester Rd.
Dakland -	ZIP	ן אסכהי	ester, MI 48307
COUNTY (313) 953-4300		COUNTY	TOWNSHIP
(713) (93-7300		(201	Sland
		TELEPHONE (INC)	LUDING AREA CODE)
		(313	) 656-0080
III. TYPE OF OWNER			IV. INDIAN LANDS
☐ FEDERAL GOVERNMENT COMMERCIAL		ANKS ARE LOC	ATED ON LAND WITHIN AN INDIAN RESERVATION OR
STATE GOVERNMENT PRIVATE		N OTHER TRUS	VED BY NATIVE AMERICAN NATION, TRIBE, OR
LOCAL GOVERNMENT	] 17	NDIVIDUAL.	TO DITION THE AMERICAN NATION, TRIBE, OR
	TRIBE OR N	ATION:	
	V. TYPE O	F FACILITY	
		OVERNMENT	CONTRACTOR CO
☐ AIR TAXI (AIRLINE)		OVERNMENT /NON-MILITAR <sup>,</sup>	
☐ AIRCRAFT OWNER	FEDERAL	-MILITARY	Y UTILITIES  RESIDENTIAL  FARM
☐ AUTO DEALERSHIP ☐ RAILROAD			<b>—</b>
E MAILROAD	] INDUSTR	IAL	OTHER (EXPLAIN)
VI. CONT	TACT PERS	ON FOR LOC	ATION
NAME	IOR TITLE		PHONE (including area code)
magela M. taracl		afety + En	
I HAVE MET THE FINANCIAL RESPONSIBILITY REQUIREMENT		RESPONSIBI	
SEE! HOSOHAICE	. IS AS REQUIR GUARAN	KED IN THĘ UST	
☐ COMMERCIAL INSURANCE			MUSTFA FUND TRUST FUND
RISK RETENTION GROUP	] LETTERO	F CREDIT	OTHER METHOD ALLOWED
FOR INFORMATION ABOUT MUSTFA ELIGIBILITY, CALL 1-80	0-468-7832		(PLEASE SPECIFY)
	VIII. CERTI	FICATION	
CERTIFY LINDER PENALTY OF LAW THAT LHAVE DEDECANA	LIVEVALABLE		MILIAR WITH THE INFORMATION SURMITTED IN THIS
AND ALL ATTACHED DOCUMENTS, AND THAT BASED ON N THE INFORMATION, I BELIEVE THAT THE SUBMITTED INFOR	MY INQUIRY ( RMATION IS T	OF THOSE INDIV RUE, ACCURAT	IDUALS IMMEDIATELY RESPONSIBLE FOR OBTAINING E AND COMPLETE.
NAME AND OFFICIAL TITLE OF OWNER OR OWNERS	SIGNATURE		DATE
AUTHORIZED REPRESENTATIVE SEE CLOVE		( J. M	taraci 10-9-96
THIS INFORMATION IS CONFIDENTIAL DISCLOSURE	A1	ITHODITY.	
OF CONFIDENTIAL INFORMATION IS PROTECTED BY THE FEDERAL PRIVACY ACT.	cc	UTHORITY: OMPLIANCE:	1984 PA 423. Required
THERE IS A \$100.00 ANNUAL REGISTRATION FEE FOR EACH NEW TANK REGIS		NALTIES:	Any owner who knowingly fails to notify or submits false information shall be subject to a misdemeanor
MICHIGAN CHECK OR MONEY OPDER FOR ALL MELLY AND THE STATE OF	•		and/or civil penalties not to exceed \$5 000 per day for
ACCOMPANY THE REGISTRATION FORM PART 8 BEFORE SUCH TANKS CAN BE CONSIDERED REGISTERED.	E		each tank for which notification is not given or for which false information is submitted.

Michigan State Police Fire Marshal Division Hazardous Materials Section 3705 W. Jolly Rd. P.O. Box 30157 Lansing, MI 48909 (800) 642-4878

\*\*\*\*\*\*\*\*\*\*

\* INVOICE \*

\*\*\*\*\*\*\*\*\*




Page 1 of 1

Fee for Underground Storage Tank registrations received on or before 3-31-90.

If there are no changes that need to be made on the registration form, timely payment and return of this invoice will suffice as your FY 1990 (10-1-89 to 19-30-90) annual renewal of your USTs, as required under P.A. 423 of 1984, as lamended. Payment due July 30, 1990. For more details, see the enclosed linformation.

Facility #	Tank #	Description	Cast
0-009055	1	10,000 Gat - Gasoline	\$100.00
0-009055	2	10,000 Gal - Gasoline	\$100.00
0-009055	3	6,000 Gai - Gasoline	\$100-00
0-009055	4	1,000 Gal - Used Dil	\$100.00



Number of Eligible Tanks: 4
Total Number of Tanks: 4

\_\_\_\_\_\_

Registration Fee: \$ 400.00 Late Fee: Amount Received: Amount Due: \$ 400.00

Make Checks Payable to: State of Michigan Payment Due on or Before: JULY 30, 1990

# **Notification for Underground Storage Tanks**

FORM APPROVED OMB NO. 2050-0049 APPROVAL EXPIRES 6-30-88

FOR TANKS

**FORM** 

Ground Water Quality Division Department of Natural Resources Box 30157 Lansing, MI 48909

I.D. Number

STATE USE ONLY

Date Received E C E I V 图

#### **GENERAL INFORMATION**

Notification is required by Federal law for all underground tanks that have been used to store regulated substances since January 1, 1974, that are in the ground as of May 8, 1986, or that are brought into use after May 8, 1986. The information requested is required by Section 9002 of the Resource Conservation and Recovery Act, (RCRA), as amended.

The primary purpose of this notification program is to locate and evaluate underground tanks that store or have stored petroleum or hazardous substances. It is expected that the information you provide will be based on reasonably available records, or, in the absence of such records, your knowledge, belief, or recollection.

Who Must Notify? Section 9002 of RCRA, as amended, requires that, unless exempted, owners of underground tanks that store regulated substances must notify

designated State or local agencies of the existence of their tanks. Owner means—
(a) in the case of an underground storage tank in use on November 8, 1984, or brought into use after that date, any person who owns an underground storage tank used for the storage, use, or dispensing of regulated substances, and
(b) in the case of any underground storage tank in use before November 8, 1984,

but no longer in use on that date, any person who owned such tank immediately before the discontinuation of its use.

What Tanks Are Included? Underground storage tank is defined as any one or combination of tanks that (1) is used to contain an accumulation of "regulated substances," and (2) whose volume (including connected underground piping) is 10% or more beneath the ground. Some examples are underground tanks storing: 1. gasoline, used oil, or diesel fuel, and 2. industrial solvents, pesticides, herbicides or fumigants.

What Tanks Are Excluded? Tanks removed from the ground are not subject to notification. Other tanks excluded from notification are:

1. farm or residential tanks of 1,100 gallons or less capacity used for storing motor fuel for noncommercial purposes;

2. tanks used for storing heating oil for consumptive use on the premises where stored; 3. septic tanks;

4. pipeline facilities (including gathering lines) regulated under the Natural Gas Pipeline Safety Act of 1968, or the Hazardon Manustre And One 1979, or which is an intrastate pipeline facility regulated under State laws:

5. surface impoundments, pits, ponds, or lagoons;

6. storm water or waste water collection systems;

7. flow-through process tanks;

8. liquid traps or associated gathering lines directly related to oil or gas production and

9. storage tanks situated in an underground area (such as a basement, cellar, mineworking, drift, shaft, or tunnel) if the storage tank is situated upon or above the

What Substances Are Covered? The notification requirements apply to underground storage tanks that contain regulated substances. This includes any substance defined as hazardous in section 101 (14) of the Comprehensive Environmental Response, Compensation and Liability Act of 1980 (CERCLA), with the exception of those substances regulated as hazardous waste under Subtitle C of RCRA. It also includes the control of the cont includes petroleum, e.g., crude oil or any fraction thereof which is liquid at standard conditions of temperature and pressure (60 degrees Fahrenheit and 14.7 pounds per square inch absolute).

Where To Notify? Completed notification forms should be sent to the address given at the top of this page.

When To Notify? 1. Owners of underground storage tanks in use or that have been taken out of operation after January 1, 1974, but still in the ground, must notify by May 8, 1986. 2. Owners who bring underground storage tanks into use after May 8, 1986, must notify within 30 days of bringing the tanks into use.

Penalties: Any owner who knowingly fails to notify or submits false information shall be subject to a civil penalty not to exceed \$10,000 for each tank for which notification is not given or for which false information is submitted.

each location containing underground storage tanks. If more than 5 tanks are photocopy the reverse side, and staple continuation sheets to this form.	owned at this location, continuation sheets attached		
I. OWNERSHIP OF TANK(S)	II. LOCATION OF TANK(S)		
Owner Name (Corporation, Individual, Public Agency, or Other Entity)	(If same as Section 1, mark box here 🔲 )		

Facility Name or Company Site Identifier, as applicable Street\_Address County Street Address or State Road, as applicable State County State City (nearest) ZIP Code Type of Owner (Mark all that apply 🔀) Private or Corporate Mark box here if tank(s) Indicate Current State or Local Gov't number of are located on land within Federal Gov't Ownership tanks at this an Indian reservation or (GSA facility I.D. no. uncertain location on other Indian trust lands **III. CONTACT PERSON AT TANK LOCATION** Name (If same as Section I, mark box here ) Job Title Area Code Phone Number PAUL )UAne 656-0080 )wener

IV. TYPE OF NOTIFICATION

Mark box here only if this is an amended or subsequent notification for this location.

### V. CERTIFICATION (Read and sign after completing Section VI.)

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete.

Name and official title	of owner or owner	er's authorized repre	sentativ
Name and official title	7-	DOALA	

Signature

Date Signed 4-9-86

**CONTINUE ON REVERSE SIDE** 

Owner Name (from Section I) Shell	100	Q 7
Owner Name (from Section I) \( \lambda \)	O, $f$	Location (from Section II) 97

975 S. Rochester RJ Page No.

2009055

VI. DESCRIPTION OF UNDERGROU	ND STORAGE TAN	KS (Complete for	each tank at this lo	callon.)	
Tank identification Vo. (e.g., ABC-123), or Arbitrarily Assigned Sequential Number (e.g., 1,2,3)	Tank No.	Tank No. Z	Tank No.	Tank No. ⊖	Tank No.
1. Status of Tank					
2. Estimated Age (Years) 3. Estimated Total Capacity (Gallons)	10,000	10,000	9 6,000	1,000	
4. Material of Construction Steel (Mark one 図) Concrete Fiberglass Reinforced Plastic Unknown Other, Please Specify				(, 500 	
5. Internal Protection (Mark all that apply (X)) Interior Lining (e.g., epoxy resins) None Unknown Other, Please Specify					
6. External Protection (Mark all that apply ☑)  Fiberglass Reinforced Plastic Coated None Unknown  Other, Please Specify					
7. Fiping Bare Steel (Mark all that apply 🗷) Galvanized Steel Fiberglass Reinforced Plastic Cathodically Protected Unknown Other, Please Specify					
8. Substance Currently or Last Stored in Greatest Quaritity by Volume  (Mark all that apply IX)  Gasoline (including alcohol blends)  Used Oil  Other, Please Specify  c. Hazardous Substance					
Please Indicate Name of Principal CERCLA Substance OR Cnemical Abstract Service (CAS) No. Mark box 図 if tank stores a mixture of substances d. Unknown					
9. Additional Information (for tanks permanently taken out of service)  a. Estimated date last used (mo/yr)  b. Estimated quantity of substance remaining (gal.)  c. Mark box DI if tank was filled with inert material (e.g., sand, concrete)	/	/	/	/	/

त्रहर्षि STRATION FOR UNDERGROUND STORAGE TANKS	STATE USE ONLY
IMPLEMENTING AGENCY: MICHIGAN STATE POLICE — FIRE MARSHAL DIVISION	ID NUMBER
TYPE OF NOTIFICATION:    NEW REGISTRATION     AMENDED INFORMATION     CLOSURE	A DATE ENTERED INTO COMPUTER
NO. OF TANKS AT FACILITY NO. OF CONTINUATION SHEETS ATTACHED	B. DATA ENTRY CLERK INITIALS C. COMMENTS SIMP NOV 0 4 1991
INSTRUCTIONS: PLEASE TYPE OR PRINT IN INK ALL ITEMS EXCEPT "SIGNATURE" IN LOCATIONS CONTAINING UNDERGROUND STORAGE TANKS. IF MORE THAN SEV PHOTOCOPY PAGES 3 AND 4, AND STAPLE CONTINUATION SHEETS TO THE FORM.	SECTION VIII. THIS FORM MUST BE COMPLETED FOR ALL

REGISTRATION IS REQUIRED BY STATE LAW FOR ALL KEGULATED UNDERGROUND STORAGE TANKS. UNLESS THE UNDERGROUND STORAGE TANK HAS BEEN PROPERLY CLOSED OR REMOVED AND NOTIFICATION PROVIDED TO THE STATE FIRE MARSHAL. IF A CHANGE SUCH AS A NEW OWNER, NEW OR UPDATED TANKS AND/OR PIPES TAKES PLACE AT THE FACILITY, A REGISTRATION FORM MUST ALSO BE SUBMITTED TO THE STATE FIRE MARSHAL INDICATING ANY CHANGE IN THE INFORMATION PREVIOUSLY SUBMITTED. THE INFORMATION REQUESTED IS REQUIRED BY SECTION 2 OF ACT NO. 423 P.A. OF 1984, AS AMENDED.

WHO MUST NOTIFY? UNLESS EXEMPTED, OWNERS OF UNDERGROUND TANKS THAT STORE OR STORED REGULATED SUBSTANCES MUST NOTIFY THE STATE FIRE MARSHAL OF THE EXISTENCE OF THEIR TANKS. OWNER MEANS ANY PERSON WHO OWNS, OR OWNED AT THE TIME OF A RELEASE, AN UNDERGROUND STORAGE TANK USED FOR THE STORAGE, USE, OR DISPENSING OF REGULATED SUBSTANCES.

WHAT TANKS ARE INCLUDED? UNDERGROUND STORAGE TANK IS DEFINED AS ANY ONE OR COMBINATION OF TANKS THAT (1) IS USED TO CONTAIN AN ACCUMLATION OF "REGULATED SUBSTANCES" AND (2) WHOSE VOLUME (INCLUDING CONNECTED UNDERGROUND PIPING) IS 10% OR MORE BENEATH THE GROUND.

WHAT SUBSTANCES ARE COVERED? THE REGISTRATION REQUIREMENTS APPLY TO UNDERGROUND STORAGE TANKS THAT CONTAIN REGULATED SUBSTANCES.. THIS INCLUDES ANY SUBSTANCE DEFINED AS HAZARDOUS IN SECTION 101(14) OF THE COMPREHENSIVE ENVIRONMENTAL RESPONSE, COMPENSATION AND LIABILITY ACT (CERCLA), WITH THE EXCEPTION OF THOSE SUBSTANCES REGULATED AS MAZARDOUS WASTE UNDER SUBTITLE C OF RCRA. IT ALSO INCLUDES PETROLEUM, E.G., CRUDE OIL OR ANY FRACTION THEREOF WHICH IS LIQUID AT STANDARD CONDITIONS OF TEMPERATURE AND PRESSURE (60) DEGREES FAHRENHEIT AND 14.7 POUNDS PER SQUARE INCH ABSOLUTE).

WHAT TANKS ARE EXCLUDED? TANKS THAT HAVE BEEN PROPERLY CLOSED OR REMOVED PRIOR TO JANUARY 1, 1974 ARE NOT SUBJECT TO REGISTRATION. OTHER TANKS EXCLUDED FROM REGISTRATION ARE:

- A FARM OR RESIDENTIAL TANK OF 1,100 GALLONS OR LESS CAPACITY USED FOR STORING MOTOR FUEL FOR NONCOMMERCIAL PURPOSES. MICHIGAN STATE POLICE
- 2 A TANK USED FOR STORING HEATING OIL FOR CONSUMPTIVE USE ON THE PREMISES WHERE THE TANK IS LOCATED.
- 3.
- A PIPELINE FACILITY, INCLUDING GATHERING LINES REGULATED UNDER EITHER OF THE FOLLOWING:
  - A. THE NATURAL GAS PIPLINE SAFETY ACT OF 1968, PUBLIC LAW 90-481, 49 U.S.C. APPX 167) TO 1677, 1679 TO 1682, AND 168
  - B. SECTIONS 201 TO 215 AND 217 OF THE HAZARDOUS LIQUIO PIPELINE SAFETY ACT OF 1979, TITLE II OF PUBLIC LAW 96-129, 4
- A SURFACE IMPOUNDMENT, PIT, POND, OR LAGOON.
- б. A STORM WATER OR WASTEWATER COLLECTION SYSTEM.
- A FLOW-THROUGH PROCESS TANK
- A STORAGE TANK STUATED IN AN UNDERCONSTRUCTION AND GATHERING OPERATIONS. FIRE MARSHAL DIVISION A STORAGE TANK SITUATED IN AN UNDERGROUND AREA, SUCH AS A BASEMENT, CELLAR, MINEWORKING, DRIFT, SHAFT, OR TUNDENGRADE TANK q SITUATED UPON OR ABOVE THE SURFACE OF THE FLOOR THE HEAVING IVILLE
- 10. ANY PIPES CONNECTED TO A TANK THAT IS DESCRIBED IN SUBPARAGRAPHS 1 to 16
- AN UNDERGROUND STORAGE TANK SYSTEM HOLDING HAZARDOUS WASTES LISTED OR IDENTIFIED UNDER SUBTITLE C OF THE SOLID N OF PUBLIC LAW 89-272, 42 U.S.C. 6921 TO 6931 AND 6933 TO 6939b OR A MIXTURE OF SUCH HAZARDOUS WASTE AND OTHER REGULAT
- A WASTEWATER TREATMENT TANK SYSTEM THAT IS PART OF WASTEWATER TREATMENT FACILITY REGULATED UNDER SECTION 307(b) 12. OF TITLE IV OF THE FEDERAL WATER POLLUTION CONTROL ACT, 33 U.S.C. 1317 AND 1342.
- 13. EQUIPMENT OR MACHINERY THAT CONTAINS REGULATED SUBSTANCES FOR OPERATIONAL PURPOSES SUCH AS HYDRAULIC LIFE **EQUIPMENT TANKS.**
- 14. AN UNDERGROUND STORAGE TANK SYSTEM WITH A CAPACITY OF 110 GALLONS OR LESS.
- 15.

AN EMBERGENCY SPILL OR OVERFLOW CONTAINMENT UNDERGROUND STORAE TANK SYSTEM THAT IS EXPEDITIOUSLY EMPTIED AFTER USA TARDOUS MATERIALS SECTION OF THE COMPLETED FORMS TO 16. WHERE TO NOTIFY? SEND COMPLETED FORMS TO:

**DEPARTMENT OF STATE POLICE** FIRE MARSHAL DIVISION HAZARDOUS MATERIALS SECTION 3705 WEST JOLLY ROAD P.O. BOX 30157 LANSING, MICHIGAN 48909

THERE IS A \$100.00 ANNUAL REGISTRATION FEE FOR EACH NEW TANK REGISTERED WITH THE STATE FIRE MARSHAL. MAKE CHECKS PAYABLE TO THE STATE OF MICHIGAN. PURSUANT TO AST NO. 423 P.A. OF 1984, AS AMENDED, A CHECK OR MONEY ORDER FOR ALL NEW TANK REGISTRATIONS MUST ACCOMPANY THE REGISTRATION FORM BEFORE SUCH TANKS CAN BE CONSIDERED REGISTERED

I. OWNERSHIP OF TANKS	II. LOCATION OF TANKS
Shell Dil Company OWNER NAME (CORPORATION/INDIVIDUAL, ETC.)  21275 Northwestern Hwy #145 STREET ADDRESS  Farmington Hills, MI 48334 CITY STATE ZIP  COUNTY TOWNSHIP  (313) 932-2358 or 2300  TEL	IF SAME AS SECTION I, PLEASE CHECK DENTIFIER  Shell Service Station  FACILITY NAME OR CO SITE IDENTIFIER  975 S. Rochester / Avon  STREET ADDRESS (P.O. BOX NOT ACCEPTABLE)  Avon. Township MI 48063  CITY STATE ZIP  Oakland  COUNTY TOWNSHIP  (313) 656-080  TFLEPHONE (INCLUDING AREA CODE)

\*THIS INFORMATION IS CONFIDENTIAL DISCLOSURE OF CONFIDENTIAL INFORMATION IS PROTECTED BY THE FEDERAL PRIVACY ACT.

AUTHORITY COMPLIANCE: PENALTIES:

ACLNO, 423 P.A. of 1984, as amended.

Any owner who knowingly fails to notify or submits false information shall be subject to a misdemeanor and or civil penalties not to exceed \$5,000 per day for each tank for which notification is not given or for which false information is submitted

III. TYPE OF OWNER	IV. INDIAN LANDS				
☐ FEDERAL GOVERNMENT ☐ COMMERCIAL ☐ STATE GOVERNMENT ☐ PRIVATE ☐ LOCAL GOVERNMENT	☐ TANKS ARE LOCATED ON LAND WITHIN AN INDIAN RESERVATION OR ON OTHER TRUST LANDS. ☐ TANKS ARE OWNED BY NATIVE AMERICAN NATION, TRIBE, OR INDIVIDUAL.  TRIBE OR NATION:				
	/. TYPE OF FACILITY				
SELECT THE APPROPRIATE FACILITY DESCRIPTION:  GAS STATION  PETROLEUM DISTRIBUTOR  AIR TAXI (AIRLINE)	STATE GOVERNMENT TRUCKING/TRANSPORT				
AIRCRAFT OWNER  AUTO DEALERSHIP  RAILROAD	FEDERAL-MILITARY [] RESIDENTIAL  COMMERCIAL [] FARM				
VI. CONTAC	T PERSON IN CHARGE OF TANKS				
Angela M. Faraci Em					
VII. FI	NANCIAL RESPONSIBILITY				
I HAVE MET THE FINANCIAL RESPONSIBILITY REQUIREMEN	TS AS REQUIRED IN THE UST RULES [5]				
CHECK ALL THAT APPLY:					
SELF INSURANCE	GUARANTEE □ STATE FUNDS				
COMMERCIAL INSURANCE	SURETY BOND TRUST FUND				
RISK RETENTION GROUP	LETTER OF CREDIT OTHER METHOD ALLOWED (PLEASE SPECIFY)				
69 1 1 2	VIII. CERTIFICATION IGN AFTER COMPLETING ALL SECTIONS)				
I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSON	ALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION SUBMITTED IN THIS MY INQUIRY OF THOSE INDIVIDUALS IMMEDIATELY RESPONSIBILE FOR OBTAINING RMATION IS TRUE, ACCURATE AND COMPLETE.				
NAME AND OFFICIAL TITLE OF OWNER OR OWNERS' AUTHORIZED REPRESENTATIVE (PRINT) Angela M Faraci CM Environmental analyst	SIGNATURE DATE  Congela M. Forció 10-30-9				
comments and/or clarifications to the Spill Containment/C installed on the	FIRE MARSHAL STAFF:  Duen fill Protection already  gaisolêne tanks.				

IX. DESCRIPTION OF UNDERGROUND STORAGE TANKS (COMPLETE FOR EACH TANK AT THIS LOCATION)								
TANK IDENTIFICATION NUMBER	TANK#/	TANK#2	TANK#3	TANK#4	TANK#	TANK#	TANK#	
1. STATUS OF TANKS (CHECK ONE)  CURRENTLY IN USE  TEMPORARILY OUT OF USE **  PERMANENTLY OUT OF USE **  AMENDMENT OF INFORMATION  **ALSO COMPLETE SECTION X	000	ं विवास	ह्याचा			0000		
2 DATE OF INSTALLATION	12/12	12/12	12/12	12/79				
3. ESTIMATEO TOTAL CAPACITY (GAL)	IOM	1011	6M	IM				
4 MATERIAL OF CONSTRUCTION (MARX ALL THAT APPLY)  ASPHALT COATED OR BARE STEEL  CATHODICALLY PROTECTED STEEL  EPOXY COATED STEEL  COMPOSITE (STEEL WITH FIBERGLASS)  FIBERGLASS REINFORCED PLASTIC  LINEO INTERIOR  DOUBLE WALLED  POLYETHYLENE TANK JACKÉT  EXCAVATION LINER  CONCRETE  UNKNOWN  OTHER, (PLEASE SPECIFY)  HAS TANK BEEN REPAIRED?	00000000000	00008000000	00000000000	o o o o o o o o o o o o o o o o o o o				
5. PIPING MATERIAL (MARK ALL THAT APPLY)  BARE STEEL  GALVANIZED STEEL  FIBERGLASS REINFORCED PLASTIC  COPPER  CATHODICALLY PROTECTED  DOUBLE WALLED  SECONDARY CONTAINMENT  UNKNOWN  OTHER, (PLEASE SPECITY)	000000	0000000	00000000		0000000	00000000		
6. PIPING (TYPE) (MARK ALL THAT APPLY) SUCTION: NO VALVE AT TANK SUCTION: VALVE AT TANK FRESSURE GRAVITY FEO HAS PIPING BEEN REPAIREO?	00000	00800			00000	ممومه	00000	
7. SUBSTANCE CURRENTLY OR LAST STORED IN GREATEST QUANTITY BY VOLUME  GASOLINE  DIESEL  GASOHOL  KEROSENE  FUEL OIL  (NOT FOR CONSUMPTIVE USE ON PREMISES)  USED DIL  OTHER (PLEASE SPECIFY)		) 1		00000	00000 0	0 0000		
HAZARDOUS SUBSTANCE  COMPREHENSIVE ENVIRONMENTAL RESPONSE COMPENSATION & LIABILITY ACT( CERCLA) NAME AND/OR  CHEMICAL ABSTRACT SERVICE (CAS) NUMBER			ease s	e <u>abo</u>	o ve			

TANK DEPTHEATON NUMBERS 1. CIONED OF TANK A. DISPANSION DATE LATE COSED D. ELIMATED DATE TANK COSED D. ELIMATED DATE TANK COSED D. C. TANK SEMONIC FROM GROUND C. TANK SEM		X. TANKS OUT OF USE OR CHANGE IN SERVICE														
A. GSTMAND DATE TANK CLOSED  1. ESTIMATED DATE TANK CLOSED  2. C. TANK PASS MADVED PROM GROUND  3. CARRENAS WADVED PROM GROUND  4. CARRENAS WADVED PROM GROUND  5. CARRENAS WADVED PROM GROUND  6. CARRENAS WAS WADVED PROM GROUND  6. CARRENAS WAS WADVED PROM GROUND  6. CARRENAS WAS WADVED PROM GROUND  7. WAS ASSESSMENT OWNER WAS WADVED PROM GROUND  8. WAS ASSESSMENT OWNER WAS WADVED PROM GROUND  9. WAS ASSESSMENT OWNER WAS WADVED PROM GROUND  1. WAS ASSESSMENT OWNER WAS WADVED PROM GROUND  1. WAS ASSESSMENT OWNER WAS WADVED PROM GROUND  1. WAS ASSESSMENT WAS ASSESSMENT WAS WADVED PROM GROUND  1. WAS ASSESSMENT WAS ASSESSMENT WAS WADVED PROM GROUND  1. WAS ASSESSMENT WAS ASSESSME	TANK	DENTIFICATION NUMBER	TANK	#	TANK	#	TANK ,	ų.	TANK	#	TANK	#	TANK	#	TANK	#
C. TAME WAS REMOVED PROM GROUND  1 GRAVE PLADE WITH HAST MATERIAL  OESCRIE TYPE OF FALL SEGROND  REASON FALL SEGROND  E. CHANGE IN SERVICE  7 INTERASSESSIME WY COMPLETED  (VODENCE OF A LEAR DENICED)  (VODENCE OF A LEAR DENICED)  VODENCE OF A LEAR DENICED  (VODENCE OF A LEAR DENICED)  XI. CERTIFICATION OF COMPLIANCE (COMPLETE FOR ALL NEW AND UPGRADED TANKS AT THIS LOCATION)  XII. CERTIFICATION OF COMPLIANCE (COMPLETE FOR ALL NEW AND UPGRADED TANKS AT THIS LOCATION)  XII. SET ALLER CRINING ON LICENSED BY  1 INSTALLATION  A PROVIDE SET THE READANGE OF TANKS AT THIS LOCATION)  A PROVIDE SET THE READANGE OF TANKS AT THIS LOCATION)  A PROVIDE SET THE READANGE OF TANKS AT THIS LOCATION)  A PROVIDE SET THE READANGE OF TANKS AT THIS LOCATION)  A PROVIDE SET THE READANGE OF TANKS AT THIS LOCATION)  A PROVIDE SET THE READANGE OF TANK SET THE LOCATION OF TANK SET THIS LOCATIO		ESTIMATED DATE LAST USED														
D STANGE FLEED WITHWINST DATERING GESTERS FIRE OF DIRE LISED AND GESTERS FIRE OF DIRECTION  XII. CERTIFICATION OF COMPLIANCE (COMPLETE FOR ALL NEW AND UFGRADED TANKS AT THIS LOCATION)  XII. CERTIFICATION OF COMPLIANCE (COMPLETE FOR ALL NEW AND UFGRADED TANKS AT THIS LOCATION)  XII. CERTIFICATION OF COMPLIANCE (COMPLETE FOR ALL NEW AND UFGRADED TANKS AT THIS LOCATION)  XII. CERTIFICATION OF COMPLIANCE (COMPLETE FOR ALL NEW AND UFGRADED TANKS AT THIS LOCATION)  XII. CERTIFICATION OF COMPLIANCE (COMPLETE FOR ALL NEW AND UFGRADED TANKS AT THIS LOCATION)  XII. CERTIFICATION OF COMPLIANCE (COMPLETE FOR ALL NEW AND UFGRADED TANKS AT THIS LOCATION)  XII. CERTIFICATION OF COMPLIANCE (COMPLETE FOR ALL NEW AND UFGRADED TANKS AT THIS LOCATION)  XII. CERTIFICATION OF COMPLIANCE (COMPLETE FOR ALL NEW AND UFGRADED TANKS AT THIS LOCATION)  XII. CERTIFICATION OF COMPLIANCE (COMPLETE FOR ALL NEW AND UFGRADED TANKS AT THIS LOCATION)  A MASSALLARION  A MA	8.	ESTIMATED DATE TANK CLOSED (MQDAYYR)														
2 SITE ASSESSMENT COMPLETED  EVIDENCE OF A LEAN DETECTED		TANK FILLED WITH INERT MATERIAL (SAND, CONCRETE, ETC.) DESCRIBE TYPE OF FILL USED AND								! ! 	_	1			_	
XI. CERTIFICATION OF COMPLIANCE (COMPLETE FOR ALL NEW AND UPGRADED TANKS AT THIS LOCATION)    INSTALLATION	E.	CHANGE IN SERVICE		1		<del>-</del>								_		<u></u>
XI. CERTIFICATION OF COMPLIANCE (COMPLETE FOR ALL NEW AND UPGRADED TANKS AT THIS LOCATION)    MISTALLATION	2 SITE	ASSESSMENT COMPLETED		]		1				]		]		]		]
STALLATION  NESTALLATION  NESTALLATION  NESTALLATION STATUS  B. INSTALLATION STATUS  C. INSTALLATION STATUS  D. INSTALLATION SECTION  APPROVIDED SYSTATE FIRE MARKHAL  E. ANOTHER METHOD ALLOWED BY STATE FIRE MARKHAL  F. ANOTHER METHOD ALLOWED BY STATE FIRE MARKHAL  E. ANOTHER METHOD ALLOWED BY STATE FIRE MARKHAL  E. ANOTHER METHOD ALLOWED BY STATE FIRE MARKHAL  C. INVENTORY CONTROL  D. AUTOMATIC TARK GAUGING  E. VAPON MONITORING  G. INVENTORY CONTROL  D. AUTOMATIC TARK GAUGING  E. VAPON MONITORING  G. INTERSTITIAL MONITORING  D. LUNC TIGHTMESS TESTING  D. LUNC TIGHTMESS SESTING  D. LUNC TIGHTMESS SESTIN	EVIDI	ENCE OF A LEAK DETECTED		]		]				1		]	Ε	]		
STALLATION  NESTALLATION  NESTALLATION  NESTALLATION STATUS  B. INSTALLATION STATUS  C. INSTALLATION STATUS  D. INSTALLATION SECTION  APPROVIDED SYSTATE FIRE MARKHAL  E. ANOTHER METHOD ALLOWED BY STATE FIRE MARKHAL  F. ANOTHER METHOD ALLOWED BY STATE FIRE MARKHAL  E. ANOTHER METHOD ALLOWED BY STATE FIRE MARKHAL  E. ANOTHER METHOD ALLOWED BY STATE FIRE MARKHAL  C. INVENTORY CONTROL  D. AUTOMATIC TARK GAUGING  E. VAPON MONITORING  G. INVENTORY CONTROL  D. AUTOMATIC TARK GAUGING  E. VAPON MONITORING  G. INTERSTITIAL MONITORING  D. LUNC TIGHTMESS TESTING  D. LUNC TIGHTMESS SESTING  D. LUNC TIGHTMESS SESTIN		XI. CERTIFICATION OF CO	AADI LA	MCE	(CORED	ETE CO	10 41 2	15101.41	WO 1120	DARCE	74612	. A.T. 711		TIO 4 "	·	
B. HATALLES CERTIFIED OR LICENSED BY THE STATE FINE MARSHAL  C. INSTALLATION INSPECTED BY A REGISTEROD ON STATE FINE MARSHAL  E. AND HER MARSHAL  E. AND HER MARSHAL  TANK PIPE  A. MANUAL ISTATICITANK GAUGING  B. TANK TIGHTHESS TESTING  C. INVENTORY CONTROL  O. AUTOMARIC TANK GAUGING  E. VARON MONITORING  G. INTERSTITIAL MONITORING  G. INTER	1NS74		IAILETIN	MCE	LOMPL	EIEFC	OK ALL N	IEVV AI	ND OPG	KADEL	IANK	ALIH	IS LOCA	A HON	) T	<del></del>
B. MATALITE REPRIED BY A  C. NISTALITION INSPECTED BY A  C. NI	A.	INSTALLER CERTIFIED BY TANK AND PIPING MANUFACTURERS.		]		]		]	[Ē			]		1		1 ¦
D. INSTALLATION INSPECTED AND APPROVIDED BY STATE FIRE MARSHAL.  E. AND THER MEMBERS ALL (PLEASE SECRIFY).  2. RELEASE OFFICITION  TANK PIPE TANK	В.	THE STATE FIRE MARSHAL.	[	]		]		]		]		ן [		]		ן נ
A PROPICE ON STATE RINE MARSHAL  E. ANDTHER METICO ALLOWED BY STATE RINE MARSHAL (PLEASE SECEPT).  2. RELEASE DETICTION  TANK PIPE TANK		REGISTERED ENGINEER.	[	]				]				]		ן נ		
2. RELEASE DETICTION  TANK PIPE  A. MANUAL ISTATIC) TANK GAUGING  B. TANK SIGHTNESS TESTING  C. INVENTIONY CONTROL  O. AUTOMATIC TANK GAUGING  E. VAPOR MONITORING  G. INTERSTITIAL MONITORING  G. INTERSTITIAL MONITORING  G. INTERSTITIAL MONITORING  G. INTERSTITIAL MONITORING  J. LINE TIGHTNESS TESTING  N. DIHER METHOD ALLOWED BY MERCHANDER  M. DOVERFILL DEVICE INSTALLED  D. SPILL AND OVERFILL PROTECTION  B. SPILL DEVICE INSTALLED  D. SPILL AND OVERFILL PROTECTION  B. SPILL DEVICE INSTALLED  D. SPILL AND OVERFILL DEVICE INSTALLED  D. MAMP PRINTED  NAME PRINTED  NAME PRINTED  NAME PRINTED  NAME PRINTED  AMAPPRINTED  AMA		APPROVED BY STATE FIRE MARSHAL.  ANOTHER METHOD ALLOWED BY STATE FIRE MARSHAL. (PLEASE		]		]		]	ָ ֓֞֞	]		]		]		ן ו
TANK PIPE  A. MANUAL (STATIC) TANK GAUGING  B. TANX TIGHTNESS TESTING  C. INVENTORY CONTROL  O. AUTOMATIC TANK GAUGING  E. VAPOR MONITORING  G. INTERSTITAL MONITORING  G. INTERSTITAL MONITORING  G. INTERSTITAL MONITORING  G. INTERSTITAL MONITORING  J. LINE TIGHTNESS TESTING  J. LINE TIGHTNESS TESTING  J. LINE TIGHTNESS TESTING  A. DVERFILL DEVICE INSTALLED  D. SPILL AND OVERFILL PROTECTION  A. DVERFILL DEVICE INSTALLED  D. SPILL AND OVERFILL PROTECTION  A. DVERFILL PROTECTION  B. SPILL DEVICE INSTALLED  D. AUTOMATIC LINE LINE TIGHTNESS TESTING  I. CERTIFY THE INFORMATION CONCERNING INSTALLATION THAT IS PROVIDED IN SECTION XI IS TRUE TO THE BEST OF MY BELIEF AND KNOWYREDGE.  INSTALLER  NAME PRINTED  NAME PRINTED																
8. TANK YIGHTMESS TESTING C. INVENTORY CONTROL O. AUTOMATIC TANK GAUGING E. VAPOR MONITORING F. GROUNDWATER MONITORING G. INTERSTITIAL MONITORING G. INTERSTITIAL MONITORING H. SECONDARY CONTAINMENT I. AUTOMATIC LINE ELAK DETECTORS J. LINE TIGHTMESS TESTING K. OTHER METHOD ALLOWED BY IMPLEMENTING AGENCY (SPECIFY)  3. SPILL AND OVERPILL PROTECTION A. DVERFILL DEVICE INSTALLED DELIEF AND KNOWLEDGE.  INSTALLER  INSTALL	2. RELE	ASE DETECTION	TANK				TANK		TANK	PIPE	TANK	PIPE	TANK	<del></del>		PIPE
A. OVERFILL DEVICE INSTALLED  B. SPILL DEVICE INSTALLED  DEPTH OF THE INFORMATION CONCERNING INSTALLATION THAT IS PROVIDED IN SECTION XI IS TRUE TO THE BEST OF MY BELIEF AND KNOWLEDGE.  INSTALLER  NAME PRINTED  NAME PRINTED  DATE  DAT	а. С. О. Е. f. G. . Н.	TANK YIGHTHESS TESTING  INVENTORY CONTROL  AUTOMATIC TANK GAUGING  VAPOR MONITORING  GROUNDWATER MONITORING  INTERSTITIAL MONITORING DOUBLE  WALLEO TANKMIPING  INTERSTITIAL MONITORING  SECONDARY CONTAINMENT  AUTOMATIC LINE LEAK DETECTORS  LINE TIGHTNESS TESTING  OTHER METHOD ALLOWED BY		0000000	0000000	00000000	0000000		0000000				00000000	00000000	0000000	0000000
B. SPILL DEVICE INSTALLED  PLEDGE: I CERTIFY THE INFORMATION CONCERNING INSTALLATION THAT IS PROVIDED IN SECTION XI IS TRUE TO THE BEST OF MY BELIEF AND KNOWLEDGE.  INSTALLER  NAME PRINTED  NAME PRI	3. SPILL	L AND OVERFILL PROTECTION				7		7		Name of the last o	,		-	7		_
PLEDGE: I CERTIFY THE INFORMATION CONCERNING INSTALLATION THAT IS PROVIDED IN SECTION XI IS TRUE TO THE BEST OF MY BELIEF AND KNOWLEDGE.  INSTALLER  INSTA	•		-			<b>⊿</b> ¬		J ¬			-	그 -		_ _		
INSTALLER INSTAL			<u>                                     </u>	<u> </u>		<u></u>	L				<u> </u>		<u> </u>			
POSITION COMPANY		INSTALLER MANOWERGE.  INSTALLER MANOPRINTED  NAMEPRINTED  NAMEPRINTED														

THE MECRIATION IS RECORDED UNDER 1994 PA 411, AS AMERICAD UNITED \$111, FAMILIES TO COMPLY WITH THE PROVISIONS OF THE ACTIMAY RESULT IN A INSCRIMENCY AND OR ONE, PERMUTICS MOT TO EXCEED 10000 PER CAR, MER TANK,

DEEL WORKSAN DEPARTMENT OF ENVIRONMENTAL QUALITY UNDERGROUND STORAGE TANK DIVISION

RELEASE REPORT: SUSPECTED

04/25/96

FACILITY NUMBER ISS	00 9055
USTD (	ise only
UPGRADE/CANCEL DATE	C-252-96
ENTRY DATE CH APR 29 1996	

INSTRUCTIONS: The owner, operator, or consultant must report suspected and confirmed release reports to the Underground Storage Tank Civision (USTD) within 24 hours of discovery. Phone 1-300-MICHUST or FAX this form to 617-335-2245. All information on this form must be provided regardless of whether the release is reported by telephone or FAX. If you have any questions, please contact the USTD at \$17-373-8168.

CONFIRMED

		l communication and the	TOWNER/OPERATOR)	AREA CODE & TELEPHONE NUMBER			
PERSON REPORT	ING RELEASE						
ANGE	LA FAKACI	التنفيذ المراجع والمراجع والم	il Products Co.	313-953-4345			
	I. OWNERSHIP OF TANKS		II. LOCATIO				
PLEASE CH	ECK IF NEW ADDRESS		PLEASE CHECK IF SAME AS SE				
	(CORPORATION/INDIVIDUAL ETC.)		FACUTY NAME OR COMPANY SITE IDEN 5NEIL 5tatio1	THER			
Shell	Dil Products	Company	STREET ADDRESS IN 0 800 No. ACCORDING	ester/Avon			
STREET MORESS		O O	ROCTES	TER STATE M1 48037			
CTY	nia. MI	48152	DAKLAND	TOWNSHIP			
AREA COCE & TEL			CONTACT PERSON FOR LOCATION  I SSAM FRANCIS	313 ) 656-0080			
DATE RELEASE DISCOVERED: 4-24-96			TIME RELEASE DISCOVERE	3:00pm			
SIZE OF TANK (Gallons)	SUBSTANCE RELEASED	CONSTRUCTION OF TANK	REASON FOR BELIEVING (e.g. presence of product, failed	1			
IOM	gasoline	STEEL	lab results	5 howed			
10 M	0 11	STEEL	MTBE in So	oil			
GM	tr er	STEEL					
V 2 ( V							
соммента:							
USTD USE ONLY							
DATE/TIME REPORTED 4/25/96 10:28 TAM PHONE FAX I VOICE MAIL							
DISTRIBUTION	ORIGINAL: USTD, FACILITY FILE COPY: OWNER	USTO SIG	MATURE July Ha				
<u> </u>			0004	2520 NOSE 928			



JOHN ENGLER, Governor

# DEPARTMENT OF ENVIRONMENTAL QUALITY

HOLLISTER BUILDING, PO BOX 30473, LANSING MI 48909-7973

RUSSELL J. HARDING, Director

April 29, 1996

REPLY TO:

UNDERGROUND STORAGE TANK DIVISION TOWN CENTER PO BOX 30157 LANSING MI 48909-7657

### **CERTIFIED MAIL**

Dear Owner/Operator:

SUBJECT:

Underground Storage Tank System Release Facility ID No. 0-009055 Confirmed Release No. C-252-96 SHELL SERVICE STATION 975 S ROCHESTER/AVON ROCHESTER, MI 48037

On 04-25-96, the Department of Environmental Quality (DEQ), Underground Storage Tank Division (USTD), was notified that there was a release of a regulated substance from an underground storage tank (UST) system at the above location. Attached is a copy of the confirmed release report. This letter and attachments are to help your understanding of the following: site investigation and cleanup requirements; forms and reporting requirements; and penalties for late reports and fraud. If necessary, contact the USTD SOUTHEAST MICHIGAN DISTRICT OFFICE at (313) 953-0241 for further guidance. (Refer to attachments)

Cleanup Requirements

Part 213 specifies actions a UST owner or operator is required to take when a release is discovered. Please refer to Part 213 and the attached flow chart to help guide you through the requirements. USTD approval is needed for any institutional controls that are a part of the cleanup program. The USTD may audit or oversee all aspects of corrective actions undertaken pursuant to Part 213. To assist the USTD in this capacity, you are required to contact our District Office at least 48 hours prior to conducting on-site activities, using the attached forms.

Forms and Reports

The USTD requires the use of forms to assist in the reporting requirements. The required forms are available from the district office. A LUST report cover sheet should be submitted with each report. In addition, you are required to notify USTD of any changes to your UST system using a registration form.

Penalties

Be advised that pursuant to Section 21313a and 21323, the owner or operator is subject to penalties for not preparing and submitting the reports outlined in Part 213. Section 21324 provides that a person who submits or causes to be submitted false or misleading information may be found guilty of fraud.

Please include the Facility ID No. found under "Subject" at the top of this notification with each submittal and on any future correspondence. Should you have questions regarding this letter, or need additional information, please contact the USTD SOUTHEAST MICHIGAN DISTRICT OFFICE at (313) 953-0241.

Sincerely,

Terri Harmon
Enforcement Unit

**Enclosures** 


cc: SOUTHEAST MICHIGAN DISTRICT OFFICE

Thank you for using Return Receipt Service.							
I also wish to receive the following services (for an extra fee):  1. ☐ Addressee's Address 2. ☐ Restricted Delivery Consult postmaster for fee.	a. Article Number P COB G33 946	To Service I ype  ☐ Registered ☐ Express Mail ☐ Return Receipt for Merchandise ☐ COD ☐ To Date of Delivery ☐ To Date of Delivery	8. Addresseë's Adgress (Only if requested and fee is paid)	Domestic Return Receipt			
**SENDER:  **Complete items 1 and/or 2 for additional services.  **Complete items 3, 4a, and 4b.  **Print your name and address on the reverse of this form so that we can return this can for you.  **Print your name and address on the reverse of this form so that we can return this can for you.  **Print your name and address on the reverse of this form so that we can return this can be can be call to you.  **Print your name and address on the mailpiece, or on the back if space does not permit?  **Print Herum Receipt Requester** on the mailpiece below the article number.  **The Return Receipt will show to whom the article was delivered and the date delivered.	a 3. Article Addressed to: 9 0.5 5 P 6.08 C P 6.08 C	Shell Oil 17370 Cauvel Ph St.200 L'vonia MI 48152.	5. Received By: (Print Name) 6. Signature: (Addressge or Agent)  X X CLL	PS Form <b>3811</b> , December 1994			

P	60	8	EE3	946
---	----	---	-----	-----

# US Postal Service Receipt for Certified Mail No Insurance Coverage Provided.

D¢	not use for internation	nal Mail <i>(See reverse)</i>
Se	ent to	
St	reet & Number	
Po	ost Office, State, & ZIP Cod	9
Po	ostage	\$
Cé	ertified Fee	<u>:</u>
Sp	pecial Delivery Fee	* -
	estricted Delivery Fee	
	etum Receipt Showing to hom & Date Delivered	
	turn Receipt Showing to Whom, to, & Addressee's Address	
TO	OTAL Postage & Fees	\$
Po	ostmark or Date	



9-1-517-335- aa45

-	•	9-1	- 517- 30	15 - a	ə45	
		TIMES & A			USTD USE ONLY	
MICHIGAN DEPAR MUNDERGRQUND S		e at top of	tank, lab	UPGR/OE/CANCEL		
ancel 1	or Afaraci-No	product los	1 2/21/10	35/9	9055	-
	E REPORT: 💢 🎖	ispected	Confirmed	D.E. CLERK INITIALS		
This information of this Act ma	is required under Act 423, F. A. 1984, a y result in a misdemeaner and/or Civil pe	s amended. Eally on to comply	with the provisions			10
24 Hbu		TLH FEB 28		FEB 12	1996 D-93.	-96
INSTRUCTION	IS: The owner, operator, or cor	sultant must report sus	pected and confirmed	Release Repo	rts to the Underground	Storage
i must be provid	USTD) within 24 hours of disco ed regardless of whether the re See reverse side of this form	Blease is redorted by te	lephone or FAX. If vol	m to 517-335- u have any que	2245. All information stions, please contact	on this for USTD at
PERSON REPORT	ing release:	COMPANY (IF NO	OT OWNER/OPERATOR)		AREA CODE & TELEPHO	NE SUMP
0- 1	ortion ,	1		$\mathcal{C}$		
milder	i taraci	Shell 0	il Troducts		313-953	<del>1</del> 300
CI PLEASE CH	I. OWNERSHIP OF TANK ECK IF NEW OWNER'S ADDRESS		PLEASE CHECK	II. LOCATION		
	(CORPORATION/INDIVIDUAL, ETC.)		FACILITY NAME OR COM			
The second second	Annual Control of the			CITIDYO	orien	
Shell (	Dil Products	Company	STREET ADDRESS (PO		- / avor	<u> </u>
STREET ADDRESS	Laurel Ph	*#200	Rochest	o'(-	STATE	ZIP CO
CITY	STATE	48152 ZIP CODE	COUNTY		TOWNSHIP	$\varphi_{\underline{\cdot}}$
L(VON) AREACODE & TEL		7810 QL	CONTACT, PERSON FOR		AREA CODE & TELEPH	OME NUMB
<u> 313 -</u>	<u>953-4300</u>		Dealer	BOOMITOR	10 20018	2080
DATE RELEA	SE DISCOVERED:	-7-96	TIME RELEASE D	ISCOVERED	: 3130 pm	
SIZE OF TANK (Gallons)	SUBSTANCE RELEASED	CONSTRUCTION OF TANK			RELEASE OCCURRE	
1D,000	Regular	7	(e.g. presence	or product, railed	tightness test, vapors, s	lains)
10,000	roceparation of	(A) (AA)	tant Ja	Week 7	ightness	<u>Cest</u>
- 1	Gasoline	9		·	·	
			ů.			
					( )	
		-			-	
					-	٠
COMMENTS:				<u>-</u>		
				,, <del>:</del>		
					· · · · · · · · · · · · · · · · · · ·	
				· F		
		נע מדצע	SE ONLY			<del></del>
DATE/TIME RI	EPORTED: 2/13/96	<del>,</del> 7.	55 - AM	☐ PHON	E - FAX D VOIC	E MAIL (
DISTRIBUTION	WHITE: UST DIVISION, FACIL	ITY FILE USTD SIG	INATURE		<u> </u>	
	COPY: MUSTFA		Terri	ff.		
	COPY: OWNER	ł	SURVA 1		***************************************	

350

**23**8109534300

SHELL MI

Ø 001	/001
-------	------

	4-	-5/	/-	700-	7942
<b>'-</b>				I.	11 የሚሞት 11

	USTD USE ONLY		
-		FACILITY NUMBER 9055	
	DE. C.ERK IMTIALS & DATE	INCIDENT NUMBER	

RELEASE REPORT: Suspected Confirma
This information is required under Act 423, RVA. 1984, as amended. Pailure to comply with the provisions
of this Act may result in a misdemeaned and/or Civil penalties not to exceed \$5000 per day, particular. RELEASE REPORT:

INSTRUCTIONS: The owner, operator, or consultant must report suspected and confirmed Release Reports to the Underground Storage Tank Division (USTD) within 24 hours of discovery. Phone 1-800-MICHUST or FAX this form to 517-335-2245. All information on this form must be provided regardless of whether the release is reported by telephone or FAX. If you have any questions, please contact USTD at

517-373-8168. See reverse side of this form for additional information.				
PERSON REPOR	ing release.	COMPANY (IF NO	OF OWNER/OPERATOR)	AREA CODE & TELEPHONE NUMBER
Hngel	a Faraci	Shell O	il Products Co.	313-9534300
	I. ÓWNERSHIP OF TANK		II. LOCA	TION OF TANKS
	HECK IF NEW OWNER'S ADDRES	3	PLEASE CHECK IF SAME AS	45/4-11/10/10/10/10/10/10/10/10/10/10/10/10/1
NAME OF QVVNE	R (CORPORATION /INDIVIDUAL ETC.)		FACILITY NAME OR COMPANY SITE IDENTIFIER  SNOW Station	
Shell_	Oil Products	Company	STREET ADDRESS (FO Box Not Acceptable) 975 ROCNOSTO / QUON	
17370		#200	Rochester COUNTY	STATE ZIP CODE
Li Voni	STATE (	1815 記	oounty alaland	TOWNSHIP
	EPHONE NUMBER		CONTACT PERSON FOR LOCATION	AREA CODE & TELEPHONE NUMBER
	953-4300		Dealer,	
	ASE DISCOVERED:	-7-96	TIME RELEASE DISCOVER	1ED: 3/30 pm
SIZE OF TANK (Gallons)	SUBSTANCE RELEASED	CONSTRUCTION OF TANK		VING RELEASE OCCURRED eiled tightness test, vapors, stains)
10,000	Regular	Fiber	tank Lailed	tight many toxt
	GONDLING	glaso	000000	confectives of.
	C > 22.6361 CV + C V		المقفه عليان وسيست مسيدة التراثين المستون ومستديين والمستون والم والمستون والمستون والمستون والمستون والمستون والمستون والمستون و	
			The second secon	
COMMENTS:				
· · · · · · · · · · · · · · · · · · ·				
	والمراجع والم والمراجع والمراجع والمراجع والمراجع والمراجع والمراجع والمراج			
USTD USE ONLY				
DATE/TIME REPORTED: AM PHONE FAX VOICE MAIL				
DISTRIBUTION	WHITE: UST DIVISION, FACILI	TY FILE USTD SIG	NATURE 1	
	COPY: MUSTFA COPY: OWNER			
· <del>-</del>				

PR 3828 (1/95)

9-1-517-335-2045

MICHIGAN DEPARTMENT OF NATURAL RESOURCES DNR UNDERGROUND STORAGE TANK DIVISION

RELEASE REPORT:

Confirmed

RELEASE REPORT: Suspected Confirma
This information is required under Act 420, P/A. 1984, as emended. Failure to comply with the provisions
of this Act may result in a misdemeanor and/or Civil penaltics not to exceed \$5000 per day, per tank,

USTD USE ONLY				
UPGRADE/GANCEL DATE	FACILITY NUMBER 9055			
O E. GLERK INITIALS & DATE	INCIDENT NUMBER			

INSTRUCTIONS: The owner, operator, or consultant must report suspected and confirmed Rolesse Reports to the Underground Storage Tank Division (USTD) within 24 hours of discovery. Phone 1-800-MICHUST or FAX this form to 517-335-2245. All information on this form must be provided regardless of whether the release is reported by telephone or FAX. If you have any questions, please contact USTO at 517-373-8168. See reverse side of this form for additional information.

The state of the s					
PERSON REPORTING RELEASE. COMPANY (IF NO			T OWNER/OPERATOR)	AREA CODE & TELEPHONE NUMBER	
Angela Fargei Shell Oi			il Products Co.	313-9534300	
I. OWNERSHIP OF TANKS				N OF TANKS	
150	ECK IF NEW OWNER'S ADDRESS		PLEASE CHECK IF SAME AS SE		
NAME OF OWNER	(CORPORATION/INDIVIDUAL, ETC.)		FACILITY NAME OR COMPANY SITE IDENTIFIER  SYNCH STOLL DAY		
Shell Oil Products Company			STREET ADDRESS (FO BOX Not Accaptable) 975 ROCNOSTET / GVON		
17370 Laurel Ph #200			Rochester	STATE ZIP CODE	
CITY STATE ZIP CODE LIVORIA MI 4815 D			COUNTY COUNTY TOWNSHIP		
	EPHONG NUMBER 953-4300		CONTACT PERSON FOR LOCATION	AREA CODE & TELEPHONE NUMBER	
DATE RELEA	SE DISCOVERED:	7-96	TIME RELEASE DISCOVERED: 3/30 pm		
SIZE OF TANK (Gzilons)	Substance released	CONSTRUCTION OF TANK	REASON FOR BELIEVIN (e.g. presence of product, failed		
10,000	Regular	Fiber	1 1	tightness test.	
	Gasoline	8/asa)			
	7444				
COMMENTS: Please CANCEL this Supperted release.					
The to	1	etino_s			
product was released 2-21-96					
USTO USE ONLY					
DATE/TIME REPORTED:    DAM   PHONE   FAX   VOICE MAIL					
DISTRIBUTION WHITE: UST DIVISION, FACILITY FILE USTD SIGNATURE  COPY: MUSTFA  COPY: OWNER					

PR 3826 (1/95)

USTO USE ONLY

USTD SIGNATURE

MA

□ PM

EQ# 3326 (10/36

☐ PHONE ☐ FAX ☐ VOICE MAIL

COPY:

HAUTION ORIGINAL: USTD, FACILITY FILE

OWNER

DATE/TIME REPORTED